

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

welcome!
ct tech pubs web page
ct water cooler
ct tech pubs updates
surveys
9800/hla
highspeed family (us)
ct/i
lightspeed family
yms family
all ct products
index
old ct emails
communiques pending
approval
customize
members

search:

advanced search
news: daily | weekly

go offline | chat | notify |
print | tutorial | help

home> all ct products

CT Service Supplies and Kits

erwin sulma (erwin s sulma), 06/12/2002 - 12:47 pm



PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
Disclosure to third parties prohibited.

Communique Number

MQUE-5ADPXQ

Equipment

All CT Products

Problem

Service Supplies previously not available for order.

Corrective Action

This communication has been updated to reflect the correct part number for the Aero Duster and show FRU status for the Collimator Cleaning Kit contents. The following parts can now be ordered through normal GE processes. Aero Duster 2226685 Standard FLS order, Amax Circuit bd Cleaner 2274104 Standard FLS order, Collimator Cleaning Kit 2339299 Standard FLS order, Ionizing Fan 2335059 Region Tool Pool. Please Note: The Ionizing Fan for DAS/Detector Service has a long lead time. Please contact your Zone Support Engineer prior to placing your order. This is a new tool and each region needs to determine local quantities.

You can download any of the files below by dragging them to your Windows desktop.
To open a file for reading, double-click it.



Author

Erwin S Sulma

Revision

06/12/2002 12:47 PM

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

CT Service Part Availability Updated 6-12-2002

Document Correction

The part number for the Aero Duster Spray Can has been corrected in this document.
The Collimator Cleaning Kit table has been updated to reflect FRU status.

This communication has been created to make you aware that previously un-available Service Tools, Kits, and Supplies can now be ordered through normal GE process.

The following items are available as follows:

Aero Duster	2226685	Standard FLS order
Amax Circuit bd. Cleaner	2274104	Standard FLS order
Collimator Cleaning Kit	2339299	Standard FLS order
Ionizing Fan	2335059	Region Tool Pool

Please Note: The Ionizing Fan for DAS/Detector Service has a long lead time.
Please contact your Zone Support Engineer prior to placing your order. This is a new tool and each region needs to determine local quantities.

2339299 Collimator Cleaning Kit FRU

Part Number	Description	-----	Kit Quantity
2335064	Aero Duster Spray System	N	1 piece
46-183000P164	91% Alcohol	Y	1 bottle
46-183039P1	Alcohol Pads	Y	1 Box = 144 total
2339300	Swabs, Circular Head	N	1 bag = 50 (2 bags per box)
46-170686P2	loctite 242 10 cc	Y	1 piece
2339305-100	Service note T-1449	NA	1 document