



ELLIS & WATTS INTERNATIONAL, INC
4400 GLEN WILLOW LAKE LANE BATAVIA, OH 45103
(513) 752-9000

10/02/01 SB-008

SERVICE BULLETIN

Service (PM) Issue

The purpose of this bulletin is to address an important service issue:

In accordance with GE specification, Engineering has changed the DOWFROST Glycol mixture to a 50/50 mix (instead of 35/65). It is also now yellow in color (instead of clear).

When performing a PM, please use the 2 gallons of the new type mixture in the unit even if this requires draining some fluid from the tank. After 2-3 PMs the mixture should be at the new requirement and will only require topping off.