


1-7-2 Installation Flowchart Explanation


Shown below are three examples of the flow chart Installation Procedures and an explanation of the areas within the procedures.

Use the CD-ROM that applies to the System being installed to locate the installation procedure listed below

Main menu selection
Installation Procedure to be performed



Use the correct Magnet Manual that applies to the System being installed to locate the installation procedure listed below




Tab within the manual where Installation Procedure is located

Section within Tab where Installation Procedure is located

Tab within this manual (Direction 2196821) where the Direction listed below is located

Installation Procedure to be performed



Direction within the Tab where the Installation Procedure listed below is located

Specific steps or room of the above Installation Procedure to be performed at this time

LEGEND FOR FOLLOWING INSTALLATION FLOWCHART



INDICATES MILESTONE COMPLETION GOAL IN DAYS



INDICATES AND OPTIONAL PATH DEPENDING ON SYSTEM CONFIGURATION



INDICATES GE PROPRIETARY PROCEDURE



INDICATES AN ADDITIONAL PROPRIETARY TEST OR ALTERNATIVE PROPRIETARY CALIBRATION PROCEDURE AVAILABLE FOR GE USE OR TO CUSTOMERS WITH AN ADVANCED SERVICE PACKAGE LIMITED LICENSE.



AFTER GRADIENT SHIM (OR LV SHIM) IT MAY BE NECESSARY TO REPAIR THE MAGNET.

NOTE 1: STANDARD CORRELATED NOISE CHECK NOT REQUIRED IF PROPRIETARY SPT FULL TEST MODE PROCEDURE PERFORMED EARLIER DURING INSTALLATION (HOWEVER, MULTICOIL AND FAST RECEIVER OPTION CORRELATED NOISE CHECKS IN PROCEDURE STILL REQUIRED).

NOTE 2: IF TROUBLESHOOTING NECESSARY.

NOTE 3:


NOTE 4: A "saveINFO" SHOULD BE DONE BEFORE SPT IS RUN. IF YOU HAVE THE EPI OPTION, IT IS NECESSARY TO "saveINFO" AGAIN. IN THIS WAY, ANY DATA COLLECTED FOR CALIBRATION WILL NOT BE LOST IF A PROBLEM OCCURS.

NOTE 5: VALUES OF LVSHIM ARE DEPENDENT UPON EDDY CURRENT COMPENSATION.

NOTE 6: VALUES OF EDDY CURRENT COMPENSATION ARE INDEPENDENT OF MAGNET SHIM.

NOTE 7: OVERNIGHT DIAGS MAY BE RUN AT END OF ANY DAY TO DETECT POSSIBLE ERRORS.

MARK OFF ☐ PERFORMED ☐ ITEMS ☐




* MAGNET MANUAL USED:
DIR 2192625 – GE 1.5T & 1.0T LCC Active Shield Magnet & Cryogens Subsystem
DIR 2226319 – GE 1.5T & 1.0T LCC Magnet Sigma MR/i; & CV/i Delivery & Installation

THIS PAGE LEFT BLANK INTENTIONALLY

THIS PAGE LEFT BLANK INTENTIONALLY

MARK OFF PERFORMED ITEMS



SIGNA MR//i & CV//i INSTALLATION FLOW CHART
ILLUSTRATION 1-2 (SHEET 3 OF 5)

THIS PAGE LEFT BLANK INTENTIONALLY

THIS PAGE LEFT BLANK INTENTIONALLY

