



System Upgrade Manuals

1 Direction 5177001: Signa EXCITE 4-Channel to 8-Channel Upgrade



2 Direction 5177002: Signa 16-Channel RF Electronics Upgrade



3 Direction 5177004: Signa HD LPCA to HDx LPCA Upgrade



4 Direction 5177005: Signa HDx Single Terminal Server Upgrade for RRI High Order Shim (HOS) Supply



5 Direction 5166004: Signa HD to HDx System Upgrade for 1.5T and 3.0T



6 Direction 5166005: Signa EXCITE to HDx 1.5T System Upgrade



7 Direction 5166008: Signa Pre-EXCITE to HDx 1.5T



8 Direction 5166010: Signa HDx 8-Channel to 16-Channel Upgrade



9 Direction 5166011: Signa HDx 16-Channel to 32-Channel System Upgrade



10 Direction 5241502: Signa HDx Forward Production B-Port Connector Upgrade



11 Direction 5244044: Signa Rear Pedestal Stabilization Installation

This Direction is included with 5198961, Rear Pedestal Assembly, and is included with the following catalogs:



- M3335BC - Early LCC WideOpen IIQ Upgrade
- M3335BD - LCC WideOpen IIQ Upgrade

12 Direction 2319685: BRM or CRM RF Shield Grounding Upgrade



13 Direction 5322720: Signa TRM to BRM System Upgrade



 [Back to top](#)