

GE Healthcare

GOC5

Illustrated Parts List

OPERATING DOCUMENTATION



5135498-100
Rev 11

IMPORTANT PRECAUTIONS

LANGUAGE

WARNING

(EN)

- This Service Manual is available in English only.
- If a customer's service provider requires a language other than English, it is the customer's responsibility to provide translation services.
- Do not attempt to service the equipment unless this service manual has been consulted and is understood.
- Failure to heed this warning may result in injury to the service provider, operator, or patient, from electric shock or from mechanical or other hazards.

ПРЕДУПРЕЖДЕНИЕ

(BG)

- ТОВА УПЪТВАНЕ ЗА РАБОТА Е НАЛИЧНО САМО НА АНГЛИЙСКИ ЕЗИК.
- АКО ДОСТАВЧИКЪТ НА УСЛУГАТА НА КЛИЕНТА ИЗИСКА ЕЗИК, РАЗЛИЧЕН ОТ АНГЛИЙСКИ, ЗАДЪЛЖЕНИЕ НА КЛИЕНТА Е ДА ОСИГУРИ ПРЕВОД.
- НЕ ИЗПОЛЗВАЙТЕ ОБОРУДВАНЕТО ПРЕДИ ДА СТЕ СЕ КОНСУЛТИРАЛИ И РАЗБРАЛИ УПЪТВАНЕТО ЗА РАБОТА.
- НЕСПАЗВАНЕТО НА ТОВА ПРЕДУПРЕЖДЕНИЕ МОЖЕ ДА ДОВЕДЕ ДО НАРАНЯВАНЕ НА ДОСТАВЧИКА НА УСЛУГАТА, ОПЕРАТОРА ИЛИ ПАЦИЕНТ В РЕЗУЛТАТ НА ТОКОВ УДАР ИЛИ МЕХАНИЧНА ИЛИ ДРУГА ОПАСНОСТ.

警告

(ZH-CN)

- 本维修手册仅提供英文版本。
- 如果维修服务提供商需要非英文版本，客户需自行提供翻译服务。
- 未详细阅读和完全理解本维修手册之前，不得进行维修。
- 忽略本警告可能对维修人员，操作员或患者造成触电、机械伤害或其他形式的伤害。

VÝSTRAHA

(CS)

- Tento provozní návod existuje pouze v anglickém jazyce.
- V případě, že externí služba zákazníkům potřebuje návod v jiném jazyce, je zajištění překladu do odpovídajícího jazyka úkolem zákazníka.
- Nesnažte se o údržbu tohoto zařízení, aniž byste si přečetli tento provozní návod a pochopili jeho obsah.
- V případě nedodržování této výstrahy může dojít k poranění pracovníka prodejního servisu, obslužného personálu nebo pacientů vlivem elektrického proudu, respektive vlivem mechanických či jiných rizik.

ADVARSEL

(DA)

- Denne servicemanual findes kun på engelsk.
- Hvis en kundes tekniker har brug for et andet sprog end engelsk, er det kundens ansvar at sørge for oversættelse.
- Forsøg ikke at servicere udstyret medmindre denne servicemanual har været konsulteret og er forstået.
- Manglende overholdelse af denne advarsel kan medføre skade på grund af elektrisk, mekanisk eller anden fare for teknikeren, operatøren eller patienten.

WAARSCHUWING

(NL)

- Deze onderhoudshandleiding is enkel in het Engels verkrijgbaar.
- Als het onderhoudspersoneel een andere taal vereist, dan is de klant verantwoordelijk voor de vertaling ervan.
- Probeer de apparatuur niet te onderhouden voordat deze onderhoudshandleiding werd geraadpleegd en begrepen is.
- Indien deze waarschuwing niet wordt opgevolgd, zou het onderhoudspersoneel, de operator of een patiënt gewond kunnen raken als gevolg van een elektrische schok, mechanische of andere gevaren.

HOIATUS

(ET)

- Käesolev teenindusjuhend on saadaval ainult inglise keeles.
- Kui klienditeeninduse osutaja nõuab juhendit inglise keelest erinevas keeles, vastutab klient tõlketeenuse osutamise eest.
- Ärge üritage seadmeid teenindada enne eelnevalt käesoleva teenindusjuhendiga tutvumist ja sellest aru saamist.
- Käesoleva hoiatuse eiramine võib põhjustada teenuseosutaja, operaatori või patsiendi vigastamist elektrilöögi, mehaanilise või muu ohu tagajärjel.

VAROITUS

(FI)

- Tämä huolto-ohje on saatavilla vain englanniksi.
- Jos asiakkaan huoltohenkilöstö vaatii muuta kuin englanninkielistä materiaalia, tarvittavan käännöksen hankkiminen on asiakkaan vastuulla.
- Älä yritä korjata laitteistoa ennen kuin olet varmasti lukenut ja ymmärtänyt tämän huolto-ohjeen.
- Mikäli tätä varoitusta ei noudateta, seurauksena voi olla huoltohenkilöstön, laitteiston käyttäjän tai potilaan vahingoittuminen sähköiskun, mekaanisen vian tai muun vaaratilanteen vuoksi.

ATTENTION

(FR)

- Ce manuel de service n'est disponible qu'en anglais.
- Si le technicien du client a besoin de ce manuel dans une autre langue que l'anglais, c'est au client qu'il incombe de le faire traduire.
- Ne pas tenter d'intervenir sur les équipements tant que le manuel service n'a pas été consulté et compris
- Le non-respect de cet avertissement peut entraîner chez le technicien, l'opérateur ou le patient des blessures dues à des dangers électriques, mécaniques ou autres.

WARNUNG

(DE)

- Diese Serviceanleitung existiert nur in Englischer Sprache.
- Falls ein fremder Kundendienst eine andere Sprache benötigt, ist es aufgabe des Kunden für eine Entsprechende Übersetzung zu sorgen.
- Versuchen Sie nicht diese Anlage zu warten, ohne diese Serviceanleitung gelesen und verstanden zu haben.
- Wird diese Warnung nicht beachtet, so kann es zu Verletzungen des Kundendiensttechnikers, des Bedieners oder des Patienten durch Stromschläge, Mechanische oder Sonstige Gefahren kommen.

ΠΡΟΕΙΔΟΠΟΙΗΣΗ

(EL)

- Το παρόν εγχειρίδιο σέρβις διατίθεται στα αγγλικά μόνο.
- Εάν το άτομο παροχής σέρβις ενός πελάτη απαιτεί το παρόν εγχειρίδιο σε γλώσσα εκτός των αγγλικών, αποτελεί ευθύνη του πελάτη να παρέχει υπηρεσίες μετάφρασης.
- Μην επιχειρήσετε την εκτέλεση εργασιών σέρβις στον εξοπλισμό εκτός εάν έχετε συμβουλευτεί και έχετε κατανοήσει το παρόν εγχειρίδιο σέρβις.
- Εάν δε λάβετε υπόψη την προειδοποίηση αυτή, ενδέχεται να προκληθεί τραυματισμός στο άτομο παροχής σέρβις, στο χειριστή ή στον ασθενή από ηλεκτροπληξία, μηχανικούς ή άλλους κινδύνους.

FIGYELMEZTETÉS

(HU)

- Ezen karbantartási kézikönyv kizárólag angol nyelven érhető el.
- Ha a vevő szolgáltatója angoltól eltérő nyelvre tart igényt, akkor a vevő felelőssége a fordítás elkészítése.
- Ne próbálja elkezdni használni a berendezést, amíg a karbantartási kézikönyvben leírtakat nem értelmezték.
- Ezen figyelmeztetés figyelmen kívül hagyása a szolgáltató, működtető vagy a beteg áramütés, mechanikai vagy egyéb veszélyhelyzet miatti sérülését eredményezheti.

AÐVÖRUN

(IS)

- Þessi þjónustuhandbók er eingöngu fáanleg á ensku.
- Ef að þjónustuveitandi viðskiptamanns þarfnast annas tungumáls en ensku, er það skylda viðskiptamanns að skaffa tungumálaþjónustu.
- Reynið ekki að afgreiða tækið nema að þessi þjónustuhandbók hefur verið skoðuð og skilin.
- Brot á sinna þessari aðvörun getur leitt til meiðsla á þjónustuveitanda, stjórnanda eða sjúklings frá raflosti, vélrænu eða öðrum áhættum.

AVVERTENZA

(IT)

- Il presente manuale di manutenzione è disponibile soltanto in inglese.
- Se un addetto alla manutenzione richiede il manuale in una lingua diversa, il cliente è tenuto a provvedere direttamente alla traduzione.
- Si proceda alla manutenzione dell'apparecchiatura solo dopo aver consultato il presente manuale ed averne compreso il contenuto
- Il non rispetto della presente avvertenza potrebbe far compiere operazioni da cui derivino lesioni all'addetto, alla manutenzione, all'utilizzatore ed al paziente per folgorazione elettrica, per urti meccanici od altri rischi.

警告

(JA)

- このサービスマニュアルには英語版しかありません。
- サービスを担当される業者が英語以外の言語を要求される場合、翻訳作業はその業者の責任で行うものとさせていただきます。
- このサービスマニュアルを熟読し理解せずに、装置のサービスを行わないでください。
- この警告に従わない場合、サービスを担当される方、操作員あるいは患者さんが、感電や機械的又はその他の危険により負傷する可能性があります。

경고

(KO)

- 본 서비스 지침서는 영어로만 이용하실 수 있습니다 .
- 고객의 서비스 제공자가 영어 이외의 언어를 요구할 경우, 번역 서비스를 제공하는 것은 고객의 책임입니다 .
- 본 서비스 지침서를 참고했고 이해하지 않는 한은 해당 장비를 수리하려고 시도하지 마십시오 .
- 이 경고에 유의하지 않으면 전기 쇼크 , 기계상의 혹은 다른 위험으로부터 서비스 제공자 , 운전자 혹은 환자에게 위해를 가할 수 있습니다 .

BRDINJUMS

(LV)

- Šī apkāļpes rokasgrāmata ir pieejama tikai angļu valodā.
- Ja klienta apkāļpes sniedzējam nepieciešama informācija citā valodā, nevis angļu, klienta pienākums ir nodrošināt tulkošanu.
- Neveiciet aprīkojuma apkalpi bez apkāļpes rokasgrāmatas izlasīšanas un saprašanas.
- Šī brīdinājuma neievērošana var radīt elektriskās strāvas trieciena, mehānisku vai citu risku izraisītu traumu apkāļpes sniedzējam, operatoram vai pacientam.

ĮSPĖJIMAS

(LT)

- Šis eksploatavimo vadovas yra prieinamas tik anglų kalba.
- Jei kliento paslaugų tiekėjas reikalauja vadovo kita kalba – ne anglų, numatyti vertimo paslaugas yra kliento atsakomybė.
- Nemėginkite atlikti įrangos techninės priežiūros, nebent atsižvelgėte į šį eksploatavimo vadovą ir jį supratote.
- Jei neatkreipsite dėmesio į šį perspėjimą, galimi sužalojimai dėl elektros šoko, mechaninių ar kitų pavojų paslaugų tiekėjui, operatoriui ar pacientui.

ADVARSEL

(NO)

- Denne servicehåndboken finnes bare på engelsk.
- Hvis kundens serviceleverandør trenger et annet språk, er det kundens ansvar å sørge for oversettelse.
- Ikke forsøk å reparere utstyret uten at denne servicehåndboken er lest og forstått.
- Manglende hensyn til denne advarselen kan føre til at serviceleverandøren, operatøren eller pasienten skades på grunn av elektrisk støt, mekaniske eller andre farer.

OSTRZEŻENIE

(PL)

- Niniejszy podręcznik serwisowy dostępny jest jedynie w języku angielskim.
- Jeśli dostawca usług klienta wymaga języka innego niż angielski, zapewnienie usługi tłumaczenia jest obowiązkiem klienta.
- Nie próbować serwisować wyposażenia bez zapoznania się i zrozumienia niniejszego podręcznika serwisowego.
- Niezastosowanie się do tego ostrzeżenia może spowodować urazy dostawcy usług, operatora lub pacjenta w wyniku porażenia elektrycznego, zagrożenia mechanicznego bądź innego.

ATENÇÃO

(PT-BR)

- Este manual de assistência técnica só se encontra disponível em inglês.
- Se qualquer outro serviço de assistência técnica, que não a gems, solicitar estes manuais noutro idioma, é da responsabilidade do cliente fornecer os serviços de tradução.
- Não tente reparar o equipamento sem ter consultado e compreendido este manual de assistência técnica.
- O não cumprimento deste aviso pode por em perigo a segurança do técnico, operador ou paciente devido a choques elétricos, mecânicos ou outros.

ATENÇÃO

(PT-PT)

- Este manual de assistência técnica só se encontra disponível em inglês.
- Se qualquer outro serviço de assistência técnica, que não a gems, solicitar estes manuais noutro idioma, é da responsabilidade do cliente fornecer os serviços de tradução.
- Não tente reparar o equipamento sem ter consultado e compreendido este manual de assistência técnica.
- O não cumprimento deste aviso pode colocar em perigo a segurança do técnico, do operador ou do paciente devido a choques eléctricos, mecânicos ou outros.

ATENȚIE

(RO)

- Acest manual de service este disponibil numai în limba engleză.
- Dacă un furnizor de servicii pentru clienți necesită o altă limbă decât cea engleză, este de datoria clientului să furnizeze o traducere.
- Nu încercați să reparați echipamentul decât ulterior consultării și înțelegerii acestui manual de service.
- Ignorarea acestui avertisment ar putea duce la rănirea depanatorului, operatorului sau pacientului în urma pericolelor de electrocutare, mecanice sau de altă natură.

ОСТОРОЖНО!

(RU)

- Данное руководство по обслуживанию предлагается только на английском языке.
- Если сервисному персоналу клиента необходимо руководство не на английском, а на каком-то другом языке, клиенту следует самостоятельно обеспечить перевод.
- Перед обслуживанием оборудования обязательно обратитесь к данному руководству и поймите изложенные в нем сведения.
- Несоблюдение требований данного предупреждения может привести к тому, что специалист по обслуживанию, оператор или пациент получат удар электрическим током, механическую травму или другое повреждение.

UPOZORENJE

(SR)

- Ovo servisno uputstvo je dostupno samo na engleskom jeziku.
- Ako klijentov serviser zahteva neki drugi jezik, klijent je dužan da obezbedi prevodilacke usluge.
- Ne pokušavajte da opravite uređaj ako niste pročitali i razumeli ovo servisno uputstvo.
- Zanemarivanje ovog upozorenja može dovesti do povređivanja serviser, rukovaoca ili pacijenta usled strujnog udara ili mehaničkih i drugih opasnosti.

UPOZORNENIE

(SK)

- Tento návod na obsluhu je k dispozícii len v angličtine.
- Ak zákazník poskytovateľ služieb vyžaduje iný jazyk ako angličtinu, poskytnutie prekladateľských služieb je zodpovednosťou zákazníka.
- Nepokúšajte sa o obsluhu zariadenia skôr, ako si neprečítate návod na obsluhu a neporozumiete mu.
- Zanedbanie tohto upozornenia môže vyústiť do zranenia poskytovateľa služieb, obsluhujúcej osoby alebo pacienta elektrickým prúdom, do mechanického alebo iného nebezpečenstva.

ATENCION

(ES)

- Este manual de servicio sólo existe en inglés.
- Si el encargado de mantenimiento de un cliente necesita un idioma que no sea el inglés, el cliente deberá encargarse de la traducción del manual.
- No se deberá dar servicio técnico al equipo, sin haber consultado y comprendido este manual de servicio.
- La no observancia del presente aviso puede dar lugar a que el proveedor de servicios, el operador o el paciente sufran lesiones provocadas por causas eléctricas, mecánicas o de otra naturaleza.

VARNING

(SV)

- Den här servicehandboken finns bara tillgänglig på engelska.
- Om en kunds servicetekniker har behov av ett annat språk än engelska ansvarar kunden för att tillhandahålla översättningstjänster.
- Försök inte utföra service på utrustningen om du inte har läst och förstår den här servicehandboken.
- Om du inte tar hänsyn till den här varningen kan det resultera i skador på serviceteknikern, operatören eller patienten till följd av elektriska stötar, mekaniska faror eller andra faror.

DIKKAT
(TR)

- Bu servis kilavuzunun sadece ingilizcesi mevcuttur.
- Eğer müşteri teknisyeni bu kilavuzu ingilizce dışında bir başka lisandan talep ederse, bunu tercüme ettirmek müşteriye düşer.
- Servis kilavuzunu okuyup anlamadan ekipmanlara müdahale etmeyiniz.
- Bu uyarıya uyulmaması, elektrik, mekanik veya diğer tehlikelerden dolayı teknisyen, operatör veya hastanın yaralanmasına yol açabilir.

DAMAGE IN TRANSPORTATION

Check for damage to property that may have occurred at the site during delivery, such as damage to floors, door frames or walls. If damage is found, notify the installation specialist.

All packages should be closely examined at time of delivery. If damage is apparent, have notation *Damage in Shipment* written on **all** copies of the freight or express bill before delivery is accepted or signed for by a GE Healthcare representative or a hospital receiving agent. Whether noted or concealed, damage **MUST** be reported to the carrier immediately upon discovery or within 14 days after receipt, and the contents and containers held for inspection by the carrier. A transportation company will not pay a claim for damage if an inspection is not requested within this 14-day period.

To file a report:

- Call 1-800-548-3366 and use option 8.
- Fill out a report on <http://egems.med.ge.com/edq/home.jsp>
- Contact the local service coordinator for more information on this process.

Rev. September 17, 2006

CERTIFIED ELECTRICAL CONTRACTOR STATEMENT

All electrical Installations that are preliminary to positioning of the equipment at the site prepared for the equipment shall be performed by licensed electrical contractors. In addition, electrical feeds into the Power Distribution Unit shall be performed by licensed electrical contractors. Other connections between pieces of electrical equipment, calibrations and testing shall be performed by qualified GE Healthcare personnel. The products involved (and the accompanying electrical installations) are highly sophisticated, and special engineering competence is required. In performing all electrical work on these products, GE will use its own specially trained field engineers. All of GE's electrical work on these products will comply with the requirements of the applicable electrical codes.

The purchaser of GE equipment shall only utilize qualified personnel (i.e., GE's field engineers, personnel of third-party service companies with equivalent training, or licensed electricians) to perform electrical servicing on the equipment.

IMPORTANT...X-RAY PROTECTION

X-ray equipment, if not properly used, may cause injury. Accordingly, the instructions herein contained should be thoroughly read and understood by everyone who will use the equipment before he or she attempts to place this equipment in operation. The GE Healthcare Company will be glad to assist and cooperate in placing this equipment in use.

Although this apparatus incorporates a high degree of protection against x-radiation other than the useful beam, no practical design of equipment can provide complete protection. Nor can any practical design compel the operator to take adequate precautions to prevent the possibility of any persons carelessly exposing themselves or others to radiation.

It is important that anyone having anything to do with x-radiation be properly trained and fully acquainted with the recommendations of the National Council on Radiation Protection and Measurements as published in NCRP Reports available from NCRP Publications, 7910 Woodmont Avenue, Room 1016, Bethesda, Maryland 20814, and of the International Commission on Radiation Protection, and take adequate steps to protect against injury.

The equipment is sold with the understanding that the GE Healthcare, its agents, and representatives have no responsibility for injury or damage which may result from improper use of the equipment. Various protective materials and devices are available. It is urged that such materials or devices be used.

IMPORTANT...RADIOACTIVE MATERIAL HANDLING

Only employees formally trained in radioactive materials handling and this equipment are authorized by the GE Healthcare Radiation Safety Officer to use radioactive materials to service this equipment.

GE Healthcare Services is required to notify the applicable U.S. state agency PRIOR to any source service event involving pin source handling. See NUC/PET Radioactive material guides for specific instruction or contact your EHS Specialist.

A radiation survey must be performed when a pin source has been removed and replaced. See Radiation Survey Form Instructions or contact your EHS Specialist.

Rev 2 (July 21, 2005)

LITHIUM BATTERY CAUTIONARY STATEMENTS

CAUTION
Risk of
Explosion

Danger of explosion if battery is incorrectly replaced. Replace only with the same or equivalent type recommended by the manufacturer. Discard used batteries according to the manufacturer's instructions.

ATTENTION
Danger
d'Explosion

Il y a danger d'explosion s'il y a remplacement incorrect de la batterie. Remplacer uniquement avec une batterie du même type ou d'un type recommandé par le constructeur. Mettre au rebut les batteries usagées conformément aux instructions du fabricant.

OMISSIONS & ERRORS

Customers, contact your GE Healthcare Sales or Service representatives.

GE personnel, use the GEMS iTrak/PQR Process to report all omissions, errors, and defects in this publication.

COPYRIGHTS

All Material Copyrighted © 2005 by the General Electric Company. All rights reserved.

Revision History

Revision	Date	Reason for Change
1	3/05/05	Initial Release.
2	3/22/05	FRU Corrections for Product M3 Release.
3	8/02/05	HP8200 PC.
4	8/22/05	New Console for use with Pro32.
5	9/27/05	PQR 13047498: Added missing SCIM and keyboard info.
6	11/04/05	PQR 13051377: Add console assembly drawing, 5115335ADW
7	1/30/06	FRU correction (Scan Disk Array).
8	8/25/06	Updates for Jarrell; added chapter for console differences as used with a PET scanner.
9	11/28/06	Updated Chapter 1; added 5115335-22 console.
10	03/28/08	Updated Language section in Important Precautions; Added new P/N 5117866-51 for HP8200 Host Computer and FX1500 Graphics Card with 4gb of Memory Updated BOMs in Chapter 1. SPR FCTge32771: Removed Chapter 1, section 1.4: "Console Assy, VCT-GRE with 1-IG 4-HDD, for LightSpeed Pro32." This console assembly was never released. (phr)
11	12/5/08	Important Precautions: added new languages (PT-BR, PT-PT, SR) SPR FCTge43413: Replaced Figures 1-1 through 1-12 with updated 5115335 ADW Rev 8. Updated 5115335 BOM to Rev. 16 Updated 5115335-2 BOM to Rev. 17 Updated 5115335-12 BOM to Rev. 18 Updated 5125213 BOM to Rev. 11 Updated 5114536 BOM to Rev. 11 Updated 5143778 BOM to Rev. 4 Updated 2336374 BOM to Rev. 2

End of Revision History.

Table of Contents

Chapter 1

GOC5	19
Section 1.0 — GOC5 Varieties	19
1.1 GOC5 with HP8000 PC and Three IGs - VCT (5115335)	20
GOC5 (5115335 Sheet 1, Rev 8)	20
GOC5 (5115335 Sheet 2, Rev 8)	21
GOC5 (5115335 Sheet 3, Rev 8)	22
GOC5 (5115335 Sheet 4, Rev 8)	23
Console Assy, VCT-GRE (5115335 BOM, Rev 16)	24
1.2 GOC5 with HP8200 PC and Three IGs - VCT (5115335-2)	26
GOC5 (5115335 Sheet 5 - Partial, Rev 8).....	26
GOC5 (5115335 Sheet 6, Rev 8)	27
GOC5 (5115335 Sheet 7, Rev 8)	28
GOC5 (5115335 Sheet 4, Rev 8)	29
Console Assy, VCT-GRE with XW8200 Host (5115335-2 BOM, Rev 17).....	30
1.3 GOC5 with HP8200 PC and One IG - Pro32 (5115335-12)	32
GOC5 (5115335 Sheet 5 - Partial, Rev 8).....	32
GOC5 (5115335 Sheet 6, Rev 8)	33
GOC5 (5115335 Sheet 7, Rev 8)	34
GOC5 (5115335 Sheet 4, Rev 8)	35
Console Assy, VCT-GRE with 1 IG, for LightSpeed Pro32 (5115335-12 BOM, Rev 18).....	36
Section 2.0 — Console Chassis Assy - GOC5 (5125213).....	38
Console Chassis Assy - GOC5 (5125213 Sheet 1, Rev 9)	38
Console Chassis Assy - GOC5 (5125213 Sheet 2, Rev 9)	39
Console Chassis Assy - GOC5 (5125213 BOM, Rev 11)	40
2.1 SubAssy, Power Distribution Switch Panel - VCT (5122587)	44
SubAssy, Power Distribution Switch Panel - VCT (5122587 Sheet 1, Rev 7).....	44
SubAssy, Power Distribution Switch Panel - VCT (5122587 Sheet 2, Rev 7).....	45
SubAssy, Power Distribution Switch Panel - VCT (5122587 BOM, Rev 3).....	46
2.2 SubAssy, Console Rear Bulkhead Panel - VCT (5122506)	48
SubAssy, Console Rear Bulkhead Panel - VCT (5122506 Sheet 1, Rev 5)	48
SubAssy, Console Rear Bulkhead Panel - VCT (5122506 BOM, Rev 5).....	49

Section 3.0 — Disk Array, 2U 8drive U320 - VDA (5114536)	50
Disk Array, 2U 8drive U320 - VDA (5114536 BOM, Rev 11)	50
Section 4.0 — Cover Assy - Console Front (5128181)	51
Cover Assy - Console Front (5128181 Sheet 1, Rev 1)	51
Cover Assy - Console Front (5128181 BOM, Rev 1)	52
Section 5.0 — Flat Panel Monitors (B7858LC)	53
Flat Panel Monitors (B7858LC BOM, Rev 3)	53
Section 6.0 — Keyboard with SCIM, Collectors	54
Keyboard and SCIM Assembly (Rev 11/15/00)	54
6.0.1 — Keyboard with SCIM Collector - English (2275758)	55
Keyboard with SCIM Collector - English (2275758 BOM, Rev 5)	55
6.0.1.1 — SCIM Collector – English (2275752)	55
SCIM Collector - English (2275752 BOM, Rev 2)	55
6.0.2 – French (2275758-2)	56
Keyboard with SCIM Collector - French (2275758-2 BOM, Rev 3)	56
6.0.2.1 – SCIM Collector - French (2275752-2)	56
SCIM Collector - French (2275752-2 BOM, Rev 2)	56
6.0.3 – German (2275758-3)	57
Keyboard with SCIM Collector - German (2275758-3 BOM, Rev 3)	57
6.0.3.1 – SCIM Collector - German (2275752-3)	57
SCIM Collector - German (2275752-3 BOM, Rev 2)	57
6.0.4 – Swedish (2275758-4)	57
Keyboard with SCIM Collector - Swedish (2275758-4 BOM, Rev 3)	57
6.0.5 – International (2275758-5)	58
Keyboard with SCIM Collector - International (2275758-5 BOM, Rev 3)	58
6.0.5.1 – SCIM Collector - International (2275752-4)	58
SCIM Collector - International (2275752-4 BOM, Rev 3)	58
6.0.6 – Spanish (2275752-7 Rev 1)	59
SCIM Collector - Spanish (2275752-7 BOM Rev 1)	59
6.0.7 – Italian (2275752-8)	59
SCIM Collector - Italian (2275752-8 BOM Rev 1)	59
6.0.8 – Portugese (2275752-9)	59
SCIM Collector - Portugese (2275752-9 BOM Rev 1)	59

	6.0.9 – English and Chinese (2275752-10)	60
	SCIM Collector - English and Chinese (2275752-10 BOM Rev 3)	60
	<i>6.0.9.1 – Keyboard and SCIM Collector - English and Chinese (2275758-10)</i>	60
	SCIM Collector - English and Chinese (2275758-10 BOM Rev 3)	60
	6.0.10 – Japanese (2275752-11)	60
	SCIM Collector - Japanese (2275752-11 BOM Rev 1)	60
6.1	Keyboard with SCIM Collector - International (2275758-5)	61
	Keyboard with SCIM Collector - International (2275758-5 BOM, Rev 3)	61
	6.1.1 – SCIM Collector - International (2275752-4)	61
	SCIM Collector - International (2275752-4 BOM, Rev 3)	61

Chapter 2

PET Additions	63
Discovery Console Update (P5053RG BOM, Rev 0)	63
Section 1.0 — Console Collector Kit - GOC4 on DST Highlander (5143778)	64
Console Collector Kit - GOC4 on DST Highlander (5143778 BOM, Rev 4)	64
1.1 DLS-SCIM Console Purchased ASM (2336374)	64
DLS-SCIM Console Purchased ASM (2336374 BOM, Rev 2)	64

Chapter 1

GOC5

Section 1.0 — GOC5 Varieties

There are multiple variations of the GOC5 console, depending on host computer model, number of IGs, gantry type, etc. Make sure to view the information that applies to the console for the appropriate system.

- [GOC5 with HP8000 PC and Three IGs - VCT \(5115335\): see page 20.](#)
- [GOC5 with HP8200 PC and Three IGs - VCT \(5115335-2\): see page 26.](#)
- [GOC5 with HP8200 PC and One IG - Pro32 \(5115335-12\): see page 32.](#)

1.1 GOC5 with HP8000 PC and Three IGs - VCT (5115335)




Figure 1-1 GOC5 (5115335 Sheet 1, Rev 8)





Figure 1-2 GOC5 (5115335 Sheet 2, Rev 8)






Figure 1-4 GOC5 (5115335 Sheet 4, Rev 8)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
3	5114523-2	1	Yes	Computer, Data Acquisition Recon Control - Ed 2
4	5114533-2	3	Yes	VIG Computer - with updated VRAC
5	5114536	1	Yes	Disk Array, 2U 8drive U320 - VDA (For further detail, see Section 3.0, beginning on page 50.)
6	2404320	1	Yes	CONSOLE INTERCOM PRESCRIBED-TILT HUB
7	5270193	1	Yes	Ethernet Switch with power supply and power cord.
8	2368838	1	Yes	SCSI TOWER, DVD-RAM, MOD
11	2304737-2	3	Yes	CABLE, DVI VIDEO CABLE - OCTANE II
16	2324697-2	1	Yes	SCSI CABLE, VHD68 TO CENT 50, LINUX
17	2368697-2	1	Yes	LINUX DDR WORKSTATION 3BUTTON PS2 MOUSE
18	2399753	1	Yes	TRACKBALL - 3 BTTN USB for GRE
19	5127222-2	4	Yes	Cable, Ethernet, 2ft Lg - CAT5e, 4 twisted pair, 24awg solid copper, Shielded - aluminized polyester and tinned copper, gray PVC jacket, snagless PVC boot, Plugs - UL94V-0 rated polycarbonate with metallic strain relief, EIA-TIA568, UL listed, CMR rated,
41	2214164	1	Yes	5.25~ 2.3GB 512 BYTES/SECTOR MOD
42	2337414	2	Yes	DVD RAM MEDIA, 9.4 GB
43	2227726	1	Yes	MOUSE PAD FOR LIGHTSPEED
44	46-136246P14	1	Yes	2~ WIDE, WHT, ADH BACK, VELCRO LOOP 25 YD
45	46-136246P21	1	Yes	2~ WIDE X 25 YD WHITE VELCRO HOOKS
46	46-208747P2	1	Yes	ADHESIVE MOUNT - CABLE TIE
47	46-208758P3	2	Yes	7.31~ X .184~ SELF-LOCKING CABLE TIE 1/16~ TO 1-3/4~ WIRE BUNDLE RANGE. 50LB TENSILE STRENGTH, NYLON MATR~L.
48	46-208758P1	2	Yes	3.62~ X .094~ CABLE TIE 1/16~ TO 5/8~ WIRE BUNDLE RANGE 18LB TENSILE STRENGTH, NYLON MATR~L.
49	46-208758P9	3	Yes	11.08~X .140~ SELF-LOCKING CABLE TIE 1/16~ TO 3~ WIRE BUNDLE RANGE. 40LB TENSILE STRENGTH, NYLON MATR~L. (DWG REV 5/92, JFK - OK).
-	5117866-28	1	Yes	Host Computer, CTPET HP8200 with FX1400 Graphics Card and 4GB Memory
-	5248406	1	Yes	CABLE, SCSI 900mm, VHDCI 68m - VHDCI 68m, with Tin plated Copper Tape

Table 1-1 Console Assy, VCT-GRE (5115335 BOM, Rev 16)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
1	5125213	1	No	Console Chassis Assy - GOC5 (For further detail, see Section 2.0, beginning on page 38.)
2	5115333	1	No	Computer, 5U VCT Host
20	2337534	1	No	SIDE COVERS GOC
21	5128181	1	No	Cover Assy - Console Front (For further detail, see Section 4.0, beginning on page 51.)
22	5116147-2	1	No	CABLE, SCSI VHDCI68m-VHDCI68m x 610mm -B-
23	5116147	1	No	CABLE, SCSI VHDCI68m-VHDCI68m x 610mm
24	46-302200P9	1	No	BLANK RATING PLATE FOR SERIAL NO ETC
25	2386393-2	1	No	LABEL, ETL COMPONENT APPROVAL, INFORMATION TECHNOLOGY EQUIPMENT
26	2366442-27	2	No	BRACKET, RACK MOUNT HOST COMPUTER
27	2132620	1	No	EMC LABEL CLASS A GROUP 1
30	46-279769P1	1	No	IEC TYPE B SYMBOL
31	2117390-2	1	No	CE Compliance and WEEE Labels
36	46-269337P6	1	No	LABEL OLD
39	46-312358P51	18	No	M5 X 0.8 X 12MM METRIC FREEDRIV ZINC PLATED CROSS RECESSED PAN HEAD MACHINE SCREW
40	2103585-2	4	No	SCREW PAN HEAD 4 MM 10 MM SPRING WASHER, ZINC PLATED, STEEL
50	2240540	1	No	NETSCAPE LICENSE

Table 1-1 Console Assy, VCT-GRE (5115335 BOM, Rev 16)

1.2 GOC5 with HP8200 PC and Three IGs - VCT (5115335-2)




Figure 1-5 GOC5 (5115335 Sheet 5 - Partial, Rev 8)




Figure 1-6 GOC5 (5115335 Sheet 6, Rev 8)




Figure 1-7 GOC5 (5115335 Sheet 7, Rev 8)




Figure 1-8 GOC5 (5115335 Sheet 4, Rev 8

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
2	5117866-28	1	Yes	Host Computer, CTPET HP8200 with FX1400 Graphics Card and 4GB Memory
3	5159833	1	Yes	VDARC - Volume Data Acq Recon Control Computer, 2nd Edition
4	5159834-3	3	Yes	Jarrell VCT IG with VRAC2, Improved EMC Performance
5	5114536	1	Yes	Disk Array, 2U 8drive U320 - VDA (For further detail, see Section 3.0, beginning on page 50.)
6	2404320	1	Yes	CONSOLE INTERCOM PRESCRIBED-TILT HUB
7	5270193	1	Yes	Ethernet Switch with power supply and power cord.
8	5167410	1	Yes	Peripheral Tower, dual-bay, MOD-DVDram
11	2304737-2	3	Yes	CABLE, DVI VIDEO CABLE - OCTANE II
16	2324697-2	1	Yes	SCSI CABLE, VHD68 TO CENT 50, LINUX
17	2368697-2	1	Yes	LINUX DDR WORKSTATION 3BUTTON PS2 MOUSE
18	2399753-2	1	Yes	TRACKBALL, RoHS - 3 BTTN USB for GRE
19	5127222-2	4	Yes	Cable, Ethernet, 2ft Lg - CAT5e, 4 twisted pair, 24awg solid copper, Shielded - aluminized polyester and tinned copper, gray PVC jacket, snagless PVC boot, Plugs - UL94V-0 rated polycarbonate with metallic strain relief, EIA-TIA568, UL listed, CMR rated,
22	5248406	2	Yes	CABLE, SCSI 900mm, VHDCI 68m - VHDCI 68m, with Tin plated Copper Tape
41	2214164	1	Yes	5.25~ 2.3GB 512 BYTES/SECTOR MOD
42	2337414	2	Yes	DVD RAM MEDIA, 9.4 GB
43	2227726	1	Yes	MOUSE PAD FOR LIGHTSPEED
44	46-136246P14	1	Yes	2~ WIDE, WHT, ADH BACK, VELCRO LOOP 25 YD
45	46-136246P21	1	Yes	2~ WIDE X 25 YD WHITE VELCRO HOOKS
46	46-208747P2	1	Yes	ADHESIVE MOUNT - CABLE TIE
47	46-208758P3	2	Yes	7.31~ X .184~ SELF-LOCKING CABLE TIE 1/16~ TO 1-3/4~ WIRE BUNDLE RANGE. 50LB TENSILE STRENGTH, NYLON MATR~L.
48	46-208758P1	2	Yes	3.62~ X .094~ CABLE TIE 1/16~ TO 5/8~ WIRE BUNDLE RANGE 18LB TENSILE STRENGTH, NYLON MATR'L.
49	46-208758P9	3	Yes	11.08~X .140~ SELF-LOCKING CABLE TIE 1/16~ TO 3~ WIRE BUNDLE RANGE. 40LB TENSILE STRENGTH, NYLON MATR~L. (DWG REV 5/92, JFK - OK).

Table 1-2 Console Assy, VCT-GRE with XW8200 Host (5115335-2 BOM, Rev 17)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
-	5114523-2	1	Yes	Computer, Data Acquisition Recon Control - Ed 2
-	5114533-2	1	Yes	VIG Computer - with updated VRAC
-	5117866-51	1	Yes	Host Computer, CTPET HP8200 with FX1500 Graphics Card and 4GB Memory
1	5125213	1	No	Console Chassis Assy - GOC5 (For further detail, see Section 2.0, beginning on page 38.)
20	2337534	1	No	SIDE COVERS GOC
21	5128181	1	No	Cover Assy - Console Front (For further detail, see Section 4.0, beginning on page 51.)
24	46-302200P9	1	No	BLANK RATING PLATE FOR SERIAL NO ETC
25	2386393-2	1	No	LABEL, ETL COMPONENT APPROVAL, INFORMATION TECHNOLOGY EQUIPMENT
26	2366442-27	2	No	BRACKET, RACK MOUNT HOST COMPUTER
27	2132620	1	No	EMC LABEL CLASS A GROUP 1
30	46-279769P1	1	No	IEC TYPE B SYMBOL
31	2117390-2	1	No	CE Compliance and WEEE Labels
36	46-269337P6	1	No	LABEL OLD
39	46-312358P51	18	No	M5 X 0.8 X 12MM METRIC FREEDRIV ZINC PLATED CROSS RECESSED PAN HEAD MACHINE SCREW
40	2103585-2	4	No	SCREW PAN HEAD 4 MM 10 MM SPRING WASHER, ZINC PLATED, STEEL
50	2240540	1	No	NETSCAPE LICENSE
51	5194414	1	No	Cable Labels for VCT

Table 1-2 Console Assy, VCT-GRE with XW8200 Host (5115335-2 BOM, Rev 17)

Note: 5117866-51 requires software release 07mw18.4 or newer.

1.3 GOC5 with HP8200 PC and One IG - Pro32 (5115335-12)




Figure 1-9 GOC5 (5115335 Sheet 5 - Partial, Rev 8)




Figure 1-10 GOC5 (5115335 Sheet 6, Rev 8)






Figure 1-12 GOC5 (5115335 Sheet 4, Rev 8)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
2	5183547-38	1	Yes	GEHC MI and CT Integrated Buy Level PC Workstation. HP8400 with 4GB Memory
3	5159833	1	Yes	VDARC - Volume Data Acq Recon Control Computer, 2nd Edition
4	5159834-3	1	Yes	Jarrell VCT IG with VRAC2, Improved EMC Performance
5	5114536	1	Yes	Disk Array, 2U 8drive U320 - VDA (For further detail, see Section 3.0, beginning on page 50.)
6	2404320-2	1	Yes	CONSOLE INTERCOM PRESCRIBED-TILT HUB
7	5270193	1	Yes	Ethernet Switch with power supply and power cord.
8	5167410	1	Yes	Peripheral Tower, dual-bay, MOD-DVDram
11	2304737-2	3	Yes	CABLE, DVI VIDEO CABLE - OCTANE II
16	2324697-2	1	Yes	SCSI CABLE, VHD68 TO CENT 50, LINUX
17	2368697-2	1	Yes	LINUX DDR WORKSTATION 3BUTTON PS2 MOUSE
18	2399753-2	1	Yes	TRACKBALL, RoHS - 3 BTTN USB for GRE
19	5127222-2	2	Yes	Cable, Ethernet, 2ft Lg - CAT5e, 4 twisted pair, 24awg solid copper, Shielded - aluminized polyester and tinned copper, gray PVC jacket, snagless PVC boot, Plugs - UL94V-0 rated polycarbonate with metallic strain relief, EIA-TIA568, UL listed, CMR rated,
22	5248406	2	Yes	CABLE, SCSI 900mm, VHDCI 68m - VHDCI 68m, with Tin plated Copper Tape
42	2337414	2	Yes	DVD RAM MEDIA, 9.4 GB
43	2227726	1	Yes	MOUSE PAD FOR LIGHTSPEED
44	46-136246P14	1	Yes	2~ WIDE, WHT, ADH BACK, VELCRO LOOP 25 YD
45	46-136246P21	1	Yes	2~ WIDE X 25 YD WHITE VELCRO HOOKS
46	46-208747P2	1	Yes	ADHESIVE MOUNT - CABLE TIE
47	46-208758P3	2	Yes	7.31~ X .184~ SELF-LOCKING CABLE TIE 1/16~ TO 1-3/4~ WIRE BUNDLE RANGE. 50LB TENSILE STRENGTH, NYLON MATR~L.
48	46-208758P1	2	Yes	3.62~ X .094~ CABLE TIE 1/16~ TO 5/8~ WIRE BUNDLE RANGE 18LB TENSILE STRENGTH, NYLON MATR'L.
49	46-208758P9	3	Yes	11.08~ X .140~ SELF-LOCKING CABLE TIE 1/16~ TO 3~ WIRE BUNDLE RANGE. 40LB TENSILE STRENGTH, NYLON MATR~L. (DWG REV 5/92, JFK - OK).
-	2404320	1	Yes	CONSOLE INTERCOM PRESCRIBED-TILT HUB

Table 1-3 Console Assy, VCT-GRE with 1 IG, for LightSpeed Pro32 (5115335-12 BOM, Rev 18)


MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
-	5114523-2	1	Yes	Computer, Data Acquisition Recon Control - Ed 2
-	5114533-2	1	Yes	VIG Computer - with updated VRAC
-	5117866-28	1	Yes	Host Computer, CTPET HP8200 with FX1400 Graphics Card and 4GB Memory
-	5117866-51	1	Yes	Host Computer, CTPET HP8200 with FX1500 Graphics Card and 4GB Memory
1	5125213	1	No	Console Chassis Assy - GOC5 (For further detail, see Section 2.0, beginning on page 38.)
10	2366442-31	2	No	PANEL - COVER
20	2337534	1	No	SIDE COVERS GOC
21	5128181	1	No	Cover Assy - Console Front (For further detail, see Section 4.0, beginning on page 51.)
24	46-302200P9	1	No	BLANK RATING PLATE FOR SERIAL NO ETC
25	2386393-2	1	No	LABEL, ETL COMPONENT APPROVAL, INFORMATION TECHNOLOGY EQUIPMENT
26	2366442-27	2	No	BRACKET, RACK MOUNT HOST COMPUTER
27	2132620	1	No	EMC LABEL CLASS A GROUP 1
30	46-279769P1	1	No	IEC TYPE B SYMBOL
31	2117390-2	1	No	CE Compliance and WEEE Labels
36	46-269337P6	1	No	LABEL OLD
39	46-312358P51	18	No	M5 X 0.8 X 12MM METRIC FREEDRIV ZINC PLATED CROSS RECESSED PAN HEAD MACHINE SCREW
40	2103585-2	4	No	SCREW PAN HEAD 4 MM 10 MM SPRING WASHER, ZINC PLATED, STEEL
41	2214164	1	No	5.25~ 2.3GB 512 BYTES/SECTOR MOD
50	2240540	1	No	NETSCAPE LICENSE
51	5194414	1	No	Cable Labels for VCT

Table 1-3 Console Assy, VCT-GRE with 1 IG, for LightSpeed Pro32 (5115335-12 BOM, Rev 18)

Note: 5117866-51 requires software release 07mw18.4 or newer.

Section 2.0 — Console Chassis Assy - GOC5 (5125213)

FRU = NO






Figure 1-14 Console Chassis Assy - GOC5 (5125213 Sheet 2, Rev 9)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
2	5122587	1	Yes	SubAssy, Power Distribution Switch Panel - VCT (For further detail, see Section 2.1, beginning on page 44.)
5	2315117	1	Yes	CABLE, PS/2 MOUSE CABLE, LINUX
6	2315117-2	1	Yes	CABLE, PS/2 KEYBOARD CABLE, LINUX
7	5123478	1	Yes	Cable, USB Bulkhead, USB-Af to USB-Am x 3ft Lg
9	2142225	6	Yes	MONITOR POWER CORD
10	2142226	5	Yes	POWER CORD FOR EMC AREA
38	2315657	1	Yes	TABLE TOP ASSEMBLY, MONITOR, GOC
39	2330566	1	Yes	TABLE TOP ASSEMBLY, KEYBOARD, GOC
55	5124071	4	Yes	Fan, Tube Axial - 115VAC, 50-60Hz, 119mm x 119mm x 25mm x 95-115cfm, ball bearing motor - Sinwan S125AP-11-1
56	5127629	1	Yes	Cable Assy - Exhaust Fan Power
61	5123485	1	Yes	Rear Access Cover - VCT
62	5128404	1	Yes	Assy, ICOM cable harness for VCT console
63	5128409	1	Yes	Assy, Gbe cable harness for VCT console
-	5323650	1	Yes	Console Monitor Table Top FRU
-	5327046	1	Yes	Console Keyboard Table Top FRU
1	2366442	1	No	CONSOLE CHASSIS SUB-ASSY, GRE
3	5123480	1	No	Bracket, Cable Cover - Dual PS2f, Single USB-Af
8	46-328421P3	6	No	SCREW PAN HEAD 2.5 MM 5 MM ZINC PLATED, STEEL
11	5122506	1	No	SubAssy, Console Rear Bulkhead Panel - VCT (For further detail, see Section 2.2, beginning on page 48.)
12	2180698-2	34	No	CLIP NUT ASSEMBLY, M5
13	2318681	2	No	ANTI-TIP LEG, CONSOLE CHASSIS
14	2319043	4	No	CASTER, 2 1/2~ SWIVEL
15	2103585	43	No	SCREW PAN HEAD 4 MM 8 MM SPRING WASHER, ZINC PLATED, STEEL
16	2325236	2	No	LEVELER, CONSOLE ANTI-TIP LEGS

Table 1-4 Console Chassis Assy - GOC5 (5125213 BOM, Rev 11)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
17	2109867-25	4	No	SCREW HEXAGON SOCKET
18	2109877-2	16	No	NUT HEXAGON 6 MM
19	2109878-4	4	No	WASHER FLAT ISO7089 M10 A2
20	2109881-3	24	No	WASHER LOCK - INTERNAL 6.4 MM 11 MM
21	2109881-4	4	No	WASHER LOCK - INTERNAL 10.5 MM 18 MM
23	2366442-12	4	No	BRACKET, SIDE COVER MTG
24	2366442-13	3	No	BRACKET, FRONT COVER MTG
27	2366442-6	2	No	PANEL, RACK MOUNT
28	2366442-7	8	No	BRACKET, RACK MOUNT
31	46-328431P2	24	No	WASHER PLAIN - LARGE 6.4 MM 18 MM ZINC PLATED, STEEL
32	46-170686P3	0	No	LOCTITE 242, 50CC 12 MONTH SHELF LIFE FROM DATE OF SHIPMENT FROM THE MANUFACTURER.
33	2376906	6	No	SOUTHCO 1/4 TURN RCVR 85-35-295-20
34	2337083-2	8	No	SCREW, M6 X 20 SOC HEAD, 12.9 CLASS
40	46-312358P51	26	No	M5 X 0.8 X 12MM METRIC FREEDRIV ZINC PLATED CROSS RECESSED PAN HEAD MACHINE SCREW
41	46-208758P3	19	No	7.31~ X .184~ SELF-LOCKING CABLE TIE 1/16~ TO 1-3/4~ WIRE BUNDLE RANGE. 50LB TENSILE STRENGTH, NYLON MATR~L.
42	5114923-2	1	No	Bracket, ICOM Lower
43	5114924-2	1	No	Bracket, ICOM Upper
44	5122710	2	No	M4 Tapped Hole Speed Nut
52	5123481	1	No	Panel, Outlet Box Mtg
53	5123484	1	No	Bracket, Exhaust Fan Mtg - Left
54	5123484-2	1	No	Bracket, Exhaust Fan Mtg - Right
57	46-272301P11	4	No	FAN ACCESSORIES FINGER GUARD PAPST LZ30
58	46-312358P44	16	No	M4 X 0.7 X 35MM METRIC FREEDRIV ZINC PLATED CROSS RECESSED PAN HEAD MACHINE SCREW
59	2381089-3	16	No	SCREW, SS NYLOCK HEX NUT, M4
60	46-328430P2	16	No	WASHER PLAIN - NORMAL 4.3 MM 9 MM ZINC PLATED, STEEL

Table 1-4 Console Chassis Assy - GOC5 (5125213 BOM, Rev 11)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
64	46-271110P1	1	No	LABEL, PROTECTIVE EARTH (GROUND) IEC STANDARD GRAPHIC SYMBOL
65	46-328431P1	8	No	WASHER PLAIN - LARGE 4.3 MM 12 MM ZINC PLATED, STEEL

Table 1-4 Console Chassis Assy - GOC5 (5125213 BOM, Rev 11)

FRU = YES






Figure 1-16 SubAssy, Power Distribution Switch Panel - VCT (5122587 Sheet 2, Rev 7)

MARK	NUMBER	QTY	FRU	DESCRIPTION
3	2351490	1.0	Yes	18-32A CONTACTOR
4	46-278446P1	8.0	Yes	15A, 125VAC, 2 POLE, 3 WIRE DUPLEX TYPE, GRAY IN COLOR. (REV TK, 7/91).
5	46-297335P3	2.0	Yes	16A, 250V 2-STAGE PWR LINE FILTER
31	2368504	1.0	Yes	CONVERTER, DB25 TO USB
1	5122594	1.0		Panel, Outlet Box Main - VCT
2	2379871	1.0		HUBBELL FLANGED INLET HBL 2415
6	46-328425P10	20.0		NUT HEXAGON 3 MM
7	46-328425P1	3.0		NUT HEXAGON 4 MM
8	46-312358P30	3.0		M3 X 0.5 X 12MM METRIC FREEDRIV ZINC PLATED CROSS RECESSED PAN HEAD MACHINE SCREW
9	46-328430P2	3.0		WASHER PLAIN - NORMAL 4.3 MM 9 MM ZINC PLATED, STEEL
10	46-208697P57	2.0		HEYCO PART NO.1247 SR-7W-2 BLACK
11	46-311804P2	20.0		3.2X9X.8 ZP ST DIN
12	46-311805P10	20.0		HELICAL LOCK WASHER M3 ZP DIN
13	46-208758P2	3.0		5.5~ X .140~ SELF-LOCKING CABLE TIE. 1/16~ TO 1-1/4~ WIRE BUNDLE RANGE. 30LB TENSILE STRENGTH, NYLON MATR~L.
14	2336074	2.0		CIRCUIT BREAKER 15 AMPS 240 VOLTS 80
15	46-328421P501	4.0		SCREW PAN HEAD 3 MM 5 MM
16	5122395	1.0		Cable, SysLite Outlet Box - internal
21	5123565	1.0		Bracket, Power Switch Mtg
22	2367804-3	1.0		REAR COVER - POWER SWITCH (GRE)
23	2336081	1.0		ROCKER SWITCH, 2PST
24	5122588	1.0		Cable, Outlet Box to Power Switch - GOC5
25	5122589	1.0		Adapter, Bulkhead RJ45 CAT5e Shielded, L-com #TDG1026KS-C5E
26	5127222-2	1.0		Cable, Ethernet, 2ft Lg - CAT5e, 4 twisted pair, 24awg solid copper, Shielded - aluminized polyester and tinned copper, gray PVC jacket, snagless PVC boot, Plugs - UL94V-0 rated polycarbonate with metallic strain relief, EIA-TIA568, UL listed, CMR rated,
28	2103585	3.0		SCREW PAN HEAD 4 MM 8 MM SPRING WASHER, ZINC PLATED, STEEL

Table 1-5 SubAssy, Power Distribution Switch Panel - VCT (5122587 BOM, Rev 3)

MARK	NUMBER	QTY	FRU	DESCRIPTION
29	46-328430P2	7.0		WASHER PLAIN - NORMAL 4.3 MM 9 MM ZINC PLATED, STEEL
30	46-328425P1	6.0		NUT HEXAGON 4 MM
32	46-170012P34	2.0		4-40, 1/4~ HEX, 3/32 THICK KEPS NUT O~ALL HT 7/64 WASH OD 9/32 WASH MAT THK .013 CAD PL KEPS
33	5125199	1.0		Lead Wire Data - Outlet Panel Assy
34	2150839	1.0		CAUTION RECEPTACLES NOT FOR GEN USE
35	46-271110P1	1.0		LABEL, PROTECTIVE EARTH (GROUND) IEC STANDARD GRAPHIC SYMBOL
36	2150839	1.0		CAUTION RECEPTACLES NOT FOR GEN USE

Table 1-5 SubAssy, Power Distribution Switch Panel - VCT (5122587 BOM, Rev 3) (Continued)

2.2 SubAssy, Console Rear Bulkhead Panel - VCT (5122506)

FRU = NO




Figure 1-17 SubAssy, Console Rear Bulkhead Panel - VCT (5122506 Sheet 1, Rev 5)

MARK	NUMBER	QTY	FRU	DESCRIPTION
2	5119410	1.0	Yes	Cable Assy, Fiber Optic, 62.5-125um LDD ZIP, LC Duplex x 1M
6	5122589	7.0	Yes	Adapter, Bulkhead RJ45 CAT5e Shielded, L-com #TDG1026KS-C5E
9	5127222-3	4.0	Yes	Cable, Ethernet x 3ft Lg - CAT5e, 4 twisted pair, 24awg solid copper, Shielded - aluminized polyester and tinned copper, gray PVC jacket, snagless PVC boot, Plugs - UL94V-0 rated polycarbonate with metallic strain relief, EIA-TIA568, UL listed, CMR rated,
3	5119536	1.0		Panel, Bulkhead Console Rear Cable Connections
4	5122507	1.0		Bulkhead Adapter, Fiber Optic - LC to LC Duplex, plastic body, ceramic sleeve, 0.525in sq. panel opening: LCOM FOA-550A-OD1
5	5128594	1.0		Connector,filtered sub-d 25position adapter
7	46-170686P3	0.0		LOCTITE 242, 50CC 12 MONTH SHELF LIFE FROM DATE OF SHIPMENT FROM THE MANUFACTURER.
8	46-221417P4	2.0		FEMALE SCREWLOCKS FOR HD CONNECTORS. 4-40 THREAD, 0.470~ OVERALL LENGTH YELLOW CHROMATE, TWO PER KIT. 0.312~ BOTTOM, 0.094~ PANEL THK. MAX (KIT INCLUDES NUTS AND WASHERS)

Table 1-6 SubAssy, Console Rear Bulkhead Panel - VCT (5122506 BOM, Rev 5)

Section 3.0 — Disk Array, 2U 8drive U320 - VDA (5114536)

FRU = YES

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
1	5114536-11	8	Yes	Scan Disk Array, Hard Drive with mounting sled, Seagate ST373455LC Firmware Revision 001
2	5114536-20	1	Yes	VCT Disk Array Chassis Assembly
-	5114536-10	1	Yes	Scan Disk Array, Hard drive with mounting sled, Seagate ST373454LC Firmware 002

Table 1-7 Disk Array, 2U 8drive U320 - VDA (5114536 BOM, Rev 11

Section 4.0 — Cover Assy - Console Front (5128181)

FRU = NO




Figure 1-18 Cover Assy - Console Front (5128181 Sheet 1, Rev 1)

MARK	NUMBER	QTY	FRU	DESCRIPTION
4	5128180	1.0	Yes	Filter, 25 PPI Quadrafoam UL94 HF-1
1	2369619	1.0		COVER, CONSOLE FRONT - GRE
2	5124020	1.0		Foam, Sound Absorbing - 54in Wd x 1in Thick
3	46-136246P18	3.21		1~ WIDE, WHT, ADH BACK, VELCRO HOOK 75 FT PER RL

Table 1-8 Cover Assy - Console Front (5128181 BOM, Rev 1)

Section 5.0 — Flat Panel Monitors (B7858LC)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
1	5169069	2.0	Yes	OEM 19 INCHES COLOR MONITOR LCD 1990SXi - SILVER

Table 1-9 Flat Panel Monitors (B7858LC BOM, Rev 3)

Section 6.0 — Keyboard with SCIM, Collectors



Figure 1-19 Keyboard and SCIM Assembly (Rev 11/15/00)

6.0.1 Keyboard with SCIM Collector - English (2275758)

FRU = YES

MARK	NAME	QTY	FRU	DESCRIPTION
1	2275756	1.0	Yes	KEYBOARD, NORTH AMERICAN PC PS/2
2	2275757	1.0	Yes	FUNCTION KEY TEMPLATE - ENGLISH
3	2275752	1.0	Yes	SCIM COLLECTOR - ENGLISH
4	2323942	1.0	Yes	CABLE, HD50 TO HD50

Table 1-10 Keyboard with SCIM Collector - English (2275758 BOM, Rev 5)

6.0.1.1 SCIM Collector – English (2275752)

FRU = YES

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-11	1.0	Yes	OVERLAY, SCIM CT, TILT - ENGLISH

Table 1-11 SCIM Collector - English (2275752 BOM, Rev 2)

6.0.2 French (2275758-2)

MARK	NUMBER	QTY	FRU	DESCRIPTION
1	2275756-2	1.0	Yes	KEYBOARD, EUROPEAN FRENCH
3	2275752-2	1.0	Yes	SCIM COLLECTOR - FRENCH (For further detail, see “SCIM Collector - French (2275752-2),” on page 56.)
4	2323942	1.0	Yes	CABLE, HD50 TO HD50
2	2275757-2	1.0	No	FUNCTION KEY TEMPLATE - F

Table 1-12 Keyboard with SCIM Collector - French (2275758-2 BOM, Rev 3)

6.0.2.1 SCIM Collector - French (2275752-2)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-12	1.0	Yes	OVERLAY, SCIM CT, TILT - FRENCH

Table 1-13 SCIM Collector - French (2275752-2 BOM, Rev 2)

6.0.3 German (2275758-3)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
1	2275756-3	1.0	Yes	KEYBOARD, GERMAN PC PS/2
3	2275752-3	1.0	Yes	SCIM COLLECTOR - GERMAN (For further detail, see “SCIM Collector - German (2275752-3),” on page 57.)
4	2323942	1.0	Yes	CABLE, HD50 TO HD50
2	2275757-3	1.0	No	FUNCTION KEY TEMPLATE - GERMAN

Table 1-14 Keyboard with SCIM Collector - German (2275758-3 BOM, Rev 3)

6.0.3.1 SCIM Collector - German (2275752-3)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-13	1.0	Yes	OVERLAY, SCIM CT, TILT - GERMAN

Table 1-15 SCIM Collector - German (2275752-3 BOM, Rev 2)

6.0.4 Swedish (2275758-4)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
1	2275756-4	1.0	Yes	KEYBOARD, SWEDISH PC PS/2
3	2275752	1.0	Yes	SCIM COLLECTOR - ENGLISH (For further detail, see “SCIM Collector – English (2275752),” on page 55.)
4	2323942	1.0	Yes	CABLE, HD50 TO HD50
2	2275757	1.0	No	FUNCTION KEY TEMPLATE - E

Table 1-16 Keyboard with SCIM Collector - Swedish (2275758-4 BOM, Rev 3)

6.0.5 International (2275758-5)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
1	2275756	1.0	Yes	KEYBOARD, NORTH AMERICAN
3	2275752-4	1.0	Yes	SCIM COLLECTOR - INTERNATIONAL (For further detail, see “SCIM Collector - International (2275752-4),” on page 61.)
4	2323942	1.0	Yes	CABLE, HD50 TO HD50
2	2283830	1.0	No	FUNCTION KEY TEMPLATE COL

Table 1-17 Keyboard with SCIM Collector - International (2275758-5 BOM, Rev 3)

6.0.5.1 SCIM Collector - International (2275752-4)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-10	1.0	Yes	OVERLAY, SCIM CT, TILT - BLANK
3	2262158-14	1.0	Yes	OVERLAY, SCIM CT, TILT - JAPANESE
4	2262158-15	1.0	Yes	OVERLAY, SCIM CT, TILT - MANDARIN
5	2262158-12	1.0	Yes	OVERLAY, SCIM CT, TILT - FRENCH
6	2262158-13	1.0	Yes	OVERLAY, SCIM CT, TILT - GERMAN
7	2262158-16	1.0	Yes	OVERLAY, SCIM CT, TILT - SPANISH
8	2262158-17	1.0	Yes	OVERLAY, SCIM CT, TILT - ITALIAN
9	2262158-18	1.0	Yes	OVERLAY, SCIM CT, TILT - PORTUGUESE
10	2262158-11	1.0	Yes	OVERLAY, SCIM CT, TILT - ENGLISH

Table 1-18 SCIM Collector - International (2275752-4 BOM, Rev 3)

6.0.6 Spanish (2275752-7 Rev 1)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-16	1.0	Yes	OVERLAY, SCIM CT, TILT - SPANISH

Table 1-19 SCIM Collector - Spanish (2275752-7 BOM Rev 1)

6.0.7 Italian (2275752-8)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-17	1.0	Yes	OVERLAY, SCIM CT, TILT - ITALIAN

Table 1-20 SCIM Collector - Italian (2275752-8 BOM Rev 1)

6.0.8 Portugese (2275752-9)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-18	1.0	Yes	OVERLAY, SCIM CT, TILT - PORTUGUESE

Table 1-21 SCIM Collector - Portugese (2275752-9 BOM Rev 1)

6.0.9 English and Chinese (2275752-10)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-11	1.0	Yes	OVERLAY, SCIM CT, TILT - ENGLISH
4	2262158-15	1.0	Yes	OVERLAY, SCIM CT, TILT - MANDARIN

Table 1-22 SCIM Collector - English and Chinese (2275752-10 BOM Rev 3)

6.0.9.1 Keyboard and SCIM Collector - English and Chinese (2275758-10)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2275756	1.0	Yes	KEYBOARD, NORTH AMERICAN PC PS/2
2	2275757	1.0	Yes	FUNCTION KEY TEMPLATE - ENGLISH
3	2275757-8	1.0	Yes	FUNCTION KEY TEMPLATE - MANDARIN
4	2275752-10	1.0	No	SCIM COLLECTOR - ENGLISH and CHINESE
5	5149890	1.0	No	Warning Label
6	5149891	1.0	No	Warning Label

Table 1-23 SCIM Collector - English and Chinese (2275758-10 BOM Rev 3)

6.0.10 Japanese (2275752-11)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-14	1.0	Yes	OVERLAY, SCIM CT, TILT - JAPANESE

Table 1-24 SCIM Collector - Japanese (2275752-11 BOM Rev 1)

6.1 Keyboard with SCIM Collector - International (2275758-5)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
1	2275756	1.0	Yes	KEYBOARD, NORTH AMERICAN
3	2275752-4	1.0	Yes	SCIM COLLECTOR - INTERNATIONAL (For further detail, see “SCIM Collector - International (2275752-4),” on page 61.)
4	2323942	1.0	Yes	CABLE, HD50 TO HD50
2	2283830	1.0	No	FUNCTION KEY TEMPLATE COL

Table 1-25 Keyboard with SCIM Collector - International (2275758-5 BOM, Rev 3)

6.1.1 SCIM Collector - International (2275752-4)

MARK	NAME	QTY	FRU	DESCRIPTION
1	2262158	1.0	Yes	SCAN CONTROL INTERCOM MODULE
2	2262158-10	1.0	Yes	OVERLAY, SCIM CT, TILT - BLANK
3	2262158-14	1.0	Yes	OVERLAY, SCIM CT, TILT - JAPANESE
4	2262158-15	1.0	Yes	OVERLAY, SCIM CT, TILT - MANDARIN
5	2262158-12	1.0	Yes	OVERLAY, SCIM CT, TILT - FRENCH
6	2262158-13	1.0	Yes	OVERLAY, SCIM CT, TILT - GERMAN
7	2262158-16	1.0	Yes	OVERLAY, SCIM CT, TILT - SPANISH
8	2262158-17	1.0	Yes	OVERLAY, SCIM CT, TILT - ITALIAN
9	2262158-18	1.0	Yes	OVERLAY, SCIM CT, TILT - PORTUGUESE
10	2262158-11	1.0	Yes	OVERLAY, SCIM CT, TILT - ENGLISH

Table 1-26 SCIM Collector - International (2275752-4 BOM, Rev 3)

Chapter 2

PET Additions

This chapter lists the differences present in the GOC5 console for a PET/CT system.

MARK	NAME	QTY	FRU	DESCRIPTION
1	5143778	1.0	N	Console collector Kit - GOC4 on DST Highlander (For further detail, see Section 1.0, beginning on page 64.)

Table 2-1 Discovery Console Update (P5053RG BOM, Rev 0)

Section 1.0 — Console Collector Kit - GOC4 on DST Highlander (5143778)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
1	2346122-5	3	No	CABLE, ETHERNET, RJ45/RJ45, RW
2	2337414	2	No	DVD RAM MEDIA, 9.4 GB
3	2336374	1	No	DLS-SCIM CONSOLE PURCASHED ASM (For further detail, see Section 1.1, beginning on page 64.)
4	5132100	1	No	IDL Runtime SW License for LINUX
5	2284884	1	No	VXWORKS 5.4 LICENCE

Table 2-2 Console Collector Kit - GOC4 on DST Highlander (5143778 BOM, Rev 4)

1.1 DLS-SCIM Console Purcashed ASM (2336374)

MARK	NUMBER	QTY	FRU	DESCRIPTION/NAME
-	2262158-9	1	Yes	CABLE, 50 PIN SCIM KEYBOARD
-	2275756	1	Yes	KEYBOARD, NORTH AMERICAN PC PS/2
-	2283830-2	1	Yes	INTL FUNCTION KEY TEMPLATE COLLECTOR

Table 2-3 DLS-SCIM Console Purcashed ASM (2336374 BOM, Rev 2)

© 2005, General Electric Company.

GE Medical Systems, a General Electric Company, going to market as GE Healthcare.

3000 N. Grandview Boulevard

Waukesha, Wisconsin 53188

USA

www.gehealthcare.com

