

FCT SERVICE NOTE

SN05081621a

Class A Service information enclosed.

Date: August 16th 2005

Subject: Analog DASM causes OS Load Error

Effectivity: VCT M3a and forward until further notice

Details: NOTE: If an Analog DASM is connected to a VCT Console an Error is generated and should be ignored.

Symptom: An FE Performed A LFC on a HP8000 with an Analog DASM attached and BIOS 4.3.13 on SW vct.134.

During the OS load, the OS load stops with an error message "**Buffer Input/Output error on /dev/sdb**"

|Retry| |Ignore| |Continue|

Upon selecting **Continue** the load continues and completes.

The OS Load successfully loads as well as the CT applications. The DASM and all disk devices were correctly configured.

During bootup, several buffer I/O errors are seen and logged to **/var/log/messages** but this does not stop the self test and doesn't require operator intervention to continue the boot sequence.

Current HQ Activity: The Console Team is trying to understand why these errors occur.

Current Work Around: When loading the HOST OS on systems with a DASM connected, the errors associated are "**normal**" and FE's need to select "**Continue**" to load the OS. The errors during bootup and in **/var/log/messages** can be **ignored**.

Resolution:

James Lehouillier
Service Methods Design Engineer