

GE Healthcare MI&CT Class C eService Notes are copyright (c) protected to General Electric Company Inc with all rights reserved. Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare Systems. Disclosure to persons not employed by GE Healthcare or not in possession of a Advanced Service Agreement with GE Healthcare is prohibited.
Duplication and distribution of any class of eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

MI&CT eSERVICE NOTE

SN07112612b

Class C information is Property of GE.

This short-term informational note is invalid 6 months after the issue date.

Date: November 26, 2007
Date Revised: August 15, 2008

Subject: OS or Image Disk Drives used on LS-QXI and CTI NexGen Consoles

Octane Disk Drives 2169940-12, 2169940-72, 2169940-78 are now Compatible on LightSpeed QX/I (Octane) and CTI Next Gen (Octane) Consoles, when using the updated Load From Cold Procedures, see latest LFC Document, the Revision History of the LFC procedure lists the updated Sections.

QXI 1.x Load From Cold Procedures 2282382-100 Rev. 02 Newly released (July 2008)
CTI Load From Cold Procedures 2284291-100 Rev. 08 Newly released (July 2008)

*** For the Latest LFC procedure look on CDL:**

<http://apps.gehealthcare.com/servlet/ClientServlet?REQ=RNEW&MODALITY=CT>

There are three different drive FRU part numbers for Octane 1 and Octane 2 Computers, the part numbers are 2169940-12, 2169940-72 and 2169940-78. The drives contain special SGI firmware, this special firmware alters the usable size of the drive. The 2169940-12, 2169940-72, and 2169940-78 drives are now compatible as both the operating system disk or image disk due to changes made in the new LFC procedures listed above. The 2169940-12 drive is no-longer available, therefore Global Parts is unable to maintain stock of the 2169940-12 drive.

2169940-12 (9 GB) DNES-309170 IBM Firmware 013-2652-001
2169940-72 (9 GB) ST39204LC SGI Firmware 013-3172-001 or 013-3172-002
2169940-78 (18 GB) ST318404LC SGI Firmware 013-3173-001

See Notes 1 and 2 for CTI systems only.

Note 1. The 2169940-78 18GB drive, when used as an image drive on CTI consoles provides only 1GB of additional useable image space. **If an image disk drive is needed for a CTI system the preferred replacement is the 2169940-72 drive.** The 2169940-78 (18 GB) drive provides Partial functionality as the image drive on CTI consoles because image space is reduce from a normal 20,000 x 512 images down to 5,000 x 512 images.

Note 2. The 2169940-78 (18 GB) disk can be used as an OS disk on a CTI console. The 2169940-78 (18GB) provides complete functionality as the OS disk in a CTI Octane console.

Effectivity: ALL LightSpeed QX/I Octane Consoles; CT/I Pro Next-Gen (Octane) Consoles.

Table 1: Console Part Numbers Affected

System Alias and Scanner Type	Console P/Ns affected	Affiliated Software affected	Operating System CD P/N affected
CTI/Pro HiSpeed Nex Gen	2169455	CTI 6.1.19 M4	2276660, 2276661, 2276662,
Lightspeed QX/I, H1 H1.2, and H1.3	2180551	10.5.1 2.8.21 H1.3 M4	2240216-2, 2240213-2, 2240215-2
Lightspeed QX/I, H1 H1.2, and H1.3	2180551-2	10.5.1 2.8.21 H1.3 M4	2240216-2, 2240213-2, 2240215-2
Lightspeed QX/I, H1 H1.2, and H1.3	2180551-3	10.5.1 2.8.21 H1.3 M4	2240216-2, 2240213-2, 2240215-2

GE Healthcare MI&CT Class C eService Notes are copyright (c) protected to General Electric Company Inc with all rights reserved. Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare Systems. Disclosure to persons not employed by GE Healthcare or not in possession of a Advanced Service Agreement with GE Healthcare is prohibited.

Duplication and distribution of any class of eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

Details: Octane LightSpeed QXI and CTI Disk Drive part numbers:

2169940-12 (9 GB) DNES-309170 IBM Firmware 013-2652-001
 2169940-72 (9 GB) ST39204LC SGI Firmware 013-3172-001 or 013-3172-002
 2169940-78 (18 GB) ST318404LC SGI Firmware 013-3173-001

Table 2: QXI 1.x Octane Disk Drive FRU list

QXI 1.x Octane Console System - Octane Disk Drive FRU	
QXI Console 2169940-12 (9 GB)	The 2169940-12 is an original 9GB drive used on Octane I which is no-longer available. The 2169940-12 is compatible on both CTI and QXI 1.x systems.
QXI Console 2169940-72 (9 GB)	The 2169940-72 drive with 013-3172-001 or 013-3172-002 Firmware provides complete functionality on Qxi 1.x Octane consoles when used with the new 2282382-100 rev 2 LFC instructions.
QXI Console 2169940-78 (18 GB)	The 2169940-78 drive provides complete functionality on Qxi 1.x Octane Consoles when used with the new 2282382-100 Rev 2 LFC instructions.

Table 3: CTI Octane Disk Drive FRU list

CTI Next Gen Octane Console systems - Octane Disk Drive FRU's	
CTI Console 2169940-12 (9 GB)	The 2169940-12 was one of the original 9GB drive used on Octane I which is no-longer available. The 2169940-12 is compatible on both CTI and QXI 1.x systems.
CTI Console 2169940-72 (9 GB)	The 2169940-72 drive with 013-3172-001 or 013-3172-002 Firmware will function properly on CTI system consoles when using the new 2284291-100 Rev 08 LFC instructions.
CTI Console 2169940-78 (18 GB)	The 2169940-78 18GB hard disk drive used as the image drive on CTI Octane consoles will provide 1GB of useable image space. If an image disk is needed for a CTI the preferred replacement is the 2169940-72. The 2169940-78 (18 GB) drive provides Partial functionality as the image drive on CTI consoles because image space is reduce from a normal 20,000 x 512 images down to 5,000 x 512 images. The 2169940-78 (18 GB) disk can be used as an OS disk on a CTI console. The 2169940-78 provides complete functionality as the OS disk in a CTI console when using the new 2284291-100 Rev 08 LFC Instructions.

Duplication and distribution of any class of eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

Resolution:

New LFC procedures were created, a few minor changes to the LFC procedures allow the use of a 2169940-72 (firmware revision 001 or 002) and 2169940-78 drives. The New LFC procedure enables the use of the 2169940-72 and 2169940-78 drives as either the Operating System disk or Image disk for all LightSpeed QX/I Octane Consoles and CTI Next Gen Octane Consoles, see Effectivity listed above. Use the latest revision of the LFC procedure for the appropriate QXI or CTI Octane system. see latest LFC Documents, the Revision History of the LFC procedure lists the updated Sections.

QXI 1.x Load From Cold Procedures 2282382-100 Rev 02 Newly released (July 2008)
CTI Load From Cold Procedures 2284291-100 Rev 08 Newly released (July 2008)

* For the Latest LFC procedure look on CDL:

<http://apps.gehealthcare.com/servlet/ClientServlet?REQ=RNEW&MODALITY=CT>

Table 4: CTI and QXI Octane Drive Compatibility

Octane Disk Drives	CTI OS Disk Compatible?	CTI Image Disk Compatible?	QXI OS Disk Compatible?	QXI Image Disk	Stocking Levels as of 7-11-2008
2169940-12	Yes	Yes	Yes	Yes	None
2169940-72	Yes	Yes	Yes	Yes	42
2169940-78 (18gb)	Yes	Partial *	Yes	Yes	43

- * The 2169940-78 (18 GB) drive provides Partial functionality as the image disk on CTI consoles because image space is reduce from a normal 20,000 by 512 images down to 5,000 by 512 images. The 2169940-78 18GB drive used as the image disk drive on CTI Octane consoles only provides 1GB of useable image space. If a replacement image disk is needed for a CTI system the preferred replacement is the 2169940-72.
- * The 2169940-78 provides complete functionality as the OS disk in a CTI console when using the new 2284291-100 rev 08 LFC Instructions.

Affected Service Publication:

LightSpeed QXI (1.3) Software Load Procedure
CT/I LFC Procedures for Versions 4.4,4.5,6.1,6.2, and 6.3

2282382-100, Revision 01 Obsolete
2284291-100, Revision 07 Obsolete

PQR/SPR #: 13120277, 13120279, 13121764, 13131803, 13144968

Mike Rose, Mike Bauer, Dave Palermo
Console Subsystem & Installed Base Engineering