

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

welcome!
ct tech pubs web page
ct water cooler
ct tech pubs updates
surveys
9800/hla
highspeed family (us)
[ct/i](#)
lightspeed family
yms family
all ct products
index
old ct emails
communiques pending
approval
customize
members

search:

advanced search
news: daily | weekly

go offline | chat | notify |
print | tutorial | help

home> [ct/i](#)

OBC Chassis FRUs For All CT/i Gantry Flavors

[christopher hardiman](#) ([christopher c hardiman](#)), 07/02/2002 - 02:56 pm

PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
Disclosure to third parties prohibited.

Communique Number

MQUE-5BNQHG

Equipment

CT/i

Problem

Field service has requested that the OBC chassis be made a FRU due to broken off screws.

Corrective Action

An OBC chassis, 2111162, does exist as a FRU for gantry models 2118213, 2118213-2, and 2113719. Another OBC chassis, 2111162-2, exists as a FRU for gantry models 2119732, 2119734, 2119732-2, 2119732-3, 2119741-4, 2119734-2, 2119742-3, 2183250, 2183250-2, 2183255, and 2183255-2. Please order the appropriate chassis for your gantry.

Author

Christopher C Hardiman

Revision

07/02/2002 02:56 PM

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)