

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

welcome!
ct tech pubs web page
ct water cooler
ct tech pubs updates
surveys
9800/hla
highspeed family (us)
ct/i
lightspeed family
yms family
all ct products
index
old ct emails
communiques pending
approval
communique change
requests
customize
members

search:

advanced search
news: daily | weekly

go offline | chat | notify |
print | tutorial | help

home> lightspeed family

Console De-staged!

christopher hardiman (christopher c hardiman), 08/27/2002 - 01:56 pm

**Priority**

1 - Big Issue, Be Sure to Read

PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
Disclosure to third parties prohibited.

Communique Number

MQUE-5DAF4P

Equipment

LightSpeed Plus, Ultra & 16

Hints/Tips

Per Tony Moore, MPE - CT Manufacturing: "As of Jul 15, 2002, CT Manufacturing stopped staging consoles with the gantry being shipped to any given customer. The consoles are now tested on the Console Assembly/Test Line. Therefore, when a console arrives with a system shipment, the console WILL NOT have the system cals loaded; you must load your System State MOD!! Also, when a console arrives with a 4 slice gantry, Reconfig must be performed; if it isn't performed you will get "Wrong DAS configuration" errors." This is different from the INTERMITTENT DAS configuration error that is fixed by cycling the DAS power or cycling the 120VAC switch on the back of the PDU.

Author

Christopher C Hardiman

Revision

08/27/2002 01:56 PM

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)