




NOTES:

- 1) Used for remote diagnostics - Option
- 2) Refer to the appropriate Pre-installation / Installation documents for the Laser Camera
- 3) Category 5 cable. Use one of the following patch cords:

Length	CAT Num	GE Part Num
	K9000WB	2215028-10 20 m
	K9000KP	2215028-5 10 m
	K9000JR	2215028-4 5 m

Only one phone connection is required for the system.

