

Effectivity

The following CT Equipment is affected:

2260619 LightSpeed Plus Gantry Assembly

Purpose

The purpose of this FMI is to install a new two-part hoist boom arm, when replacing the Detector, Tube or Tank, on the CT gantry.

Furnished Materials

FMI Kit Part Number 2299388 includes the items listed below.

Qty	Description	Part #
1	FMI Document	2299190-100
1	Hoist boom arm	2282509
1	Hoist boom	2282510

Disposal

U.S. ONLY

- 1.) Return all obsolete parts to:

GEMS Recycling Center
c/o ACE Warehouse, Bldg. 11
2200 College Avenue
Cudahy, WI 53110

- 2.) Destroy and/or dispose of all obsolete software and documentation according to GE policy.

INTERNATIONAL SITES (OUTSIDE THE U.S.)

Destroy and/or dispose of all obsolete hardware, software and documentation according to GE policy.

People Power

Allow 0.25 hours of labor for the completion of this FMI.

Procedure

With gantry covers removed, the hoist boom may be installed, to assist with Detector, Tube or Tank replacement. To assemble the new two-piece boom:

- 1.) Find the hoist boom mounting location.




Figure 1 Hoist boom mounting location

- 2.) Insert the hoist boom (Figure 2) into the mounting hole.



Figure 2 Hoist Boom

- 3.) Slide the hoist boom arm (Figure 3) onto the hoist boom. The boom is ready for use.




Figure 3 Hoist Boom Arm

- 4.) Remove the two-piece boom before attempting to reassemble the gantry.

End of Document