

FCT SERVICE NOTE

SN05081620a

Class A Service information enclosed.

Date: August 16th 2005

Subject: IGs need console re-boot to come up properly

Effectivity: VCT M3a and forward until further notice

Details: **NOTE:** IGs may not start up reliably when restarting applications without a system reboot.

Symptom: An FE had removed and then installed a new option. He used the Applications shutdown in the Service Desktop to restart the system. On the start up the system took quite sometime to start up. After a long wait the FE finally got a pop up that stated recon time will be slower. Call Service

Current HQ Activity: The Console Team is trying to understand why an Applications shutdown & restart is not restarting the IG's.

Current Work Around: Re-Boot the Console to insure IG's are fully operational. Do NOT rely on the Applications Shutdown and re-start.

Resolution:

James Lehouillier
Service Methods Design Engineer