

FCT SERVICE NOTE

SN06013010a

Class A Service information enclosed.

Date: January 30, 2006

Subject: Cover may slip when secured to Cover Dollies

Effectivity: All CT Systems using current Front and Rear Cover Dollie design

Details: The Cover Dollies use a wingnut design that must be adequately tightened to ensure the cover is positively attached the cover dollie before moving the cover. Due to constant reuse the wingnuts, covers and shoulder bolt, (Standoff) may all wear which can make it very difficult to ensure the cover is secured adequately to the dollies before the cover weight is transferred to the dollies. In addition, during normal servicing any failure to ensure that the wingnuts are as tight as possible, may also cause the cover to slip when it is rolled away.

Resolution: Long Term: A re-design of the Wingnut and shoulder bolt to a more positive locking handle is underway and will become available to order by June of 2006. In the short term, make sure the wingnuts are adequately tightened before cover removal. If necessary use a tool and/or add washers between the wingnut and shoulder bolt, (Standoff) and cover before transferring the weight of the covers to the dollies.

The process of removal and moving of the cover on the dollies is a two man job. Have both FE's or support personnel inspect/double check the wingnut tightened in place prior to moving the cover on the cover Dollies. DO NOT move the cover on the dollie without ensuring the wingnut is positively holding the cover to the dollie.

Excerpt of Service procedure:

1. Assemble the rear cover dolly.
2. Tighten the two (2) shoulder bolts to the rear cover.
3. Fit side dolly through the shoulder bolts and secure assembly with two (2) wing nuts.
4. Repeat steps a and b for the other side dolly.

Douglas Hofstetter
FCT Service Engineering