Soft Start with PIC16F15313

By YU3MA August 2020

https://forum.yu3ma.net

https://github.com/mikikg/picss


open hardware
forum.yu3ma.net
github.com/mikitg/picss
AC-OUT
Input: 230VAC 50Hz
Max output: 2000VA
PIC16F15313
Soft-Start v1.0
By YU3MA
2020
Text
Max
Power
DANGER!
HIGH VOLTAGE!
Start / Stop
- Time +
- Power +
MCLR
-5V
0V


OUT
IN
IN
OUT
PIC Soft-start by YU3MA 2020
R16
R5
R17



Sheet:		
File: pic-scr.kicad_pcb		
Title:		
Size: A4	Date:	**Rev:**
KiCad E.D.A. kicad (5.0.0-3-g5ebb6b6)		Id: 1/1



Sheet:		
File: pic-scr.kicad_pcb		
Title:		
Size: A4	Date:	**Rev:**
KiCad E.D.A. kicad (5.0.0-3-g5ebb6b6)		Id: 1/1



Sheet:		
File: pic-scr.kicad_pcb		
Title:		
Size: A4	Date:	**Rev:**
KiCad E.D.A. kicad (5.0.0-3-g5ebb6b6)		Id: 1/1



Sheet:		
File: pic-scr.kicad_pcb		
Title:		
Size: A4	Date:	**Rev:**
KiCad E.D.A. kicad (5.0.0-3-g5ebb6b6)		Id: 1/1



Sheet:		
File: pic-scr.kicad_pcb		
Title:		
Size: A4	Date:	**Rev:**
KiCad E.D.A. kicad (5.0.0-3-g5ebb6b6)		Id: 1/2

Soft-start with PIC16F15313 by YU3MA



Soft-start with PIC16F15313
YU3MA 2020
forum.yu3ma.net

Sheet: /	
File: pic-scr.sch	
Title: Soft-start with PIC16F15313	
Size: A4	Date: 1st August 2020.
KiCad E.D.A. kicad (5.0.0-3-g5ebb6b6)	Rev: 1
	Id: 1/1