
Required Components



BOM

- 1. 1X 3D Printed Yankauer-Holder-Top Case
- 2. 1X 3D Printed Yankauer-Holder-Base Case
- 3. 1X 30x10x3-4MM Neodymium Rectangle Magnet
- 4. 1X 3D Printed Yankauer-Holder-Top Case
- 5. 1X 3D Printed Yankauer-Holder-Clip Case
- 6. 1X 30x10x3-4MM Neodymium Rectangle Magnet

V1.0 | April 2023

Yankauer-Holder ASSEMBLY GUIDE V1.0


Required Tools

• Side cutters


Assembly Instructions

Step 1

Prepare parts to assemble Base component. These parts include a Neodymium magnet, a Yankauer-Holder-Top case, and a Yankauer-Holder-Base case.




Step 2
Place the Neodymium magnet firmly onto the Base component section. Ensure the posts of the base go through the two holes of the magnet.



Step 3

Clip the posts of Yankauer-Holder-Top case onto the Yankauer-Holder-Base case, as shown in the image below.




Step 4

Prepare parts to assemble clip component. These parts include a Neodymium magnet, a Yankauer-Holder-Top case, and a Yankauer-Holder-cClip case.



Step 5

Place the Neodymium magnet firmly onto the Clip component magnet section. Ensure the posts of the Clip go through the two holes of the magnet.




Step 6

Clip the posts of Yankauer-Holder-Top case onto the Yankauer-Holder-Clip case, as shown in the image below.



Step 7
The Yankauer-Holder base and clip assembly process is now complete.



Step 8
The Yankauer-Holder is being used to prevent suction tip to fall on the ground.

