BDI - PART REQUEST

Tech name: Brendon Dixon

Type: Normal Priority: Order

Vin #: 1FUJGLDR79LAH6294

Engine #:

Comments:

PARTS:

SEG DESCRIPTION QTY

2 A0009958102 - turbo outlet clamp (v band clamp)

1