## **BDI - EMPLOYEE WRITE UP FORM**

Employee: Peter Vigna	Date: 2019-07-15
	Supervisor: Richard Zimmer
Department:	Supervisor. Richard Zimmer
Employee Seniority Date: 1970-01-01	Trade level: BRANDELL DIESEL INC
Disciplinary action: Y	
TYPE OF VIOLATION:	WARNING:
Carelessness	Last warning: 1970-01-01
Work Quality Comeback	Previous warning: 1970-01-01 Warnings: 1
Comoduck	Wallings. 1
EMPLOYER STATEMENT:	
this job. On RO 9538, you had reinstalled the fan hub, as well as reinstalled the radiator. The Charge Air mounting bolts that were used were too long, and went right into the rad. They were just long enough to vibrate and the customer got 25 engine hrs on it before it failed in FT McMurray. When the tech got up there and removed the rad for replacement, he also found one of the fan mounting nuts completely loose, almost falling off. This would have went through the rad and caused even more damage. This is going to cost us a new rad, as well as Earth's mechanic time and fly up to repair. More importantly though, this could potentially lose us our biggest customer. This was careless and poor work quality. Because of the location of these items, this wasn't anything that could have been found on a QC unless it was checked over with a mirror. But these are 2 items that shouldn't even need to be checked. There needs to be a standard that we work within and can trust our technicians.  Due to the seriousness of this failure, the amount of damage that resulted, and the poor workmanship, BDI is reducing your wage by \$3.00 / Hr. Next instance of low work quality will be termination.	
I HAVE READ THIS "WARNING LETTER" AND I UNDERSTAND IF I HAVE RECIEVED A COPY OF THE SAME	
Employee Sign	nature Management Signature
	Witness Signature Brandell Diesel Inc. Page 1/1