BDI - PART REQUEST

Tech name: Owen McGowan Type: 911 Priority: Order Vin #: 51Z4D5615D4060077 Engine #: 570HM2U3334533

Comments:

- 1) CAC top & bottom rubber pipes
- 2) Intake manifold High pressure rubber air pipe
- 3)Low pressure turbo, compressor outlet rubber joint(connects LP turbo to HP turbo via rubber joint and Alloy pipe)
- 4) ISC Rubber seal for air inlet
- 5)Turbo oil feed pipe
- 6)HP & LP turbo compressor outlet rubber pipes

7)HP turb	o Exhaust elbow Round gasket (Contains no hole	s for studs)
PARTS:		
<u>SEG</u>	DESCRIPTION	QTY
HP to2rbo	Exhaust elbow Round gasket (Contains no holes	for studs)
1	HP & LP turbo compressor outlet rubber pipes	2
1	Turbo oil feed pipe	1
2	ISC Rubber seal for air inlet	1
urbo, compr é sso	or outlet rubber joint(connects LP turbo to HP turbo	o via rubber joint and Alloy p
2	Intake manifold High pressure rubber air pipe	1
1	CAC top & bottom rubber pipes	1