## **BDI - PART REQUEST**

Tech name: Brendon Dixon

Type: 911 Priority: Order

Vin #: 5KJRALDRXDPBY3277

Engine #: 472904S0132904

Comments:

SENT DAVID PICS - IS FOR THE ONLY BANJO BOLT ON THE FUEL

RAIL - LOCATED AT THE BACK SIDE OF FUEL RAIL

PARTS:

<u>SEG</u>	<u>DESCRIPTION</u>	<u>QTY</u>
11	SEAL RING WASHER	2