

Property Dossier

Damrak 1, 1012 LG Amsterdam

Built: 1920 | Residential | 85 m²

Prepared: 2 March 2026

Risk Overview

Noise	62/100
Air Quality	81/100
Climate Stress	50/100
Sunlight	72/100

2 attention flags

- Moderate foundation risk
- Asbestos risk

Risk Analysis

Noise

62/100

Moderate

Moderate road traffic noise. Verify peak evening traffic.
Source: RIVM - Atlas Leefomgeving (2024)

Air Quality

81/100

Good

Air quality is good. PM2.5 and NO2 are within limits.
Source: RIVM - GCN (2024)

Climate Stress

50/100

Moderate

Moderate heat stress. Some flood risk in heavy rain.
Source: Klimaateffectatlas (2023)

Sunlight

72/100

Good

Good sunlight access from south-facing facade.
Source: 3DBAG + SunCalc (2024)

Neighborhood Profile

Burgwallen-Oude Zijde, Amsterdam

Population density	15234 per km2
Avg. household size	1.6
Single-person households	68.2%
Owner-occupied	22.1%
Avg. property value	€385,000
Distance to train station	0.8 km
Distance to supermarket	0.3 km

Source: CBS (Statistics Netherlands)

Livability

50/100

Physical	63/100
Safety	25/100
Social	50/100
Amenities	75/100
Housing	38/100

Source: Leefbaarometer (2024)

Crime

28/100

Crime rate is above the national average.

Total per 1,000 residents	142.3
National average	52.1
Burglary per 1,000 residents	8.7
Violent crime per 1,000 residents	12.4

Source: CBS (2024)

Viewing Checklist

Bring these questions to the property viewing.

Noise

- ☐ Open a window facing the street. How loud is traffic?
- ☐ Visit at multiple times to check noise variation.

Foundation

- ☐ Check walls for cracks near windows and doors.
- ☐ Ask for the most recent foundation inspection report.

Property Warnings

Foundation Risk

Risk: **Medium**

- Built on clay soil with wooden piles common to this era.
- Schedule a foundation inspection before purchase.

Ground Lease (Erfpacht)

Ground lease detected (municipality based)

- Amsterdam often applies ground lease.
- Check canon level and buyout options.

Owners Association (VvE)

Number of units: 12

- Request owners association minutes and maintenance plan.
- Review reserve fund adequacy.

Asbestos

Asbestos risk flagged

- Building predates 1994. Asbestos inspection advised.

Lead Pipes

Lead pipe risk flagged

- Building predates 1960. Lead pipes may still be present.

Methodology

Scoring Methodology

All risk indicators are normalized to a 0–100 scale, where higher scores are better. Severity is determined as follows:

Score	Severity	Meaning
70–100	Good	Minimal risk
40–69	Moderate	Further investigation recommended
20–39	Poor	Significant risk — get this checked
0–19	Critical	Serious risk — professional advice required

Data Sources

Indicator	Source
Noise	RIVM — Atlas Leefomgeving (ALO)
Air quality	RIVM — Grootschalige Concentratiekaarten (GCN)
Climate stress	Klimaat-effectatlas (KNMI/Deltares)
Sunlight	3DBAG + SunCalc (own computation)
Neighborhood stats	CBS (Statistics Netherlands)
Livability	Leefbaarometer (Min. BZK)
Crime	CBS Police statistics
Building facts	BAG (Basisregistratie Adressen en Gebouwen)
Energy label	EP-Online (RVO)

Limitations

- This report is based on publicly available data and is intended as indicative guidance only.
- Noise and air quality data are macro-level modeling and may not reflect exact conditions at the address.
- Climate risk coverage varies by region; some layers are not available nationally.
- Sunlight calculations are based on 3D building models and may differ from reality due to vegetation and future construction.
- Verify all information on-site and consult professionals for purchase decisions.

Report ID rpt-epic4-0001
VBO ID 0363010012345678
Methodology v2.1 (2026-02-28)