

Less Than 30 Days of Installation with Troubles

April 24, 2013

Affected Site GT-MANDALUYONG HOST/SWITCH

Service/Circuit ID IC-AIZ-6297

Activation Date 03/14/2013

Circuit Maturity 29 Days old from first outage

Project Engr ATB

Status **NEW ACTIVATION**

Ticket Id	Rcvd Date/Time	Trouble Reported	Close Date/Time	Duration(in minutes)	Pending Time(in minutes)	Reason For Outage	Last Action Taken	Aging(in days)
1068939	04/12/2013 09:28:34	[EGIP]_NBS Head Office IC-AAA-8240	04/23/2013 14:29:10	16141	1721	Routing- instance hang- up.	Emailed client for verification of circuit status. RFO: Routing-instance hang-up.	29

Affected Site GT-IC PLAZA NODE

Service/Circuit ID IC-AIZ-5976

Activation Date 03/23/2013

Circuit Maturity 16 Days old from first outage

Project Engr ERH

Status **NEW ACTIVATION**

Ticket Id	Rcvd Date/Time	Trouble Reported	Close Date/Time	Duration(in minutes)	Pending Time(in minutes)	Reason For Outage	Last Action Taken	Aging(in days)
1067969	04/08/2013 12:30:33	Ckt#IC-AIZ-5976 Ayala- Cebu(Intermittent)	04/23/2013 16:39:30	21849	1467	Circuit is erroneous	The circuit is confirmed stable by Nestor/HQ. and agreed to close the ticket. RFO: Circuit is erroneous Action Taken: Circuit become stable before the joint testing.	16