

## Less Than 30 Days of Installation with Troubles

**April 26, 2013** 

Affected Site GT-PARC ROYALE

Service/Circuit ID IC-AIZ-7511

Activation Date 04/04/2013

Circuit Maturity 1 Days old from first outage

Project Engr DPR

Status **NEW ACTIVATION** 

Ticket Id	Rcvd Date/Time	Trouble Reported	Close Date/Time	Duration(in minutes)	Pending Time(in minutes)	Reason For Outage	Last Action Taken	Aging(in days)
1067376	04/04/2013 23:14:04	Attn: Raymart - Reroute IC-AIZ-7511	04/25/2013 06:50:55	29257	0	Costumer requesting for reroute to near IP 203.28.52.210		1

Affected Site GT-MANDALUYONG HOST/SWITCH

Service/Circuit ID IC-AIZ-5949

Activation Date 03/25/2013

Circuit Maturity 29 Days old from first outage

Project Engr JRB

Status **NEW ACTIVATION** 

Ticket Id	Rcvd Date/Time	Trouble Reported	Close Date/Time	Duration(in minutes)	Pending Time(in minutes)	Reason For Outage	Last Action Taken	Aging(in days)
1072165	04/23/2013 13:00:32	Glory City - IC-AIZ- 5949 - No Connection	04/25/2013 11:22:08	2782	0	No problem in GT side.	Able to ping up to LAN ip. RFO: No problem in GT side.	29

Affected Site GT-LOS BANOS

Service/Circuit ID IC-AIZ-7046

Activation Date 03/14/2013

Circuit Maturity 13 Days old from first outage

Project Engr JRB

Status **NEW ACTIVATION** 

Ticket Id	Rcvd Date/Time	Trouble Reported	Close Date/Time	Duration(in minutes)	Pending Time(in minutes)	Reason For Outage	Last Action Taken	Aging(in days)
1069200	04/12/2013 21:00:29	Link Down	04/25/2013 14:15:51	18315	454	Monitored with NTU Power off alarm. Possible modem was turned off	RFO: Monitored with NTU Power off alarm.	29