

# Back Panel — Laser Marking Check

User Guide

/backpanel/laser

## Step 1 — Enter Work Order & Lookup

Scan or type the Work Order, then click **Lookup** (or press Enter).

**Save** — remember this Work Order for next time.

**Reset** — clear everything to start a new Work Order.

## Step 2 — Scan Serial Number

Scan the panel's serial number. The system checks it automatically.

## Step 3 — Watch the result circle

**PASS** (green) — done, continue to the next serial.

**FAIL** (red) — check the error message shown, then retry.

Look at the process list on the right — if it fails at **step 2.2** or **step 3**, click **Try Again** to retry.

## Step 4 — Work Order complete

Watch the progress count (done/total) next to the **Save** / **Reset** buttons. When it reaches the total quantity, this Work Order is complete — switch to a new Work Order and continue from **Step 1**.