

TECHNICAL BULLETIN



MODEL/DERIVATIVE:

All Models

Bull. N°: **0001**

CDS. ref: **R6529bu**

Issue: **1**

Date: **23.03.94**

AFFECTED RANGE:

All vehicles with Radio Data System (RDS) Radio.

PROBLEM:

RADIO - POOR RECEPTION - RDS INOPERATIVE

Radios are being returned under warranty with the above alleged faults which, when tested, cannot be substantiated.

CAUSE:

Radio preset buttons have never been used to select locally available stations.

ACTION:

In order for the RDS to work, the radio must be tuned to locally available stations which must then be istored' using the preset buttons in accordance with the ICE handbook.

NOTE:- This is currently a customer assurance and vehicle validation reauirement.

In future, radios returned under the warranty exchange scheme, which show only the manufacturers original test station frequencies on the preset buttons, will be subjected to a handling charge.

PARTS INFORMATION:

Not applicable.

WARRANTY CLAIMS:

Not applicable.