

TECHNICAL BRIEF



MODEL/DERIVATIVE:

All Models

Ref: **RT0003bu**

Issue: **1**

Date: **17/03/97**

AFFECTED RANGE:

All Disc (English only)

PROBLEM:

IN SUFFICIENT DETAIL BEING RELATED TO TESTBOOK HELP DESK

CAUSE:

The need for this information not fully communicated and appreciated, resulting in delay in handling the problem.

ACTION:

The following information is the basic minimum that the Technician needs to communicate to the Help Desk either by fax or phone:

- 1. Dealer Name.**
- 2. Corporate I.D. No.**
- 3. Contact Name with phone and fax number.**
- 4. TestBook Serial/Model No (located on rear of TestBook screen).**
- 5. Screen ref/Node ID when the fault occurred (alpha-numeric data displayed top left hand corner of the screen).**
- 6. Compact Disc reference (printed on the disc or displayed on welcome screen under the "i" button).**
- 7. RDS release number (displayed on top right of screen).**
- 8. Vehicle details: including model, model year, engine, transmission, derivative.**
- 9. Details of test being used.**
- 10. Error message displayed on the screen.**
- 11. Cabling Diagram being used. This information should be given either verbally or by using the TestBook Help Desk report form.**

PLEASE DISPOSE OF THIS COPY AFTER USE - DO NOT FILE

PARTS INFORMATION:

Not applicable

WARRANTY CLAIMS:

This Brief is intended only as a suggestion to resolve a problem, therefore an SRO and time is not provided. Claims should be submitted in the normal way by using published SRO's and reducing time claimed where applicable. If non schedule operations are required the claim should be completed, noting the requirements of the Policy & Procedure Manual page 'Two -5'.