Chapter 8


Notes to the Instructor.

1. For Problems 8-33 through 8-44 and 8-51 through 8-58. There is a statement preceding Prob. 8-33 which covers a change which will be corrected in the second printing of the 10th edition.


2. For Probs. 8-41 to 8-44. These problems, as well as many others in this chapter are best implemented using a spreadsheet.

impremented doing wapromonion

8-1 (a) Thread depth= 2.5 mm Ans. Width = 2.5 mm Ans. $d_m = 25 - 1.25 - 1.25 = 22.5$ mm $d_r = 25 - 5 = 20$ mm l = p = 5 mm Ans.



(b) Thread depth = 2.5 mm Ans. Width at pitch line = 2.5 mm Ans. $d_m = 22.5$ mm $d_r = 20$ mm l = p = 5 mm Ans.



8-2 From Table 8-1,

$$d_r = d - 1.226869p$$

$$d_m = d - 0.649519p$$

$$\bar{d} = \frac{d - 1.226869p + d - 0.649519p}{2} = d - 0.938194p$$

$$A_{t} = \frac{\pi \overline{d}^{2}}{4} = \frac{\pi}{4} (d - 0.938194p)^{2}$$
 Ans.


8-3 From Eq. (*c*) of Sec. 8-2,

$$P_R = F \frac{\tan \lambda + f}{1 - f \tan \lambda}$$

Shigley's MED, 10th edition

$$\begin{split} T_R &= \frac{P_R d_m}{2} = \frac{F d_m}{2} \frac{\tan \lambda + f}{1 - f \tan \lambda} \\ e &= \frac{T_0}{T_R} = \frac{F l / (2\pi)}{F d_m / 2} \frac{1 - f \tan \lambda}{\tan \lambda + f} = \tan \lambda \frac{1 - f \tan \lambda}{\tan \lambda + f} \quad Ans. \end{split}$$

Using f = 0.08, form a table and plot the efficiency curve.



8-4 Given F = 5 kN, l = 5 mm, and $d_m = d - p/2 = 25 - 5/2 = 22.5$ mm, the torque required to raise the load is found using Eqs. (8-1) and (8-6)

$$T_R = \frac{5(22.5)}{2} \left[\frac{5 + \pi(0.09)22.5}{\pi(22.5) - 0.09(5)} \right] + \frac{5(0.06)45}{2} = 15.85 \text{ N} \cdot \text{m}$$
 Ans.

The torque required to lower the load, from Eqs. (8-2) and (8-6) is

$$T_L = \frac{5(22.5)}{2} \left[\frac{\pi(0.09)22.5 - 5}{\pi(22.5) + 0.09(5)} \right] + \frac{5(0.06)45}{2} = 7.83 \text{ N} \cdot \text{m}$$
 Ans.

Since T_L is positive, the thread is self-locking. From Eq.(8-4) the efficiency is

$$e = \frac{5(5)}{2\pi(15.85)} = 0.251$$
 Ans.

8-5 Collar (thrust) bearings, at the bottom of the screws, must bear on the collars. The bottom segment of the screws must be in compression. Whereas, tension specimens and their grips must be in tension. Both screws must be of the same-hand threads.

8-6 Screws rotate at an angular rate of

$$n = \frac{1720}{60} = 28.67 \text{ rev/min}$$

(a) The lead is 0.25 in, so the linear speed of the press head is V = 28.67(0.25) = 7.17 in/min Ans.

(b) F = 2500 lbf/screw

$$d_m = 2 - 0.25 / 2 = 1.875 \text{ in}$$

sec $\alpha = 1 / \cos(29^\circ / 2) = 1.033$

Eq. (8-5):

$$T_R = \frac{2500(1.875)}{2} \left(\frac{0.25 + \pi(0.05)(1.875)(1.033)}{\pi(1.875) - 0.05(0.25)(1.033)} \right) = 221.0 \text{ lbf} \cdot \text{in}$$

Eq. (8-6):

$$T_c = 2500(0.08)(3.5 / 2) = 350 \text{ lbf} \cdot \text{in}$$
 $T_{total} = 350 + 221.0 = 571 \text{ lbf} \cdot \text{in/screw}$
 $T_{motor} = \frac{571(2)}{60(0.95)} = 20.04 \text{ lbf} \cdot \text{in}$
 $H = \frac{Tn}{63\ 025} = \frac{20.04(1720)}{63\ 025} = 0.547 \text{ hp}$ Ans.

8-7
$$L = 3.5 \text{ in, } T = 3.5 \text{ F, } M = (L - 3/8) F = (3.5 - 0.375) F = 3.125 F, S_y = 41 \text{ kpsi.}$$

$$\sigma = S_y = \frac{32M}{\pi d^3} = \frac{32(3.125)F}{\pi (0.1875)^3} = 41\ 000$$

$$F = 8.49 \text{ lbf}$$

$$T = 3.5(8.49) = 29.7 \text{ lbf} \cdot \text{in}$$
 Ans.

(b) Eq. (8-5),
$$2\alpha = 60^{\circ}$$
, $l = 1/10 = 0.1$ in, $f = 0.15$, $\sec \alpha = 1.155$, $p = 0.1$ in
$$d_m = \frac{3}{4} - 0.649 \, 519 \big(0.1 \big) = 0.6850 \text{ in}$$

$$T_R = \frac{F_{\text{clamp}}(0.6850)}{2} \bigg(\frac{0.1 + \pi(0.15)(0.6850)(1.155)}{\pi(0.6850) - 0.15(0.1)(1.155)} \bigg)$$

$$T_R = 0.075 \, 86 F_{\text{clamp}}$$

$$F_{\text{clamp}} = \frac{T_R}{0.075 \, 86} = \frac{29.7}{0.075 \, 86} = 392 \, \text{lbf} \quad \textit{Ans}.$$

(c) The column has one end fixed and the other end pivoted. Base the decision on the mean diameter column. Input: C = 1.2, D = 0.685 in, $A = \pi (0.685^2)/4 = 0.369$ in², $S_y = 41$ kpsi, $E = 30(10^6)$ psi, L = 6 in, k = D/4 = 0.171 25 in, L/k = 35.04. From Eq. (4-45),

$$\left(\frac{l}{k}\right)_{1} = \left(\frac{2\pi^{2}CE}{S_{y}}\right)^{1/2} = \left[\frac{2\pi^{2}(1.2)30(10^{6})}{41\,000}\right]^{1/2} = 131.7$$

From Eq. (4-46), the limiting clamping force for buckling is

$$F_{\text{clamp}} = P_{\text{cr}} = A \left[S_y - \left(\frac{S_y}{2\pi} \frac{l}{k} \right)^2 \frac{1}{CE} \right]$$

$$= 0.369 \left\{ 41 \left(10^3 \right) - \left[\frac{41 \left(10^3 \right)}{2\pi} 35.04 \right]^2 \frac{1}{1.2 \left(30 \right) 10^6} \right\} = 14.6 \left(10^3 \right) \text{ lbf} \qquad Ans$$

(d) This is a subject for class discussion.

8-8
$$T = 8(3.5) = 28 \text{ lbf} \cdot \text{in}$$

$$d_m = \frac{3}{4} - \frac{1}{12} = 0.6667$$
 in

$$l = \frac{1}{6} = 0.1667 \text{ in}, \quad \alpha = \frac{29^0}{2} = 14.5^0, \text{ sec } 14.5^0 = 1.033$$

From Eqs. (8-5) and (8-6)

$$T_{\text{total}} = \frac{0.6667F}{2} \left[\frac{0.1667 + \pi (0.15)(0.6667)(1.033)}{\pi (0.6667) - 0.15(0.1667)(1.033)} \right] + \frac{0.15(1)F}{2} = 0.1542F$$

$$F = \frac{28}{0.1542} = 182 \text{ lbf}$$
 Ans.

8-9 $d_m = 1.5 - 0.25/2 = 1.375$ in, l = 2(0.25) = 0.5 in

From Eq. (8-1) and Eq. (8-6),

$$T_R = \frac{2.2(10^3)(1.375)}{2} \left[\frac{0.5 + \pi(0.10)(1.375)}{\pi(1.375) - 0.10(0.5)} \right] + \frac{2.2(10^3)(0.15)(2.25)}{2}$$

= 330 + 371 = 701 lbf · in

Since n = V/l = 2/0.5 = 4 rev/s = 240 rev/min

so the power is

$$H = \frac{Tn}{63\ 025} = \frac{701(240)}{63\ 025} = 2.67 \text{ hp}$$
 Ans.

8-10 $d_m = 40 - 4 = 36 \text{ mm}, l = p = 8 \text{ mm}$

From Eqs. (8-1) and (8-6)

$$T = \frac{36F}{2} \left[\frac{8 + \pi(0.14)(36)}{\pi(36) - 0.14(8)} \right] + \frac{0.09(100)F}{2}$$

$$= (3.831 + 4.5)F = 8.33F \quad \text{N} \cdot \text{m} \quad (F \text{ in kN})$$

$$\omega = 2\pi n = 2\pi(1) = 2\pi \text{ rad/s}$$

$$H = T\omega$$

$$T = \frac{H}{\omega} = \frac{3000}{2\pi} = 477 \text{ N} \cdot \text{m}$$

$$F = \frac{477}{8.33} = 57.3 \text{ kN} \quad Ans.$$

$$e = \frac{Fl}{2\pi T} = \frac{57.3(8)}{2\pi(477)} = 0.153 \quad Ans.$$

8-11 (a) Table A-31, nut height H = 12.8 mm. $L \ge l + H = 2(15) + 12.8 = 42.8$ mm. Rounding up,

L = 45 mm Ans.

(b) From Eq. (8-14), $L_T = 2d + 6 = 2(14) + 6 = 34$ mm From Table 8-7, $l_d = L - L_T = 45 - 34 = 11$ mm, $l_t = l - l_d = 2(15) - 11 = 19$ mm,

 $A_d = \pi (14^2) / 4 = 153.9 \text{ mm}^2$. From Table 8-1, $A_t = 115 \text{ mm}^2$. From Eq. (8-17)


$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{153.9(115)207}{153.9(19) + 115(11)} = 874.6 \text{ MN/m}$$
 Ans.

(c) From Eq. (8-22), with l = 2(15) = 30 mm

$$k_{m} = \frac{0.5774\pi Ed}{2\ln\left(5\frac{0.5774l + 0.5d}{0.5774l + 2.5d}\right)} = \frac{0.5774\pi(207)14}{2\ln\left[5\frac{0.5774(30) + 0.5(14)}{0.5774(30) + 2.5(14)}\right]} = 3\ 116.5\ \text{MN/m} \quad Ans.$$

- **8-12** (a) Table A-31, nut height H = 12.8 mm. Table A-33, washer thickness t = 3.5 mm. Thus, the grip is l = 2(15) + 3.5 = 33.5 mm. $L \ge l + H = 33.5 + 12.8 = 46.3$ mm. Rounding up L = 50 mm Ans.
 - (**b**) From Eq. (8-14), $L_T = 2d + 6 = 2(14) + 6 = 34$ mm From Table 8-7, $l_d = L - L_T = 50 - 34 = 16$ mm, $l_t = l - l_d = 33.5 - 16 = 17.5$ mm, $A_d = \pi(14^2)/4 = 153.9$ mm². From Table 8-1, $A_t = 115$ mm². From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{153.9(115)207}{153.9(17.5) + 115(16)} = 808.2 \text{ MN/m}$$
 Ans



From Eq. (8-22)

$$k_{m} = \frac{0.5774\pi Ed}{2\ln\left(5\frac{0.5774l + 0.5d}{0.5774l + 2.5d}\right)} = \frac{0.5774\pi(207)14}{2\ln\left[5\frac{0.5774(33.5) + 0.5(14)}{0.5774(33.5) + 2.5(14)}\right]} = 2 969 \text{ MN/m} \quad Ans.$$

- **8-13** (a) Table 8-7, l = h + d/2 = 15 + 14/2 = 22 mm. $L \ge h + 1.5d = 36$ mm. Rounding up L = 40 mm Ans.
 - **(b)** From Eq. (8-14), $L_T = 2d + 6 = 2(14) + 6 = 34$ mm

From Table 8-7, $l_d = L - L_T = 40 - 34 = 6$ mm, $l_t = l - l_d = 22 - 6 = 16$ mm

 $A_d = \pi (14^2) / 4 = 153.9 \text{ mm}^2$. From Table 8-1, $A_t = 115 \text{ mm}^2$. From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{153.9(115)207}{153.9(16) + 115(6)} = 1162.2 \text{ MN/m}$$
 Ans.

(c) From Eq. (8-22), with l = 22 mm


$$k_{m} = \frac{0.5774\pi Ed}{2\ln\left(5\frac{0.5774l + 0.5d}{0.5774l + 2.5d}\right)} = \frac{0.5774\pi(207)14}{2\ln\left[5\frac{0.5774(22) + 0.5(14)}{0.5774(22) + 2.5(14)}\right]} = 3 624.4 \text{ MN/m}$$
 Ans.

- **8-14** (a) From Table A-31, the nut height is H = 7/16 in. $L \ge l + H = 2 + 1 + 7/16 = 37/16$ in. Rounding up, L = 3.5 in Ans.
 - **(b)** From Eq. (8-13), $L_T = 2d + 1/4 = 2(0.5) + 0.25 = 1.25$ in

From Table 8-7, $l_d = L - L_T = 3.5 - 1.25 = 2.25$ in, $l_t = l - l_d = 3 - 2.25 = 0.75$ in

 $A_d = \pi (0.5^2)/4 = 0.1963 \text{ in}^2$. From Table 8-2, $A_t = 0.1419 \text{ in}^2$. From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.1963(0.1419)30}{0.1963(0.75) + 0.1419(2.25)} = 1.79 \text{ Mlbf/in}$$
 Ans



Top steel frustum: t = 1.5 in, d = 0.5 in, D = 0.75 in, E = 30 Mpsi. From Eq. (8-20)

$$k_{1} = \frac{0.5774\pi (30)0.5}{\ln \left[1.155(1.5) + 0.75 - 0.5\right](0.75 + 0.5)} = 22.65 \text{ Mlbf/in}$$
$$\ln \left[1.155(1.5) + 0.75 + 0.5\right](0.75 - 0.5)$$

Lower steel frustum: t = 0.5 in, d = 0.5 in, D = 0.75 + 2(1) tan $30^{\circ} = 1.905$ in, E = 30 Mpsi. Eq. (8-20) $\Rightarrow k_2 = 210.7$ Mlbf/in

Cast iron: t = 1 in, d = 0.5 in, D = 0.75 in, E = 14.5 Mpsi (Table 8-8). Eq. (8-20) $\Rightarrow k_3 = 12.27$ Mlbf/in

From Eq. (8-18)


$$k_m = (1/k_1 + 1/k_2 + 1/k_3)^{-1} = (1/22.65 + 1/210.7 + 1/12.27)^{-1} = 7.67 \text{ Mlbf/in}$$
 Ans

- **8-15** (a) From Table A-32, the washer thickness is 0.095 in. Thus, l = 2 + 1 + 2(0.095) = 3.19 in. From Table A-31, the nut height is H = 7/16 in. $L \ge l + H = 3.19 + 7/16 = 3.63$ in. Rounding up, L = 3.75 in Ans.
 - **(b)** From Eq. (8-13), $L_T = 2d + 1/4 = 2(0.5) + 0.25 = 1.25$ in

From Table 8-7, $l_d = L - L_T = 3.75 - 1.25 = 2.5$ in, $l_t = l - l_d = 3.19 - 2.5 = 0.69$ in

 $A_d = \pi (0.5^2)/4 = 0.1963 \text{ in}^2$. From Table 8-2, $A_t = 0.1419 \text{ in}^2$. From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.1963(0.1419)30}{0.1963(0.69) + 0.1419(2.5)} = 1.705 \text{ Mlbf/in}$$
 Ans.



Each steel washer frustum: t = 0.095 in, d = 0.531 in (Table A-32), D = 0.75 in, E = 30 Mpsi. From Eq. (8-20)

$$k_1 = \frac{0.5774\pi (30)0.531}{\ln \left[1.155 (0.095) + 0.75 - 0.531 \right] (0.75 + 0.531)} = 89.20 \text{ Mlbf/in}$$

$$10 = \frac{1.155 (0.095) + 0.75 + 0.531}{1.155 (0.095) + 0.75 + 0.531} = 89.20 \text{ Mlbf/in}$$

Top plate, top steel frustum: t = 1.5 in, d = 0.5 in, D = 0.75 + 2(0.095) tan $30^{\circ} = 0.860$ in, E = 30 Mpsi. Eq. (8-20) $\Rightarrow k_2 = 28.99$ Mlbf/in

Top plate, lower steel frustum: t = 0.5 in, d = 0.5 in, D = 0.860 + 2(1) tan $30^{\circ} = 2.015$ in, E = 30 Mpsi. Eq. (8-20) $\Rightarrow k_3 = 234.08$ Mlbf/in

Cast iron: t = 1 in, d = 0.5 in, D = 0.75 + 2(0.095) tan $30^{\circ} = 0.860$ in, E = 14.5 Mpsi (Table 8-8). Eq. (8-20) $\Rightarrow k_4 = 15.99$ Mlbf/in From Eq. (8-18)

$$k_m = (2/k_1 + 1/k_2 + 1/k_3 + 1/k_4)^{-1} = (2/89.20 + 1/28.99 + 1/234.08 + 1/15.99)^{-1}$$

= 8.08 Mlbf/in Ans.


8-16 (a) From Table 8-7, l = h + d/2 = 2 + 0.5/2 = 2.25 in. $L \ge h + 1.5 d = 2 + 1.5(0.5) = 2.75$ in Ans.

(b) From Table 8-7,
$$L_T = 2d + 1/4 = 2(0.5) + 0.25 = 1.25$$
 in $l_d = L - L_T = 2.75 - 1.25 = 1.5$ in, $l_t = l - l_d = 2.25 - 1.5 = 0.75$ in

Shigley's MED, 10th edition

 $A_d = \pi (0.5^2)/4 = 0.1963 \text{ in}^2$. From Table 8-2, $A_t = 0.1419 \text{ in}^2$. From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.1963(0.1419)30}{0.1963(0.75) + 0.1419(1.5)} = 2.321 \text{ Mlbf/in}$$
 Ans.



Top steel frustum: t = 1.125 in, d = 0.5 in, D = 0.75 in, E = 30 Mpsi. From Eq. (8-20)

$$k_1 = \frac{0.5774\pi (30)0.5}{\ln \left[1.155 (1.125) + 0.75 - 0.5 \right] (0.75 + 0.5)} = 24.48 \text{ Mlbf/in}$$
$$\ln \left[1.155 (1.125) + 0.75 + 0.5 \right] (0.75 - 0.5)$$

Lower steel frustum: t = 0.875 in, d = 0.5 in, D = 0.75 + 2(0.25) tan $30^{\circ} = 1.039$ in, E = 30 Mpsi. Eq. (8-20) $\Rightarrow k_2 = 49.36$ Mlbf/in

Cast iron: t = 0.25 in, d = 0.5 in, D = 0.75 in, E = 14.5 Mpsi (Table 8-8). Eq. (8-20) $\Rightarrow k_3 = 23.49$ Mlbf/in

From Eq. (8-18)


$$k_m = (1/k_1 + 1/k_2 + 1/k_3)^{-1} = (1/24.48 + 1/49.36 + 1/23.49)^{-1} = 9.645 \text{ Mlbf/in}$$
 Ans.

8-17 a) Grip, l = 2(2 + 0.095) = 4.19 in. $L \ge 4.19 + 7/16 = 4.628$ in. Rounding up, L = 4.75 in *Ans*.

(b) From Eq. (8-13),
$$L_T = 2d + 1/4 = 2(0.5) + 0.25 = 1.25$$
 in

From Table 8-7, $l_d = L - L_T = 4.75 - 1.25 = 3.5$ in, $l_t = l - l_d = 4.19 - 3.5 = 0.69$ in $A_d = \pi (0.5^2)/4 = 0.1963$ in². From Table 8-2, $A_t = 0.1419$ in². From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.1963(0.1419)30}{0.1963(0.69) + 0.1419(3.5)} = 1.322 \text{ Mlbf/in}$$
 Ans.



Upper and lower halves are the same. For the upper half, Steel frustum: t = 0.095 in, d = 0.531 in, D = 0.75 in, and E = 30 Mpsi. From Eq. (8-20)

$$k_1 = \frac{0.5774\pi (30)0.531}{\ln \left[\frac{1.155(0.095) + 0.75 - 0.531}{[1.155(0.095) + 0.75 + 0.531](0.75 + 0.531)} \right]} = 89.20 \text{ Mlbf/in}$$

Aluminum: t = 2 in, d = 0.5 in, D = 0.75 + 2(0.095) tan $30^{\circ} = 0.860$ in, and E = 10.3 Mpsi. Eq. (8-20) $\Rightarrow k_2 = 9.24$ Mlbf/in For the top half, $k'_m = (1/k_1 + 1/k_2)^{-1} = (1/89.20 + 1/9.24)^{-1} = 8.373$ Mlbf/in Since the bottom half is the same, the overall stiffness is given by

$$k_m = (1/k'_m + 1/k'_m)^{-1} = k'_m/2 = 8.373/2 = 4.19 \text{ Mlbf/in}$$
 Ans


8-18 (a) Grip, l = 2(2 + 0.095) = 4.19 in. $L \ge 4.19 + 7/16 = 4.628$ in. Rounding up, L = 4.75 in Ans.

(b) From Eq. (8-13),
$$L_T = 2d + 1/4 = 2(0.5) + 0.25 = 1.25$$
 in

Shigley's MED, 10th edition

From Table 8-7, $l_d = L - L_T = 4.75 - 1.25 = 3.5$ in, $l_t = l - l_d = 4.19 - 3.5 = 0.69$ in $A_d = \pi (0.5^2)/4 = 0.1963$ in². From Table 8-2, $A_t = 0.1419$ in². From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.1963(0.1419)30}{0.1963(0.69) + 0.1419(3.5)} = 1.322 \text{ Mlbf/in}$$
 Ans.



Upper aluminum frustum: t = [4 + 2(0.095)]/2 = 2.095 in, d = 0.5 in, D = 0.75 in, and E = 10.3 Mpsi. From Eq. (8-20)

$$k_1 = \frac{0.5774\pi (10.3)0.5}{\ln \left[1.155(2.095) + 0.75 - 0.5 \right] (0.75 + 0.5)} = 7.23 \text{ Mlbf/in}$$

$$\frac{10.5774\pi (10.3)0.5}{\left[1.155(2.095) + 0.75 + 0.5 \right] (0.75 - 0.5)} = 7.23 \text{ Mlbf/in}$$

Lower aluminum frustum: t = 4 - 2.095 = 1.905 in, d = 0.5 in, D = 0.75 + 4(0.095) tan $30^\circ = 0.969$ in, and E = 10.3 Mpsi. Eq. (8-20) $\Rightarrow k_2 = 11.34$ Mlbf/in

Steel washers frustum: t = 2(0.095) = 0.190 in, d = 0.531 in, D = 0.75 in, and E = 30 Mpsi. Eq. (8-20) $\Rightarrow k_3 = 53.91$ Mlbf/in

From Eq. (8-18)
$$k_m = (1/k_1 + 1/k_2 + 1/k_3)^{-1} = (1/7.23 + 1/11.34 + 1/53.91)^{-1} = 4.08 \text{ Mlbf/in}$$
 Ans.


8-19 (a) From Table A-31, the nut height is H = 8.4 mm. L > l + H = 50 + 8.4 = 58.4 mm.

Rounding up, L = 60 mm Ans.

Shigley's MED, 10th edition

(**b**) From Eq. (8-14), $L_T = 2d + 6 = 2(10) + 6 = 26$ mm, $l_d = L - L_T = 60 - 26 = 34$ mm, $l_t = l - l = 50 - 34 = 16$ mm. $A_d = \pi(10^2) / 4 = 78.54$ mm². From Table 8-1, $A_t = 58$ mm². From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{78.54(58.0)207}{78.54(16) + 58.0(34)} = 292.1 \text{ MN/m}$$
 Ans.



Upper and lower frustums are the same. For the upper half,

Aluminum: t = 10 mm, d = 10 mm, D = 15 mm, and from Table 8-8, E = 71 GPa. From Eq. (8-20)

$$k_{1} = \frac{0.5774\pi (71)10}{\ln \left[1.155(10) + 15 - 10\right](15 + 10)} = 1576 \text{ MN/m}$$
$$1.155(10) + 15 + 10\left[(15 - 10)\right]$$

Steel: t = 15 mm, d = 10 mm, $D = 15 + 2(10) \tan 30^{\circ} = 26.55$ mm, and E = 207 GPa. From Eq. (8-20)

$$k_2 = \frac{0.5774\pi (207)10}{\ln \left[1.155(15) + 26.55 - 10 \right] (26.55 + 10)} = 11 \ 440 \ \text{MN/m}$$
$$\frac{11.155(15) + 26.55 + 10 \left[(26.55 - 10) \right]}{11.155(15) + 26.55 + 10 \left[(26.55 - 10) \right]} = 11 \ 440 \ \text{MN/m}$$

For the top half, $k'_m = (1/k_1 + 1/k_2)^{-1} = (1/1576 + 1/11440)^{-1} = 1385 \text{ MN/m}$

Since the bottom half is the same, the overall stiffness is given by

$$k_m = (1/k'_m + 1/k'_m)^{-1} = k'_m/2 = 1385/2 = 692.5 \text{ MN/m}$$
 Ans.


8-20 (a) From Table A-31, the nut height is H = 8.4 mm. L > l + H = 60 + 8.4 = 68.4 mm.

Rounding up, L = 70 mm Ans.

(**b**) From Eq. (8-14), $L_T = 2d + 6 = 2(10) + 6 = 26$ mm, $l_d = L - L_T = 70 - 26 = 44$ mm, $l_t = l - l_d = 60 - 44 = 16$ mm. $A_d = \pi (10^2) / 4 = 78.54$ mm². From Table 8-1, $A_t = 58$ mm². From Eq. (8-17)

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{78.54(58.0)207}{78.54(16) + 58.0(44)} = 247.6 \text{ MN/m}$$
 Ans.

(c)



Upper aluminum frustum: t = 10 mm, d = 10 mm, D = 15 mm, and E = 71 GPa. From Eq. (8-20)

$$k_{1} = \frac{0.5774\pi (10.3)71}{\ln \left[\frac{1.155(2.095) + 15 - 10}{1.155(2.095) + 15 + 10} \right] (15 + 10)} = 1576 \text{ MN/m}$$

Lower aluminum frustum: t = 20 mm, d = 10 mm, D = 15 mm, and E = 71 GPa. Eq. (8-20) $\Rightarrow k_2 = 1$ 201 MN/m

Top steel frustum: t = 20 mm, d = 10 mm, D = 15 + 2(10) tan $30^{\circ} = 26.55$ mm, and E = 207 GPa. Eq. (8-20) $\Rightarrow k_3 = 9.781$ MN/m

Lower steel frustum: t = 10 mm, d = 10 mm, D = 15 + 2(20) tan $30^{\circ} = 38.09$ mm, and E = 207 GPa. Eq. $(8-20) \Rightarrow k_4 = 29~070$ MN/m


From Eq. (8-18)

$$k_m = (1/k_1 + 1/k_2 + 1/k_3 + 1/k_4)^{-1} = (1/1576 + 1/1201 + 1/9781 + 1/29070)^{-1}$$

= 623.5 MN/m Ans.

- **8-21** (a) From Table 8-7, l = h + d/2 = 10 + 30 + 10/2 = 45 mm. $L \ge h + 1.5$ d = 10 + 30 + 1.5(10) = 55 mm. *Ans*.
 - (**b**) From Eq. (8-14), $L_T = 2d + 6 = 2(10) + 6 = 26$ mm, $l_d = L L_T = 55 26 = 29$ mm, $l_t = l l_d = 45 29 = 16$ mm. $A_d = \pi(10^2) / 4 = 78.54$ mm². From Table 8-1, $A_t = 58$ mm². From Eq. (8-17)

29 lilli,
$$l_t = l - l_d = 43 - 29 = 16$$
 lilli. $A_d = \pi (10) / 4 = 78.34$ lilli. Fro $A_t = 58 \text{ mm}^2$. From Eq. (8-17)
$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{78.54 (58.0) 207}{78.54 (16) + 58.0 (29)} = 320.9 \text{ MN/m}$$
Ans.



Upper aluminum frustum: t = 10 mm, d = 10 mm, D = 15 mm, and E = 71 GPa. From Eq. (8-20)

$$k_{1} = \frac{0.5774\pi (10.3)71}{\ln \left[1.155(2.095) + 15 - 10\right](15 + 10)} = 1576 \text{ MN/m}$$
$$\frac{\left[1.155(2.095) + 15 + 10\right](15 - 10)}{\left[1.155(2.095) + 15 + 10\right](15 - 10)}$$

Lower aluminum frustum: t = 5 mm, d = 10 mm, D = 15 mm, and E = 71 GPa. Eq. $(8-20) \Rightarrow k_2 = 2\ 300$ MN/m

Top steel frustum: t = 12.5 mm, d = 10 mm, D = 15 + 2(10) tan $30^{\circ} = 26.55$ mm, and E = 207 GPa. Eq. $(8-20) \Rightarrow k_3 = 12.759$ MN/m

Lower steel frustum: t = 17.5 mm, d = 10 mm, D = 15 + 2(5) tan $30^{\circ} = 20.77$ mm, and E = 207 GPa. Eq. $(8-20) \Rightarrow k_4 = 6.806$ MN/m

From Eq. (8-18)

$$k_m = (1/k_1 + 1/k_2 + 1/k_3 + 1/k_4)^{-1} = (1/1576 + 1/2300 + 1/12759 + 1/6806)^{-1}$$

= 772.4 MN/m Ans.

-----<u>-</u>------

8-22 Equation (f), p. 428:
$$C = \frac{k_b}{k_b + k_m}$$

Eq. (8-17):
$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d}$$

Eq. (8-22):
$$k_{m} = \frac{0.5774\pi (207)d}{2\ln \left[5\frac{0.5774(40) + 0.5d}{0.5774(40) + 2.5d} \right]}$$

See Table 8-7 for other terms used.

Using a spreadsheet, with coarse-pitch bolts (units are mm, mm², MN/m):

d	A_t	A_d	Н	L >	L	L_T
10	58	78.53982	8.4	48.4	50	26
12	84.3	113.0973	10.8	50.8	55	30
14	115	153.938	12.8	52.8	55	34
16	157	201.0619	14.8	54.8	55	38
20	245	314.1593	18	58	60	46
24	353	452.3893	21.5	61.5	65	54
30	561	706.8583	25.6	65.6	70	66


d	l	l_d	l_t	k_b	k_m	С
10	40	24	16	356.0129	1751.566	0.16892
12	40	25	15	518.8172	2235.192	0.188386
14	40	21	19	686.2578	2761.721	0.199032
16	40	17	23	895.9182	3330.796	0.211966
20	40	14	26	1373.719	4595.515	0.230133
24	40	11	29	1944.24	6027.684	0.243886
30	40	4	36	2964.343	8487.533	0.258852

Use a M14 \times 2 bolt, with length 55 mm. *Ans.*

8-23 Equation (f), p. 428:
$$C = \frac{k_b}{k_b + k_w}$$

Shigley's MED, 10th edition

Eq. (8-17):
$$k_b = \frac{A_d A_i E}{A_d l_i + A_i l_d}$$



For upper frustum, Eq. (8-20), with D = 1.5 d and t = 1.5 in:

$$k_{1} = \frac{0.5774\pi(30)d}{\ln\left[\frac{\left[1.155(1.5) + 0.5d\right](2.5d)}{\left[1.155(1.5) + 2.5d\right](0.5d)}\right]} = \frac{0.5774\pi(30)d}{\ln\left[5\frac{(1.733 + 0.5d)}{(1.733 + 2.5d)}\right]}$$

Lower steel frustum, with $D = 1.5d + 2(1) \tan 30^{\circ} = 1.5d + 1.155$, and t = 0.5 in:

$$k_2 = \frac{0.5774\pi (30)d}{\ln \left[\frac{(1.733 + 0.5d)(2.5d + 1.155)}{(1.733 + 2.5d)(0.5d + 1.155)} \right]}$$

For cast iron frustum, let E = 14. 5 Mpsi, and D = 1.5 d, and t = 1 in:

$$k_3 = \frac{0.5774\pi (14.5)d}{\ln \left[5\frac{(1.155 + 0.5d)}{(1.155 + 2.5d)} \right]}$$

Overall,
$$k_m = (1/k_1 + 1/k_2 + 1/k_3)^{-1}$$

See Table 8-7 for other terms used.

Using a spreadsheet, with coarse-pitch bolts (units are in, in², Mlbf/in):


		1	ı	ı	1	ı	ı	1
d	A_t	A_d	Н	L >	L	L_T	l	
0.375	0.0775	0.110447	0.328125	3.328125	3.5	1	3	
0.4375	0.1063	0.15033	0.375	3.375	3.5	1.125	3	
0.5	0.1419	0.19635	0.4375	3.4375	3.5	1.25	3	
0.5625	0.182	0.248505	0.484375	3.484375	3.5	1.375	3	
0.625	0.226	0.306796	0.546875	3.546875	3.75	1.5	3	
0.75	0.334	0.441786	0.640625	3.640625	3.75	1.75	3	
0.875	0.462	0.60132	0.75	3.75	3.75	2	3	
d	l_d	l_t	k_b	k_1	k_2	k_3	k_m	C
0.375	2.5	0.5	1.031389	15.94599	178.7801	8.461979	5.362481	0.161309
0.4375	2.375	0.625	1.383882	19.21506	194.465	10.30557	6.484256	0.175884
0.5	2.25	0.75	1.791626	22.65332	210.6084	12.26874	7.668728	0.189383
0.5625	2.125	0.875	2.245705	26.25931	227.2109	14.35052	8.915294	0.20121
0.625	2.25	0.75	2.816255	30.03179	244.2728	16.55009	10.22344	0.215976
0.75	2	1	3.988786	38.07191	279.7762	21.29991	13.02271	0.234476
0.875	1.75	1.25	5.341985	46.7663	317.1203	26.51374	16.06359	0.24956

Use a $\frac{9}{16}$ –12 UNC × 3.5 in long bolt

Ans.

8-24 Equation (f), p. 428:
$$C = \frac{k_b}{k_b + k_m}$$

Eq. (8-17):
$$k_b = \frac{A_d A_l E}{A_d l_t + A_l l_d}$$



Top frustum, Eq. (8-20), with E = 10.3Mpsi, D = 1.5 d, and t = l/2:

$$k_{1} = \frac{0.5774\pi (10.3)d}{\ln \left[5\frac{1.155 l/2 + 0.5d}{1.155 l/2 + 2.5d} \right]}$$

Middle frustum, with E = 10.3 Mpsi, D = 1.5d + 2(l - 0.5) tan 30°, and t = 0.5 - l/20.5774 π (10.3)d

$$k_{2} = \frac{0.5774k(10.5)d}{\ln \frac{\left\{ \left[1.155(0.5 - 0.5l) + 0.5d + 2(l - 0.5)\tan 30^{\circ} \right] \left[2.5d + 2(l - 0.5)\tan 30^{\circ} \right] \right\}}{\left\{ \left[1.155(0.5 - 0.5l) + 2.5d + 2(l - 0.5)\tan 30^{\circ} \right] \left[0.5d + 2(l - 0.5)\tan 30^{\circ} \right] \right\}}$$

Lower frustum, with E = 30Mpsi, D = 1.5 d, t = l - 0.5

$$k_{3} = \frac{0.5774\pi(30)d}{\ln 5\left\{ \frac{\left[1.155(l-0.5)+0.5d\right]}{\left[1.155(l-0.5)+2.5d\right]}\right\}}$$

See Table 8-7 for other terms used.

Using a spreadsheet, with coarse-pitch bolts (units are in, in², Mlbf/in)

Size	d	A_t	A_d	L >	L	L_T	l	l_d
1	0.073	0.00263	0.004185	0.6095	0.75	0.396	0.5365	0.354
2	0.086	0.0037	0.005809	0.629	0.75	0.422	0.543	0.328
3	0.099	0.00487	0.007698	0.6485	0.75	0.448	0.5495	0.302
4	0.112	0.00604	0.009852	0.668	0.75	0.474	0.556	0.276
5	0.125	0.00796	0.012272	0.6875	0.75	0.5	0.5625	0.25
6	0.138	0.00909	0.014957	0.707	0.75	0.526	0.569	0.224
8	0.164	0.014	0.021124	0.746	0.75	0.578	0.582	0.172
10	0.19	0.0175	0.028353	0.785	1	0.63	0.595	0.37
Size	d	l_t	k_b	k_1	k_2	k_3	k_m	C
1	0.073	0.1825	0.194841	1.084468	1.954599	7.09432	0.635049	0.23478
2	0.086	0.215	0.261839	1.321595	2.449694	8.357692	0.778497	0.251687
3	0.099	0.2475	0.333134	1.570439	2.993366	9.621064	0.930427	0.263647
4	0.112	0.28	0.403377	1.830494	3.587564	10.88444	1.090613	0.27
5	0.125	0.3125	0.503097	2.101297	4.234381	12.14781	1.258846	0.285535
6	0.138	0.345	0.566787	2.382414	4.936066	13.41118	1.434931	0.28315
8	0.164	0.41	0.801537	2.974009	6.513824	15.93792	1.809923	0.306931
10	0.19	0.225	1.15799	3.602349	8.342138	18.46467	2.214214	0.343393

Use a 2–56 UNC \times 0.75 in long bolt.

Ans.

8-25 For half of joint, Eq. (8-20): t = 20 mm, d = 14 mm, D = 21 mm, and E = 207 GPa

$$k_{1} = \frac{0.5774\pi (207)14}{\ln \left[\frac{1.155(20) + 21 - 14}{1.155(20) + 21 + 14} \right] (21 + 14)} = 5523 \text{ MN/m}$$

$$k_m = (1/k_1 + 1/k_1)^{-1} = k_1/2 = 5523/2 = 2762 \text{ MN/m}$$
 Ans.

From Eq. (8-22) with l = 40 mm

$$k_{m} = \frac{0.5774\pi (207)14}{2\ln \left[5\frac{0.5774(40) + 0.5(14)}{0.5774(40) + 2.5(14)} \right]} = 2762 \text{ MN/m}$$
 Ans.

which agrees with the earlier calculation.

For Eq. (8-23), from Table 8-8, $A = 0.787 \, 15$, $B = 0.628 \, 73$

$$k_m = 207(14)(0.78715) \exp [0.62873(14)/40] = 2843 \text{ MN/m}$$
 Ans.

This is 2.9% higher than the earlier calculations.

8-26 (a) Grip, l = 10 in. Nut height, H = 41/64 in (Table A-31). $L \ge l + H = 10 + 41/64 = 10.641$ in. Let L = 10.75 in. Table 8-7, $L_T = 2d + 0.5 = 2(0.75) + 0.5 = 2$ in, $l_d = L - L_T = 10.75 - 2 = 8.75$ in, $l_t = l - l_d = 10 - 8.75 = 1.25$ in

 $A_d = \pi (0.75^2)/4 = 0.4418 \text{ in}^2$, $A_t = 0.373 \text{ in}^2$ (Table 8-2) Eq. (8-17),

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.4418(0.373)30}{0.4418(1.25) + 0.373(8.75)} = 1.296$$
 Mlbf/in Ans.

Eq. (4-4), p. 163

$$k_m = \frac{A_m E_m}{I} = \frac{(\pi/4)(1.125^2 - 0.75^2)30}{10} = 1.657$$
 Mlbf/in Ans.

Eq. (f), p. 428,
$$C = k_b/(k_b + k_m) = 1.296/(1.296 + 1.657) = 0.439$$
 Ans.

Let: $N_t = \text{no. of turns}$, p = pitch of thread (in), N = no. of threads per in = 1/p. Then,

$$\delta = \delta_b + \delta_m = N_t \, p = N_t / N \tag{1}$$

But, $\delta_b = F_i / k_b$, and, $\delta_m = F_i / k_m$. Substituting these into Eq. (1) and solving for F_i gives

$$F_{i} = \frac{k_{b}k_{m}}{k_{b} + k_{m}} \frac{N_{t}}{N}$$

$$= \frac{1.296(1.657)10^{6}}{1.296 + 1.657} \frac{1/3}{16} = 15150 \text{ lbf}$$
Ans.

8-27 Proof for the turn-of-nut equation is given in the solution of Prob. 8-26, Eq. (2), where $N_t = \theta/360^\circ$.

The relationship between the turn-of-nut method and the torque-wrench method is as follows.

$$N_{t} = \left(\frac{k_{b} + k_{m}}{k_{b}k_{m}}\right) F_{i}N \qquad \text{(turn-of-nut)}$$

$$T = KF_{i}d \qquad \text{(torque-wrench)}$$

Eliminate F_i

$$N_{t} = \left(\frac{k_{b} + k_{m}}{k_{b}k_{m}}\right) \frac{NT}{Kd} = \frac{\theta}{360^{\circ}} \quad Ans.$$

8-28 (a) From Ex. 8-4, $F_i = 14.4$ kip, $k_b = 5.21(10^6)$ lbf/in, $k_m = 8.95(10^6)$ lbf/in Eq. (8-27): $T = kF_i d = 0.2(14.4)(10^3)(5/8) = 1800$ lbf · in Ans. From Prob. 8-27,

$$N_{t} = \left(\frac{k_{b} + k_{m}}{k_{b}k_{m}}\right) F_{i}N = \left[\frac{5.21 + 8.95}{5.21(8.95)10^{6}}\right] (14.4)(10^{3})11$$
$$= 0.0481 \text{ turns} = 17.3^{\circ} \quad Ans.$$

Bolt group is (1.5)/(5/8) = 2.4 diameters. Answer is much lower than RB&W recommendations.

recommendations.

8-29 $C = k_b / (k_b + k_m) = 3/(3+12) = 0.2$, $P = P_{\text{total}} / N = 80/6 = 13.33$ kips/bolt Table 8-2, $A_t = 0.141$ 9 in²; Table 8-9, $S_p = 120$ kpsi; Eqs. (8-31) and (8-32), $F_i = 0.75$ $A_t S_p = 0.75(0.141$ 9)(120) = 12.77 kips (a) From Eq. (8-28), the factor of safety for yielding is

$$n_p = \frac{S_p A_t}{CP + F_i} = \frac{120(0.1419)}{0.2(13.33) + 12.77} = 1.10$$
 Ans.

(b) From Eq. (8-29), the overload factor is

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{120(0.1419) - 12.77}{0.2(13.33)} = 1.60$$
 Ans.

(c) From Eq. (803), the joint separation factor of safety is

$$n_0 = \frac{F_i}{P(1-C)} = \frac{12.77}{13.33(1-0.2)} = 1.20$$
 Ans.

8-30 1/2 - 13 UNC Grade 8 bolt, K = 0.20

(a) Proof strength, Table 8-9, $S_p = 120 \text{ kpsi}$ Table 8-2, $A_t = 0.141 \text{ 9 in}^2$ Maximum, $F_i = S_p A_t = 120(0.141 \text{ 9}) = 17.0 \text{ kips}$

(**b**) From Prob. 8-29, C = 0.2, P = 13.33 kips Joint separation, Eq. (8-30) with $n_0 = 1$

Minimum $F_i = P(1 - C) = 13.33(1 - 0.2) = 10.66$ kips Ans.

(c) $\overline{F}_i = (17.0 + 10.66)/2 = 13.8 \text{ kips}$ Eq. (8-27), $T = KF_i d = 0.2(13.8)10^3 (0.5)/12 = 115 \text{ lbf} \cdot \text{ft}$ Ans.

8-31 (a) Table 8-1, $A_t = 20.1 \text{ mm}^2$. Table 8-11, $S_p = 380 \text{ MPa}$.

Eq. (8-31),
$$F_i = 0.75 F_p = 0.75 A_t S_p = 0.75(20.1)380(10^{-3}) = 5.73 \text{ kN}$$

Eq. (f), p. 428,
$$C = \frac{k_b}{k_b + k_m} = \frac{1}{1 + 2.6} = 0.278$$

Shigley's MED, 10th edition

Eq. (8-28) with $n_p = 1$,

$$P = \frac{S_p A_t - F_i}{C} = \frac{0.25 S_p A_t}{C} = \frac{0.25 (20.1)380 (10^{-3})}{0.278} = 6.869 \text{ kN}$$

$$P_{\text{total}} = NP = 8(6.869) = 55.0 \text{ kN} \qquad Ans.$$

(b) Eq. (8-30) with $n_0 = 1$,

$$P = \frac{F_i}{1 - C} = \frac{5.73}{1 - 0.278} = 7.94 \text{ kN}$$

 $P_{\text{total}} = NP = 8(7.94) = 63.5 \text{ kN}$ Ans. Bolt stress would exceed proof strength

8-32 (a) Table 8-2, $A_t = 0.141 \text{ 9 in}^2$. Table 8-9, $S_p = 120 \text{ kpsi.}$

Eq. (8-31),
$$F_i = 0.75 F_p = 0.75 A_t S_p = 0.75(0.141 \text{ 9})120 = 12.77 \text{ kips}$$

Eq. (f), p. 428,
$$C = \frac{k_b}{k_b + k_m} = \frac{4}{4 + 12} = 0.25$$

Eq. (8-28) with $n_p = 1$,

$$P_{\text{total}} = N \left(\frac{S_p A_t - F_i}{C} \right) = \frac{0.25 N S_p A_t}{C}$$

$$N = \frac{P_{\text{total}}C}{0.25S_{p,A}} = \frac{80(0.25)}{0.25(120)0.1419} = 4.70$$

Round to N = 5 bolts Ans.

(b) Eq. (8-30) with $n_0 = 1$,

$$P_{\text{total}} = N \left(\frac{F_i}{1 - C} \right)$$

$$N = \frac{P_{\text{total}} (1 - C)}{F_i} = \frac{80(1 - 0.25)}{12.77} = 4.70$$

Round to N = 5 bolts Ans.

Problems 8-33 through 8-44 and 8-51 through 8-58. Note to the instructor: In previous editions of this solutions manual, in Probs. 8-33 through 8-36 the cylinder diameter was mistakenly used, instead of the effective gasket diameter, in determining the external force from the cylinder pressure. To correct this, the second printing of the 10th edition changes the problem statement so that the old value of the cylinder diameter is used for the effective gasket diameter. Consequently, the solutions to these problems, as well as several others that reference these problems remain numerically the same as before, with the diameter being redefined in the problem statements.

8-33 Bolts: From Table A-31, the nut height is H = 10.8 mm. $L \ge l + H = 40 + 10.8 = 50.8$ mm.

Round up to L = 55 mm Ans.

Eq. (8-14):
$$L_T = 2d + 6 = 2(12) + 6 = 30 \text{ mm}$$

Table 8-7:
$$l_d = L - L_T = 55 - 30 = 25$$
 mm, $l_t = l - l_d = 40 - 25 = 15$ mm

$$A_d = \pi (12^2)/4 = 113.1 \text{ mm}^2$$
, Table 8-1: $A_t = 84.3 \text{ mm}^2$

Eq. (8-17):

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{113.1(84.3)207}{113.1(15) + 84.3(25)} = 518.8 \text{ MN/m}$$

Members: Steel cyl. head: t = 20 mm, d = 12 mm, D = 18 mm, E = 207 GPa. Eq. (8-20),

$$k_{1} = \frac{0.5774\pi (207)12}{\ln \left[1.155(20) + 18 - 12\right](18 + 12)} = 4470 \text{ MN/m}$$

$$\ln \left[1.155(20) + 18 + 12\right](18 - 12)$$

Cast iron: t = 20 mm, d = 12 mm, D = 18 mm, E = 100 GPa (from Table 8-8). The only difference from k_1 is the material

$$k_2 = (100/207)(4470) = 2159 \text{ MN/m}$$

Eq. (8-18):
$$k_m = (1/4470 + 1/2159)^{-1} = 1456 \text{ MN/m}$$

$$C = k_b / (k_b + k_m) = 518.8/(518.8 + 1456) = 0.263$$

Table 8-11: $S_p = 650 \text{ MPa}$

For a non-permanent connection, using Eqs. (8-31) and (8-32)

$$F_i = 0.75 A_t S_p = 0.75(84.3)(650)10^{-3} = 41.1 \text{ kN}$$

The total external load is $P_{\text{total}} = p_g A_g$, where A_g is the effective area of the cylinder, based on the effective sealing diameter of 100 mm. The external load per bolt is $P = P_{\text{total}}/N$. Thus

$$P = [6\pi (100^2)/4](10^{-3})/10 = 4.712 \text{ kN/bolt}$$

Yielding factor of safety, Eq. (8-28):

$$n_p = \frac{S_p A_t}{CP + F_i} = \frac{650(84.3)10^{-3}}{0.263(4.712) + 41.10} = 1.29$$
 Ans.

Overload factor of safety, Eq. (8-29):

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{650(84.3)10^{-3} - 41.10}{0.263(4.712)} = 11.1$$
 Ans.

Separation factor of safety, Eq. (8-30):

$$n_0 = \frac{F_i}{P(1-C)} = \frac{41.10}{4.712(1-0.263)} = 11.8$$
 Ans.

8-34 Instructors: See note preceding Prob. 8-33.

Bolts: Grip, l = 1/2 + 5/8 = 1.125 in. From Table A-31, the nut height is H = 7/16 in. $L \ge l + H = 1.125 + 7/16 = 1.563$ in.

Round up to L = 1.75 in Ans.

Eq. (8-13):
$$L_T = 2d + 0.25 = 2(0.5) + 0.25 = 1.25$$
 in

Table 8-7:
$$l_d = L - L_T = 1.75 - 1.25 = 0.5$$
 in, $l_t = l - l_d = 1.125 - 0.5 = 0.625$ in

$$A_d = \pi (0.5^2)/4 = 0.196 \text{ 3 in}^2$$
, Table 8-2: $A_t = 0.141 \text{ 9 in}^2$

Eq. (8-17):

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.196 \ 3(0.141 \ 9)30}{0.196 \ 3(0.625) + 0.141 \ 9(0.5)} = 4.316 \ \text{Mlbf/in}$$

Members: Steel cyl. head: t = 0.5 in, d = 0.5 in, D = 0.75 in, E = 30 Mpsi. Eq. (8-20),

$$k_1 = \frac{0.5774\pi (30)0.5}{\ln \left[1.155(0.5) + 0.75 - 0.5 \right] (0.75 + 0.5)} = 33.30 \text{ Mlbf/in}$$

$$\frac{11.155(0.5) + 0.75 + 0.5}{11.155(0.5) + 0.75 + 0.5} = 33.30 \text{ Mlbf/in}$$

Cast iron: Has two frusta. Midpoint of complete joint is at (1/2 + 5/8)/2 = 0.5625 in.

Upper frustum,
$$t = 0.5625 - 0.5 = 0.0625$$
 in, $d = 0.5$ in, $D = 0.75 + 2(0.5)$ tan $30^{\circ} = 1.327$ in, $E = 14.5$ Mpsi (from Table 8-8)

Eq. (8-20)
$$\Rightarrow k_2 = 292.7 \text{ Mlbf/in}$$

Lower frustum, t = 0.5625 in, d = 0.5 in, D = 0.75 in, E = 14.5 Mpsi

Eq. (8-20)
$$\Rightarrow k_3 = 15.26 \text{ Mlbf/in}$$

Eq. (8-18):
$$k_m = (1/33.30 + 1/292.7 + 1/15.26)^{-1} = 10.10 \text{ Mlbf/in}$$

$$C = k_b / (k_b + k_m) = 4.316/(4.316+10.10) = 0.299$$

Table 8-9: $S_p = 85 \text{ kpsi}$

For a non-permanent connection, using Eqs. (8-31) and (8-32)

$$F_i = 0.75 A_t S_p = 0.75(0.141 9)(85) = 9.05 \text{ kips}$$

The total external load is $P_{\text{total}} = p_g A_g$, where A_g is the effective area of the cylinder, based on the effective sealing diameter of 3.5 in. The external load per bolt is $P = P_{\text{total}}/N$. Thus,

$$P = [1.500\pi(3.5^2)/4](10^{-3})/10 = 1.443 \text{ kips/bolt}$$

Yielding factor of safety, Eq. (8-28):

$$n_p = \frac{S_p A_t}{CP + F_t} = \frac{85(0.1419)}{0.299(1.443) + 9.05} = 1.27$$
 Ans.

Overload factor of safety, Eq. (8-29):

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{85(0.1419) - 9.05}{0.299(1.443)} = 6.98$$
 Ans.

Separation factor of safety, Eq. (8-30):

$$n_0 = \frac{F_i}{P(1-C)} = \frac{9.05}{1.443(1-0.299)} = 8.95$$
 Ans.

8-35 Instructors: See note preceding Prob. 8-33.

Bolts: Grip: l = 20 + 25 = 45 mm. From Table A-31, the nut height is H = 8.4 mm. $L \ge l + H = 45 + 8.4 = 53.4$ mm.

Round up to L = 55 mm Ans.

Eq. (8-14):
$$L_T = 2d + 6 = 2(10) + 6 = 26 \text{ mm}$$

Table 8-7:
$$l_d = L - L_T = 55 - 26 = 29 \text{ mm}, l_t = l - l_d = 45 - 29 = 16 \text{ mm}$$

$$A_d = \pi (10^2)/4 = 78.5 \text{ mm}^2$$
, Table 8-1: $A_t = 58.0 \text{ mm}^2$

Eq. (8-17):

$$k_b = \frac{A_d A_l E}{A_d l_t + A_l l_d} = \frac{78.5(58.0)207}{78.5(16) + 58.0(29)} = 320.8 \text{ MN/m}$$

Members: Steel cyl. head: t = 20 mm, d = 10 mm, D = 15 mm, E = 207 GPa. Eq. (8-20),

$$k_{1} = \frac{0.5774\pi (207)10}{\ln \left[1.155(20) + 15 - 10 \right] (15 + 10)} = 3503 \text{ MN/m}$$

$$\frac{1}{1} = \frac{1.155(20) + 15 - 10}{1.155(20) + 15 + 10} = 3503 \text{ MN/m}$$

Cast iron: Has two frusta. Midpoint of complete joint is at (20 + 25)/2 = 22.5 mm Upper frustum, t = 22.5 - 20 = 2.5 mm, d = 10 mm,

$$D = 15 + 2(20) \tan 30^\circ = 38.09 \text{ mm}, E = 100 \text{ GPa (from Table 8-8)},$$

Eq. (8-20) $\implies k_2 = 45 880 \text{ MN/m}$

Lower frustum,
$$t = 22.5$$
 mm, $d = 10$ mm, $D = 15$ mm, $E = 100$ GPa Eq. (8-20) $\Rightarrow k_3 = 1632$ MN/m

Eq. (8-18):
$$k_m = (1/3503 + 1/45 880 + 1/1632)^{-1} = 1087 \text{ MN/m}$$

$$C = k_b / (k_b + k_m) = 320.8/(320.8 + 1087) = 0.228$$

Table 8-11: $S_p = 830 \text{ MPa}$

For a non-permanent connection, using Eqs. (8-31) and (8-32)

$$F_i = 0.75 A_t S_p = 0.75(58.0)(830)10^{-3} = 36.1 \text{ kN}$$

The total external load is $P_{\text{total}} = p_g A_g$, where A_g is the effective area of the cylinder, based on the effective sealing diameter of 0.8 m. The external load per bolt is $P = P_{\text{total}} / N$. Thus,

$$P = [550\pi(0.8^2)/4]/36 = 7.679 \text{ kN/bolt}$$

Yielding factor of safety, Eq. (8-28):

$$n_p = \frac{S_p A_t}{CP + F_i} = \frac{830(58.0)10^{-3}}{0.228(7.679) + 36.1} = 1.27 \qquad Ans.$$

Overload factor of safety, Eq. (8-29):

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{830(58.0)10^{-3} - 36.1}{0.228(7.679)} = 6.88 \text{ Ans.}$$

Separation factor of safety, Eq. (8-30):

$$n_0 = \frac{F_i}{P(1-C)} = \frac{36.1}{7.679(1-0.228)} = 6.09$$
 Ans.

8-36 Instructors: See note preceding Prob. 8-33.

Bolts: Grip, l = 3/8 + 1/2 = 0.875 in. From Table A-31, the nut height is H = 3/8 in. $L \ge l + H = 0.875 + 3/8 = 1.25$ in.

Let L = 1.25 in Ans.

Eq. (8-13):
$$L_T = 2d + 0.25 = 2(7/16) + 0.25 = 1.125$$
 in

Table 8-7: $l_d = L - L_T = 1.25 - 1.125 = 0.125$ in, $l_t = l - l_d = 0.875 - 0.125 = 0.75$ in

$$A_d = \pi (7/16)^2 / 4 = 0.150 \text{ 3 in}^2$$
, Table 8-2: $A_t = 0.106 \text{ 3 in}^2$

Eq. (8-17),

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.150 \ 3(0.106 \ 3)30}{0.150 \ 3(0.75) + 0.106 \ 3(0.125)} = 3.804 \ \text{Mlbf/in}$$

Members: Steel cyl. head: t = 0.375 in, d = 0.4375 in, D = 0.65625 in, E = 30 Mpsi. Eq. (8-20),

$$k_{1} = \frac{0.5774\pi (30)0.4375}{\ln \left[1.155 (0.375) + 0.65625 - 0.4375 \right] (0.65625 + 0.4375)} = 31.40 \text{ Mlbf/in}$$

$$\frac{1.155 (0.375) + 0.65625 + 0.4375}{1.155 (0.375) + 0.65625 + 0.4375} = 31.40 \text{ Mlbf/in}$$

Cast iron: Has two frusta. Midpoint of complete joint is at (3/8 + 1/2)/2 = 0.4375 in.

Upper frustum, t = 0.4375 - 0.375 = 0.0625 in, d = 0.4375 in, D = 0.65625 + 2(0.375) tan $30^{\circ} = 1.089$ in, E = 14.5 Mpsi (from Table 8-8)

Eq. (8-20)
$$\Rightarrow k_2 = 195.5 \text{ Mlbf/in}$$

Lower frustum, t = 0.4375 in, d = 0.4375 in, D = 0.65625 in, E = 14.5 Mpsi

Eq. (8-20)
$$\implies k_3 = 14.08 \text{ Mlbf/in}$$

Eq. (8-18):
$$k_m = (1/31.40 + 1/195.5 + 1/14.08)^{-1} = 9.261 \text{ Mlbf/in}$$

$$C = k_b / (k_b + k_m) = 3.804/(3.804 + 9.261) = 0.291$$

Table 8-9: $S_p = 120 \text{ kpsi}$

For a non-permanent connection, using Eqs. (8-31) and (8-32)

$$F_i = 0.75 A_t S_p = 0.75(0.106 3)(120) = 9.57 \text{ kips}$$

The total external load is $P_{\text{total}} = p_g A_g$, where A_g is the effective area of the cylinder, based on the effective sealing diameter of 3.25 in. The external load per bolt is $P = P_{\text{total}}/N$. Thus,

 $P = [1\ 200\pi(3.25^2)/4](10^{-3})/8 = 1.244 \text{ kips/bolt}$

Yielding factor of safety, Eq. (8-28):

$$n_p = \frac{S_p A_i}{CP + F_i} = \frac{120(0.106 \text{ 3})}{0.291(1.244) + 9.57} = 1.28$$
 Ans.

Overload factor of safety, Eq. (8-29):

$$n_L = \frac{S_p A_i - F_i}{CP} = \frac{120(0.1063) - 9.57}{0.291(1.244)} = 8.80$$
 Ans.

Separation factor of safety, Eq. (8-30):

$$n_0 = \frac{F_i}{P(1-C)} = \frac{9.57}{1.244(1-0.291)} = 10.9$$
 Ans.

8-37 Instructors: See note preceding Prob. 8-33.

From Table 8-7,
$$h = t_1 = 20$$
 mm
For $t_2 > d$, $l = h + d/2 = 20 + 12/2 = 26$ mm
 $L \ge h + 1.5 d = 20 + 1.5(12) = 38$ mm. Round up to $L = 40$ mm
 $L_T = 2d + 6 = 2(12) + 6 = 30$ mm

$$l_d = L - L_T = 40 - 20 = 10 \text{ mm}$$

 $l_t = l - l_d = 26 - 10 = 16 \text{ mm}$

From Table 8-1, $A_t = 84.3 \text{ mm}^2$. $A_d = \pi (12^2)/4 = 113.1 \text{ mm}^2$ Eq. (8-17),

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{113.1(84.3)207}{113.1(16) + 84.3(10)} = 744.0 \text{ MN/m}$$

Similar to Fig. 8-21, we have three frusta

Top frusta, steel: t = l / 2 = 13 mm, d = 12 mm, D = 18 mm, E = 207 GPa. Eq. (8-20)

$$k_{1} = \frac{0.5774\pi (207)12}{\ln \left[1.155(13) + 18 - 12 \right] (18 + 12)} = 5 \ 316 \ \text{MN/m}$$
$$\frac{1.155(13) + 18 + 12 \left[(18 - 12) \right]}{\ln \left[1.155(13) + 18 + 12 \right] (18 - 12)} = 5 \ 316 \ \text{MN/m}$$

Middle frusta, steel: t = 20 - 13 = 7 mm, d = 12 mm, D = 18 + 2(13 - 7) tan $30^{\circ} = 24.93$ mm, E = 207 GPa. Eq. (8-20) $\Rightarrow k_2 = 15$ 660 MN/m

Lower frusta, cast iron: t = 26 - 20 = 6 mm, d = 12 mm, D = 18 mm, E = 100 GPa (see Table 8-8). Eq. (8-20) $\Rightarrow k_3 = 3$ 887 MN/m

Eq. (8-18),
$$k_m = (1/5 \ 316 + 1/15 \ 660 + 1/3 \ 887)^{-1} = 1 \ 964 \ MN/m$$

 $C = k_b / (k_b + k_m) = 744.0/(744.0 + 1 \ 964) = 0.275$

Table 8-11: $S_p = 650$ MPa. For a non-permanent connection, using Eqs. (8-31) and (8-32)

$$F_i = 0.75 A_t S_p = 0.75(84.3)(650)10^{-3} = 41.1 \text{ kN}$$

The total external load is $P_{\text{total}} = p_g A_g$, where A_g is the effective area of the cylinder, based on the effective sealing diameter of 100 mm. The external load per bolt is $P = P_{\text{total}} / N$. Thus

$$P = [6\pi (100^2)/4](10^{-3})/10 = 4.712 \text{ kN/bolt}$$

Yielding factor of safety, Eq. (8-28)

$$n_p = \frac{S_p A_t}{CP + F_s} = \frac{650(84.3)10^{-3}}{0.275(4.712) + 41.1} = 1.29$$
 Ans.

Overload factor of safety, Eq. (8-29)

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{650(84.3)10^{-3} - 41.1}{0.275(4.712)} = 10.7$$
 Ans.

Separation factor of safety, Eq. (8-30)

$$n_0 = \frac{F_i}{P(1-C)} = \frac{41.1}{4.712(1-0.275)} = 12.0$$
 Ans.

8-38 Instructors: See note preceding Prob. 8-33.

From Table 8-7, $h = t_1 = 0.5$ in

For $t_2 > d$, l = h + d/2 = 0.5 + 0.5/2 = 0.75 in

 $L \ge h + 1.5 d = 0.5 + 1.5(0.5) = 1.25$ in. Let L = 1.25 in

 $L_T = 2d + 0.25 = 2(0.5) + 0.25 = 1.25$ in. All threaded.

From Table 8-1, $A_t = 0.141 \text{ 9 in}^2$. The bolt stiffness is $k_b = A_t E / l = 0.141 \text{ 9(30)/0.75} = 5.676 \text{ Mlbf/in}$

Similar to Fig. 8-21, we have three frusta.

Top frusta, steel: t = l / 2 = 0.375 in, d = 0.5 in, D = 0.75 in, E = 30 Mpsi

$$k_{1} = \frac{0.5774\pi (30)0.5}{\ln \frac{\left[1.155(0.375) + 0.75 - 0.5\right](0.75 + 0.5)}{\left[1.155(0.375) + 0.75 + 0.5\right](0.75 - 0.5)}} = 38.45 \text{ Mlbf/in}$$

Middle frusta, steel: t = 0.5 - 0.375 = 0.125 in, d = 0.5 in,

 $D = 0.75 + 2(0.75 - 0.5) \text{ tan } 30^{\circ} = 1.039 \text{ in, } E = 30 \text{ Mpsi.}$

Eq. (8-20) $\Rightarrow k_2 = 184.3 \text{ Mlbf/in}$

Lower frusta, cast iron: t = 0.75 - 0.5 = 0.25 in, d = 0.5 in, D = 0.75 in, E = 14.5 Mpsi. Eq. (8-20) $\Rightarrow k_3 = 23.49$ Mlbf/in

Eq. (8-18),
$$k_m = (1/38.45 + 1/184.3 + 1/23.49)^{-1} = 13.51 \text{ Mlbf/in}$$

 $C = k_b / (k_b + k_m) = 5.676 / (5.676 + 13.51) = 0.296$

Table 8-9, $S_p = 85$ kpsi. For a non-permanent connection, using Eqs. (8-31) and (8-32)

$$F_i = 0.75 A_t S_p = 0.75(0.141 9)(85) = 9.05 \text{ kips}$$

The total external load is $P_{\text{total}} = p_g A_g$, where A_g is the effective area of the cylinder, based on the effective sealing diameter of 3.5 in. The external load per bolt is $P = P_{\text{total}} / N$. Thus

$$P = [1.500\pi(3.5^2)/4](10^{-3})/10 = 1.443 \text{ kips/bolt}$$

Yielding factor of safety, Eq. (8-28)

$$n_p = \frac{S_p A_t}{CP + F_s} = \frac{85(0.1419)}{0.296(1.443) + 9.05} = 1.27$$
 Ans.

Overload factor of safety, Eq. (8-29)

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{85(0.1419) - 9.05}{0.296(1.443)} = 7.05$$
 Ans.

Separation factor of safety, Eq. (8-30)

$$n_0 = \frac{F_i}{P(1-C)} = \frac{9.05}{1.443(1-0.296)} = 8.91$$
 Ans.

8-39 Instructors: See note preceding Prob. 8-33.

From Table 8-7, $h = t_1 = 20 \text{ mm}$ For $t_2 > d$, l = h + d/2 = 20 + 10/2 = 25 mm $L \ge h + 1.5 d = 20 + 1.5(10) = 35 \text{ mm}$. Let L = 35 mm $L_T = 2d + 6 = 2(10) + 6 = 26 \text{ mm}$ $l_d = L - L_T = 35 - 26 = 9 \text{ mm}$ $l_t = l - l_d = 25 - 9 = 16 \text{ mm}$

From Table 8-1, $A_t = 58.0 \text{ mm}^2$. $A_d = \pi (10^2)/4 = 78.5 \text{ mm}^2$ Eq. (8-17),

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{78.5(58.0)207}{78.5(16) + 58.0(9)} = 530.1 \text{ MN/m}$$

Similar to Fig. 8-21, we have three frusta.

Top frusta, steel: t = l/2 = 12.5 mm, d = 10 mm, D = 15 mm, E = 207 GPa. Eq. (8-20)

$$k_{1} = \frac{0.5774\pi (207)10}{\ln \left[1.155 (12.5) + 15 - 10 \right] (15 + 10)} = 4 \ 163 \ \text{MN/m}$$
$$1 = \frac{1.155 (12.5) + 15 - 10}{\left[1.155 (12.5) + 15 + 10 \right] (15 - 10)} = 4 \ 163 \ \text{MN/m}$$

Middle frusta, steel: t = 20 - 12.5 = 7.5 mm, d = 10 mm, D = 15 + 2(12.5 - 7.5) tan $30^{\circ} = 20.77$ mm, E = 207 GPa. Eq. (8-20) $\implies k_2 = 10$ 975 MN/m

Lower frusta, cast iron: t = 25 - 20 = 5 mm, d = 10 mm, D = 15 mm, E = 100 GPa (see Table 8-8). Eq. (8-20) $\Rightarrow k_3 = 3$ 239 MN/m

Eq. (8-18),
$$k_m = (1/4\ 163 + 1/10\ 975 + 1/3\ 239)^{-1} = 1\ 562\ \text{MN/m}$$

 $C = k_b / (k_b + k_m) = 530.1/(530.1 + 1\ 562) = 0.253$

Table 8-11: $S_p = 830$ MPa. For a non-permanent connection, using Eqs. (8-31) and (8-32)

$$F_i = 0.75 A_t S_p = 0.75(58.0)(830)10^{-3} = 36.1 \text{ kN}$$

The total external load is $P_{\text{total}} = p_g A_g$, where A_g is the effective area of the cylinder, based on the effective sealing diameter of 0.8 m. The external load per bolt is $P = P_{\text{total}} / N$. Thus

$$P = [550\pi (0.8^2)/4]/36 = 7.679 \text{ kN/bolt}$$

Yielding factor of safety, Eq. (8-28)

$$n_p = \frac{S_p A_i}{CP + F_i} = \frac{830(58.0)10^{-3}}{0.253(7.679) + 36.1} = 1.27$$
 Ans.

Overload factor of safety, Eq. (8-29)

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{830(58.0)10^{-3} - 36.1}{0.253(7.679)} = 6.20$$
 Ans.

Separation factor of safety, Eq. (8-30)

$$n_0 = \frac{F_i}{P(1-C)} = \frac{36.1}{7.679(1-0.253)} = 6.29$$
 Ans.

8-40 Instructors: See note preceding Prob. 8-33.

From Table 8-7, $h = t_1 = 0.375$ in For $t_2 > d$, l = h + d/2 = 0.375 + 0.4375/2 = 0.59375 in $L \ge h + 1.5 d = 0.375 + 1.5(0.4375) = 1.031$ in. Round up to L = 1.25 in $L_T = 2d + 0.25 = 2(0.4375) + 0.25 = 1.125$ in $l_d = L - L_T = 1.25 - 1.125 = 0.125$ $l_t = l - l_d = 0.59375 - 0.125 = 0.46875$ in

 $A_d = \pi (7/16)^2 / 4 = 0.150 \text{ 3 in}^2$, Table 8-2: $A_t = 0.106 \text{ 3 in}^2$

Eq. (8-17),

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.150 \ 3(0.106 \ 3)30}{0.150 \ 3(0.46875) + 0.106 \ 3(0.125)} = 5.724 \ \text{Mlbf/in}$$

Similar to Fig. 8-21, we have three frusta.

Top frusta, steel: t = l/2 = 0.296875 in, d = 0.4375 in, D = 0.65625 in, E = 30 Mpsi

$$k_{1} = \frac{0.5774\pi (30)0.4375}{\ln \left[\frac{1.155(0.296875) + 0.656255 - 0.4375}{\left[1.155(0.296875) + 0.75 + 0.656255 \right] \left(0.75 + 0.656255 \right)} = 35.52 \text{ Mlbf/in}$$

Middle frusta, steel: t = 0.375 - 0.296875 = 0.078125 in, d = 0.4375 in, D = 0.65625 + 2(0.59375 - 0.375) tan $30^{\circ} = 0.9088$ in, E = 30 Mpsi. Eq. (8-20) $\implies k_2 = 215.8$ Mlbf/in

Lower frusta, cast iron: t = 0.59375 - 0.375 = 0.21875 in, d = 0.4375 in, D = 0.65625 in, E = 14.5 Mpsi. Eq. (8-20) $\Rightarrow k_3 = 20.55$ Mlbf/in

Eq. (8-18), $k_m = (1/35.52 + 1/215.8 + 1/20.55)^{-1} = 12.28 \text{ Mlbf/in}$

$$C = k_b / (k_b + k_m) = 5.724/(5.724 + 12.28) = 0.318$$

Table 8-9, $S_p = 120$ kpsi. For a non-permanent connection, using Eqs. (8-31) and (8-32)

$$F_i = 0.75 A_t S_p = 0.75(0.106 3)(120) = 9.57 \text{ kips}$$

The total external load is $P_{\text{total}} = p_g A_g$, where A_g is the effective area of the cylinder, based on the effective sealing diameter of 3.25 in. The external load per bolt is $P = P_{\text{total}}/N$. Thus

$$P = [1\ 200\pi(3.25^2)/4](10^{-3})/8 = 1.244 \text{ kips/bolt}$$

Yielding factor of safety, Eq. (8-28)

$$n_p = \frac{S_p A_i}{CP + F_i} = \frac{120(0.1063)}{0.318(1.244) + 9.57} = 1.28$$
 Ans.

Overload factor of safety, Eq. (8-29)

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{120(0.1063) - 9.57}{0.318(1.244)} = 8.05$$
 Ans.

Separation factor of safety, Eq. (8-30)

$$n_0 = \frac{F_i}{P(1-C)} = \frac{9.57}{1.244(1-0.318)} = 11.3$$
 Ans.

8-41 Instructors: See note preceding Prob. 8-33.

This is a design problem and there is no closed-form solution path or a unique solution. What is presented here is one possible iterative approach. We will demonstrate this with an example.

- 1. Select the diameter, d. For this example, let d = 10 mm. Using Eq. (8-20) on members, and combining using Eq. (8-18), yields $k_m = 1$ 141 MN/m (see Prob. 8-33 for method of calculation.
- 2. Look up the nut height in Table A-31. For the example, H = 8.4 mm. From this, L is rounded up from the calculation of l + H = 40 + 8.4 = 48.4 mm to 50 mm. Next, calculations are made for $L_T = 2(10) + 6 = 26$ mm, $l_d = 50 26 = 24$ mm, $l_t = 40 24 = 16$ mm. From step 1, $A_d = \pi (10^2)/4 = 78.54$ mm². Next, from Table 8-1, $A_t = 78.54$ mm². From Eq. (8-17), $k_b = 356$ MN/m. Finally, from Eq. (f), p. 428, C = 0.238.

3. From Prob. 8-33, the bolt circle diameter is E = 200 mm. Substituting this for D_b in Eq. (8-34), the number of bolts are

$$N = \frac{\pi D_b}{4d} = \frac{\pi (200)}{4(10)} = 15.7$$

Rounding this up gives N = 16.

- 4. Next, select a grade bolt. Based on the solution to Prob. 8-33, the strength of ISO 9.8 was so high to give very large factors of safety for overload and separation. Try ISO 4.6 with $S_p = 225$ MPa. From Eqs. (8-31) and (8-32) for a non-permanent connection, $F_i = 9.79$ kN.
- 5. The external load requirement per bolt is $P = 1.15 \, p_g \, A_g/N$, where from Prob 8-33, $p_g = 6 \, \text{MPa}$, and $A_g = \pi (100^2)/4$. This gives $P = 3.39 \, \text{kN/bolt}$.
- 6. Using Eqs. (8-28) to (8-30) yield $n_p = 1.23$, $n_L = 4.05$, and $n_0 = 3.79$.

Steps 1 - 6 can be easily implemented on a spreadsheet with lookup tables for the tables used from the text. The results for four bolt sizes are shown below. The dimension of each term is consistent with the example given above.

d	k_m	Н	L	L_T	l_d	l_t	A_d	A_t	k_b
8	854	6.8	50	22	28	12	50.26	36.6	233.9
10	1141	8.4	50	26	24	16	78.54	58	356
12	1456	10.8	55	30	25	15	113.1	84.3	518.8
14	1950	12.8	55	34	21	19	153.9	115	686.3

d	С	N	S_p	F_i	P	n_p	n_L	n_0
8	0.215	20	225	6.18	2.71	1.22	3.53	2.90
10	0.238	16	225	9.79	3.39	1.23	4.05	3.79
12	0.263	13*	225	14.23	4.17	1.24	4.33	4.63
14	0.276	12	225	19.41	4.52	1.25	5.19	5.94

^{*}Rounded down from 13.08997, so spacing is slightly greater than four diameters.

Any one of the solutions is acceptable. A decision-maker might be cost such as $N \times \text{cost/bolt}$, and/or $N \times \text{cost}$ per hole, etc.

8-42 Instructors: See note preceding Prob. 8-33.

This is a design problem and there is no closed-form solution path or a unique solution. What is presented here is one possible iterative approach. We will demonstrate this with an example.

- 1. Select the diameter, d. For this example, let d = 0.5 in. Using Eq. (8-20) on three frusta (see Prob. 8-34 solution), and combining using Eq. (8-19), yields $k_m = 10.10$ Mlbf/in.
- 2. Look up the nut height in Table A-31. For the example, H = 0.4375 in. From this, L is rounded up from the calculation of l + H = 1.125 + 0.4375 = 1.5625 in to 1.75 in. Next, calculations are made for $L_T = 2(0.5) + 0.25 = 1.25$ in, $l_d = 1.75 1.25 = 0.5$ in, $l_t = 1.125 0.5 = 0.625$ in. From step 1, $A_d = \pi (0.5^2)/4 = 0.1963$ in. Next, from Table 8-1, $A_t = 0.1419$ in. From Eq. (8-17), $k_b = 4.316$ Mlbf/in. Finally, from Eq. (f), p. 428, C = 0.299.
- 3. From Prob. 8-34, the bolt circle diameter is E=6 in. Substituting this for D_b in Eq. (8-34), for the number of bolts

$$N = \frac{\pi D_b}{4d} = \frac{\pi (6)}{4(0.5)} = 9.425$$

Rounding this up gives N = 10.

- 4. Next, select a grade bolt. Based on the solution to Prob. 8-34, the strength of SAE grade 5 was adequate. Use this with $S_p = 85$ kpsi. From Eqs. (8-31) and (8-32) for a non-permanent connection, $F_i = 9.046$ kips.
- 5. The external load requirement per bolt is $P = 1.15 \, p_g \, A_g/N$, where from Prob 8-34, $p_g = 1\,500$ psi, and $A_g = \pi (3.5^2)/4$. This gives P = 1.660 kips/bolt.
- 6. Using Eqs. (8-28) to (8-30) yield $n_p = 1.26$, $n_L = 6.07$, and $n_0 = 7.78$.

d	k_m	Н	L	L_T	l_d	l_t	A_d	A_t	k_b
0.375	6.75	0.3281	1.5	1	0.5	0.625	0.1104	0.0775	2.383
0.4375	9.17	0.375	1.5	1.125	0.375	0.75	0.1503	0.1063	3.141
0.5	10.10	0.4375	1.75	1.25	0.5	0.625	0.1963	0.1419	4.316
0.5625	11.98	0.4844	1.75	1.375	0.375	0.75	0.2485	0.182	5.329

	d	C	N	S_p	F_{i}	P	n_p	n_L	n_0
0	.375	0.261	13	85	4.941	1.277	1.25	4.95	5.24
0.	4375	0.273	11	85	6.777	1.509	1.26	5.48	6.18
	0.5	0.299	10	85	9.046	1.660	1.26	6.07	7.78
0.	5625	0.308	9	85	11.6	1.844	1.27	6.81	9.09

Any one of the solutions is acceptable. A decision-maker might be cost such as $N \times \text{cost/bolt}$, and/or $N \times \text{cost}$ per hole, etc.

8-43 Instructors: See note preceding Prob. 8-33.

This is a design problem and there is no closed-form solution path or a unique solution. What is presented here is one possible iterative approach. We will demonstrate this with an example.

- 1. Select the diameter, d. For this example, let d = 10 mm. Using Eq. (8-20) on three frusta (see Prob. 8-35 solution), and combining using Eq. (8-19), yields $k_m = 1$ 087 MN/m.
- 2. Look up the nut height in Table A-31. For the example, H=8.4 mm. From this, L is rounded up from the calculation of l+H=45+8.4=53.4 mm to 55 mm. Next, calculations are made for $L_T=2(10)+6=26$ mm, $l_d=55-26=29$ mm, $l_t=45-29=16$ mm. From step 1, $A_d=\pi(10^2)/4=78.54$ mm². Next, from Table 8-1, $A_t=58.0$ mm². From Eq. (8-17), $k_b=320.9$ MN/m. Finally, from Eq. (f), p. 428, C=0.228. 3. From Prob. 8-35, the bolt circle diameter is E=1000 mm. Substituting this for D_b in

3. From Prob. 8-35, the bolt circle diameter is E = 1000 mm. Substituting this for D_b in Eq. (8-34), for the number of bolts

$$N = \frac{\pi D_b}{4d} = \frac{\pi (1000)}{4(10)} = 78.5$$

Rounding this up gives N = 79. A rather large number, since the bolt circle diameter, E is so large. Try larger bolts.

- 4. Next, select a grade bolt. Based on the solution to Prob. 8-35, the strength of ISO 9.8 was so high to give very large factors of safety for overload and separation. Try ISO 5.8 with $S_p = 380$ MPa. From Eqs. (8-31) and (8-32) for a non-permanent connection, $F_i = 16.53$ kN.
- 5. The external load requirement per bolt is $P = 1.15 p_g A_g/N$, where from Prob 8-35, $p_g = 0.550$ MPa, and $A_g = \pi (800^2)/4$. This gives P = 4.024 kN/bolt.
- 6. Using Eqs. (8-28) to (8-30) yield $n_p = 1.26$, $n_L = 6.01$, and $n_0 = 5.32$.

Steps 1 - 6 can be easily implemented on a spreadsheet with lookup tables for the tables used from the text. The results for three bolt sizes are shown below. The dimension of each term is consistent with the example given above.

d	k_m	Н	L	L_T	l_d	l_t	A_d	A_t	k_b
10	1087	8.4	55	26	29	16	78.54	58	320.9
20	3055	18	65	46	19	26	314.2	245	1242
36	6725	31	80	78	2	43	1018	817	3791

d	С	N	S_p	F_i	P	n_p	n_L	n_0
10	0.228	79	380	16.53	4.024	1.26	6.01	5.32
20	0.308	40	380	69.83	7.948	1.29	9.5	12.7
36	0.361	22	380	232.8	14.45	1.3	14.9	25.2

A large range is presented here. Any one of the solutions is acceptable. A decision-maker might be cost such as $N \times \text{cost/bolt}$, and/or $N \times \text{cost}$ per hole, etc.

8-44 Instructors: See note preceding Prob. 8-33.

This is a design problem and there is no closed-form solution path or a unique solution. What is presented here is one possible iterative approach. We will demonstrate this with an example.

- 1. Select the diameter, d. For this example, let d = 0.375 in. Using Eq. (8-20) on three frusta (see Prob. 8-36 solution), and combining using Eq. (8-19), yields $k_m = 7.42$ Mlbf/in.
- 2. Look up the nut height in Table A-31. For the example, H = 0.3281 in. From this, $L \ge l + H = 0.875 + 0.3281 = 1.2031$ in. Rounding up, L = 1.25. Next, calculations are made for $L_T = 2(0.375) + 0.25 = 1$ in, $l_d = 1.25 1 = 0.25$ in, $l_t = 0.875 0.25 = 0.625$ in. From step 1, $A_d = \pi (0.375^2)/4 = 0.1104$ in². Next, from Table 8-1, $A_t = 0.0775$ in². From Eq. (8-17), $k_b = 2.905$ Mlbf/in. Finally, from Eq. (f), p. 428, C = 0.263.
- 3. From Prob. 8-36, the bolt circle diameter is E = 6 in. Substituting this for D_b in Eq. (8-34), for the number of bolts

$$N = \frac{\pi D_b}{4d} = \frac{\pi (6)}{4(0.375)} = 12.6$$

Rounding this up gives N = 13.

- 4. Next, select a grade bolt. Based on the solution to Prob. 8-36, the strength of SAE grade 8 seemed high for overload and separation. Try SAE grade 5 with $S_p = 85$ kpsi. From Eqs. (8-31) and (8-32) for a non-permanent connection, $F_i = 4.941$ kips.
- 5. The external load requirement per bolt is $P = 1.15 \, p_g \, A_g/N$, where from Prob 8-34, $p_g = 1 \, 200 \, \text{psi}$, and $A_g = \pi \, (3.25^2)/4$. This gives $P = 0.881 \, \text{kips/bolt}$.
- 6. Using Eqs. (8-28) to (8-30) yield $n_p = 1.27$, $n_L = 6.65$, and $n_0 = 7.81$.

Steps 1 - 6 can be easily implemented on a spreadsheet with lookup tables for the tables used from the text. For this solution we only looked at one bolt size, $\frac{3}{8}$ -16, but evaluated changing the bolt grade. The results for four bolt grades are shown below. The dimension of each term is consistent with the example given above.

d	k_m	Н	L	L_T	l_d	l_t	A_d	A_t	k_b
0.375	7.42	0.3281	1.25	1	0.25	0.625	0.1104	0.0775	2.905

d	C	N	SAE grade	S_p	F_i	P	n_p	n_L	n_0
0.375	0.281	13	1	33	1.918	0.881	1.18	2.58	3.03
0.375	0.281	13	2	55	3.197	0.881	1.24	4.30	5.05
0.375	0.281	13	4	65	3.778	0.881	1.25	5.08	5.97
0.375	0.281	13	5	85	4.941	0.881	1.27	6.65	7.81

Note that changing the bolt grade only affects S_p , F_i , n_p , n_L , and n_0 . Any one of the solutions is acceptable, especially the lowest grade bolt.

8-45 (a)
$$F'_b = RF'_{b,\text{max}} \sin \theta$$

Half of the external moment is contributed by the line load in the interval $0 \le \theta \le \pi$

$$\frac{M}{2} = \int_0^{\pi} F_b' R^2 \sin\theta \, d\theta = \int_0^{\pi} F_{b,\text{max}}' R^2 \sin^2\theta \, d\theta$$

$$\frac{M}{2} = \frac{\pi}{2} F_{b,\text{max}}' R^2$$

from which $F'_{b,\text{max}} = \frac{M}{\pi R^2}$

$$F_{\text{max}} = \int_{\phi_1}^{\phi_2} F_b' R \sin \theta \, d\theta = \frac{M}{\pi R^2} \int_{\phi_1}^{\phi_2} R \sin \theta \, d\theta = \frac{M}{\pi R} (\cos \phi_1 - \cos \phi_2)$$

Noting $\phi_1 = 75^{\circ}$, $\phi_2 = 105^{\circ}$,

$$F_{\text{max}} = \frac{12\ 000}{\pi(8/2)}(\cos 75^{\circ} - \cos 105^{\circ}) = 494\ \text{lbf}$$
 Ans.

(b)
$$F_{\text{max}} = F'_{b,\text{max}} R \Delta \phi = \frac{M}{\pi R^2} (R) \left(\frac{2\pi}{N} \right) = \frac{2M}{RN}$$
$$F_{\text{max}} = \frac{2(12\ 000)}{(8/2)(12)} = 500\ \text{lbf} \quad Ans.$$

(c) $F = F_{\text{max}} \sin \theta$

$$M = 2 F_{\text{max}} R \left[(1) \sin^2 90^\circ + 2 \sin^2 60^\circ + 2 \sin^2 30^\circ + (1) \sin^2 (0) \right] = 6 F_{\text{max}} R$$

from which,

$$F_{\text{max}} = \frac{M}{6R} = \frac{12\ 000}{6(8/2)} = 500\ \text{lbf}$$
 Ans.

The simple general equation resulted from part (b)

$$F_{\text{max}} = \frac{2M}{RN}$$

8-46

(a) From Table 8-11, $S_p = 600$ MPa. From Table 8-1, $A_t = 353$ mm².

Eq. (8-31):
$$F_i = 0.9 A_i S_p = 0.9 (353) (600) (10^{-3}) = 190.6 \text{ kN}$$

Table 8-15: K = 0.18

Eq. (8-27):
$$T = K F_i d = 0.18(190.6)(24) = 823 \text{ N} \cdot \text{m}$$
 Ans.

(b) Washers: t = 4.6 mm, d = 24 mm, D = 1.5(24) = 36 mm, E = 207 GPa.

Eq. (8-20),

$$k_{1} = \frac{0.5774\pi (207) 24}{\ln \left[1.155 (4.6) + 36 - 24\right] (36 + 24)} = 31 990 \text{ MN/m}$$

$$\frac{11.155 (4.6) + 36 + 24}{11.155 (4.6) + 36 + 24} = 31 990 \text{ MN/m}$$

Cast iron: t = 20 mm, d = 24 mm, $D = 36 + 2(4.6) \tan 30^{\circ} = 41.31$ mm, E = 135 GPa. Eq. (8-20) $\Rightarrow k_2 = 10.785$ MN/m

Steel joist: t = 20 mm, d = 24 mm, D = 41.31 mm, E = 207 GPa. Eq. (8-20) $\implies k_3 = 16 537 \text{ MN/m}$

Eq. (8-18):
$$k_m = (2 / 31 990 + 1 / 10 785 + 1 / 16 537)^{-1} = 4 636 \text{ MN/m}$$

Bolt: l = 2(4.6) + 2(20) = 49.2 mm. Nut, Table A-31, H = 21.5 mm. L > 49.2 + 21.5 = 70.7 mm. From Table A-17, use L = 80 mm. From Eq. (8-14)

$$L_T = 2(24) + 6 = 54 \text{ mm}, l_d = 80 - 54 = 26 \text{ mm}, l_t = 49.2 - 26 = 23.2 \text{ mm}$$

From Table (8-1), $A_t = 353 \text{ mm}^2$, $A_d = \pi (24^2) / 4 = 452.4 \text{ mm}^2$

Eq. (8-17):

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{452.4(353)207}{452.4(23.2) + 353(26)} = 1680 \text{ MN/m}$$

$$C = k_b / (k_b + k_m) = 1680 / (1680 + 4636) = 0.266, S_p = 600 \text{ MPa}, F_i = 190.6 \text{ kN}, P = P_{\text{total}} / \text{N} = 18/4 = 4.5 \text{ kN}$$

Yield: From Eq. (8-28)

$$n_p = \frac{S_p A_t}{CP + F_i} = \frac{600(353)10^{-3}}{0.266(4.5) + 190.6} = 1.10$$
 Ans.

Load factor: From Eq. (8-29)

$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{600(353)10^{-3} - 190.6}{0.266(4.5)} = 17.7 \quad Ans.$$

Separation: From Eq. (8-30)

$$n_0 = \frac{F_i}{P(1-C)} = \frac{190.6}{4.5(1-0.266)} = 57.7$$
 Ans.

As was stated in the text, bolts are typically preloaded such that the yielding factor of safety is not much greater than unity which is the case for this problem. However, the other load factors indicate that the bolts are oversized for the external load.

8-47 (a) ISO M 20×2.5 grade 8.8 coarse pitch bolts, lubricated.

Table 8-2, $A_t = 245 \text{ mm}^2$ Table 8-11, $S_p = 600 \text{ MPa}$

 $F_i = 0.90 A_t S_p = 0.90(245)600(10^{-3}) = 132.3 \text{ kN}$

Table 8-15, K = 0.18

Eq. (8-27), $T = KF_i d = 0.18(132.3)20 = 476 \text{ N} \cdot \text{m}$ Ans.

(**b**) Table A-31, H = 18 mm, $L \ge L_G + H = 48 + 18 = 66$ mm. Round up to L = 80 mm per Table A-17.

$$L_T = 2d + 6 = 2(20) + 6 = 46 \text{ mm}$$

 $l_d = L - L_T = 80 - 46 = 34 \text{ mm}$
 $l_t = l - l_d = 48 - 34 = 14 \text{ mm}$

 $A_d = \pi (20^2) / 4 = 314.2 \text{ mm}^2,$

$$k_b = \frac{A_d A_l E}{A_d l_t + A l_d} = \frac{314.2(245)(207)}{314.2(14) + 245(34)} = 1251.9 \text{ MN/m}$$

Members: Since all members are steel use Eq. (8-22) with E=207 MPa, l=48 mm, d=20mm

$$k_{m} = \frac{0.5774\pi Ed}{2\ln\left(5\frac{0.5774l + 0.5d}{0.5774l + 2.5d}\right)} = \frac{0.5774\pi(207)20}{2\ln\left[5\frac{0.5774(48) + 0.5(20)}{0.5774(48) + 2.5(20)}\right]} = 4236 \text{ MN/m}$$

$$C = \frac{k_b}{k_b + k_m} = \frac{1251.9}{1251.9 + 4236} = 0.228$$

 $P = P_{\text{total}} / N = 40/2 = 20 \text{ kN},$

Yield: From Eq. (8-28)

$$n_p = \frac{S_p A_i}{CP + F_i} = \frac{600(245)10^{-3}}{0.228(20) + 132.3} = 1.07$$
 Ans.

Load factor: From Eq. (8-29)

$$n_L = \frac{S_p A_i - F_i}{CP} = \frac{600(245)10^{-3} - 132.3}{0.228(20)} = 3.22 \quad Ans.$$

Separation: From Eq. (8-30)

$$n_0 = \frac{F_i}{P(1-C)} = \frac{132.3}{20(1-0.228)} = 8.57$$
 Ans.

8-48 From Prob. 8-29 solution, $P_{\text{max}} = 13.33 \text{ kips}$, C = 0.2, $F_i = 12.77 \text{ kips}$, $A_t = 0.141 \text{ 9 in}^2$

$$\sigma_i = \frac{F_i}{A_i} = \frac{12.77}{0.1419} = 90.0 \text{ kpsi}$$

Eq. (8-39),
$$\sigma_a = \frac{CP}{2A_t} = \frac{0.2(13.33)}{2(0.1419)} = 9.39 \text{ kpsi}$$

Eq. (8-41),
$$\sigma_m = \sigma_a + \sigma_i = 9.39 + 90.0 = 99.39 \text{ kpsi}$$

(a) Goodman Eq. (8-45) for grade 8 bolts, $S_e = 23.2$ kpsi (Table 8-17), $S_{ut} = 150$ kpsi (Table 8-9)

$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{\sigma_a \left(S_{ut} + S_e \right)} = \frac{23.2 \left(150 - 90.0 \right)}{9.39 \left(150 + 23.2 \right)} = 0.856$$
 Ans

(b) Gerber Eq. (8-46)

$$\begin{split} n_f &= \frac{1}{2\sigma_a S_e} \left[S_{uu} \sqrt{S_{uu}^2 + 4S_e \left(S_e + \sigma_i \right)} - S_{uu}^2 - 2\sigma_i S_e \right] \\ &= \frac{1}{2(9.39)23.2} \left[150\sqrt{150^2 + 4(23.2)(23.2 + 90.0)} - 150^2 - 2(90.0)23.2 \right] = 1.32 \quad Ans. \end{split}$$

(c) ASME-elliptic Eq. (8-47) with $S_p = 120$ kpsi (Table 8-9)

$$\begin{split} n_f &= \frac{S_e}{\sigma_a \left(S_p^2 + S_e^2\right)} \left(S_p \sqrt{S_p^2 + S_e^2 - \sigma_i^2} - \sigma_i S_e\right) \\ &= \frac{23.2}{9.39 \left(120^2 + 23.2^2\right)} \left[120\sqrt{120^2 + 23.2^2 - 90^2} - 90(23.2)\right] = 1.30 \quad Ans. \end{split}$$

8-49 Attention to the Instructor. Part (d) requires the determination of the endurance strength, S_e , of a class 5.8 bolt. Table 8-17 does not provide this and the student will be required to estimate it by other means [see the solution of part (d)].

Per bolt,
$$P_{b\text{max}} = 60/8 = 7.5 \text{ kN}, P_{b\text{min}} = 20/8 = 2.5 \text{ kN}$$

$$C = \frac{k_b}{k_b + k_m} = \frac{1}{1 + 2.6} = 0.278$$

(a) Table 8-1, $A_t = 20.1 \text{ mm}^2$; Table 8-11, $S_p = 380 \text{ MPa}$ Eqs. (8-31) and (8-32), $F_i = 0.75 A_t S_p = 0.75(20.1)380(10^{-3}) = 5.73 \text{ kN}$

Yield, Eq. (8-28),
$$n_p = \frac{S_p A_t}{CP + F} = \frac{380(20.1)10^{-3}}{0.278(7.5) + 5.73} = 0.98$$
 Ans

(b) Overload, Eq. (8-29),
$$n_L = \frac{S_p A_t - F_i}{CP} = \frac{380(20.1)10^{-3} - 5.73}{0.278(7.5)} = 0.915 \quad Ans.$$

(c) Separation, Eq. (8-30),
$$n_0 = \frac{F_i}{P(1-C)} = \frac{5.73}{7.5(1-0.278)} = 1.06$$
 Ans.

(**d**) Goodman, Eq. (8-35),
$$\sigma_a = \frac{C(P_{b\text{max}} - P_{b\text{min}})}{2A_t} = \frac{0.278(7.5 - 2.5)10^3}{2(20.1)} = 34.6 \text{ MPa}$$

Eq. (8-36),
$$\sigma_m = \frac{C(P_{b\text{max}} + P_{b\text{min}})}{2A_t} + \frac{F_i}{A_t} = \frac{0.278(7.5 + 2.5)10^3}{2(20.1)} + \frac{5.73(10^3)}{20.1} = 354.2 \text{ MPa}$$

Table 8-11, $S_{ut} = 520 \text{ MPa}$, $\sigma_i = F_i / A_t = 5.73(10^3)/20.1 = 285 \text{ MPa}$

We have a problem for S_e . Table 8-17 does not list S_e for class 5.8 bolts. Here, we will estimate S_e using the methods of Chapter 6. Estimate S'_e from the,

Eq. (6-8), p. 290,
$$S'_e = 0.5S_{ut} = 0.5(520) = 260 \text{ MPa}.$$

Table 6-2, p. 296,
$$a = 4.51, b = -0.265$$

Eq. (6-19), p. 295,
$$k_a = aS_{ut}^b = 4.51(520^{-0.265}) = 0.860$$

Eq. (6-21), p. 296,
$$k_b = 1$$

Eq. (6-26), p. 298,
$$k_c = 0.85$$

The fatigue stress-concentration factor, from Table 8-16, is $K_f = 2.2$. For simple axial loading and infinite-life it is acceptable to reduce the endurance limit by K_f and use the nominal stresses in the stress/strength/design factor equations. Thus,

Eq. (6-18), p. 295,
$$S_e = k_a k_b k_c S'_e / K_f = 0.86(1)0.85(260) / 2.2 = 86.4 \text{ MPa}$$

Eq. (8-38),
$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{S_{ut} \sigma_a + S_e \left(\sigma_m - \sigma_i \right)} = \frac{86.4 \left(520 - 285 \right)}{520 \left(34.6 \right) + 86.4 \left(354.2 - 285 \right)} = 0.847 \qquad Ans.$$

It is obvious from the various answers obtained, the bolted assembly is undersized. This can be rectified by a one or more of the following: more bolts, larger bolts, higher class bolts.

8-50 Per bolt,
$$P_{b\text{max}} = P_{\text{max}}/N = 80/10 = 8 \text{ kips}, P_{b\text{min}} = P_{\text{min}}/N = 20/10 = 2 \text{ kips}$$

 $C = k_b / (k_b + k_m) = 4/(4 + 12) = 0.25$

(a) Table 8-2, $A_t = 0.141 \text{ 9 in}^2$, Table 8-9, $S_p = 120 \text{ kpsi}$ and $S_{ut} = 150 \text{ kpsi}$ Table 8-17, $S_e = 23.2 \text{ kpsi}$

Eqs. (8-31) and (8-32), $F_i = 0.75 A_t S_p \implies \sigma_i = F_i / A_t = 0.75 S_p = 0.75(120) = 90 \text{ kpsi}$

Eq. (8-35),
$$\sigma_a = \frac{C(P_{b \max} - P_{b \min})}{2A_t} = \frac{0.25(8-2)}{2(0.1419)} = 5.29 \text{ kpsi}$$

Eq. (8-36),
$$\sigma_m = \frac{C(P_{b\text{max}} + P_{b\text{min}})}{2A_t} + \sigma_i = \frac{0.25(8+2)}{2(0.1419)} + 90 = 98.81 \text{ kpsi}$$

Eq. (8-38),

$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{S_{ut} \sigma_a + S_e \left(\sigma_m - \sigma_i \right)} = \frac{23.2 \left(150 - 90 \right)}{150 \left(5.29 \right) + 23.2 \left(98.81 - 90 \right)} = 1.39 \qquad Ans.$$

8-51 Instructors: See note preceding Prob. 8-33.

From Prob. 8-33, C = 0.263, $P_{\text{max}} = 4.712 \text{ kN} / \text{bolt}$, $F_i = 41.1 \text{ kN}$, $S_p = 650 \text{ MPa}$, and $A_t = 84.3 \text{ mm}^2$

Eq. (8-39):
$$\sigma_i = 0.75 S_p = 0.75(650) = 487.5 \text{ MPa}$$

$$\sigma_a = \frac{CP}{2A} = \frac{0.263(4.712)10^3}{2(84.3)} = 7.350 \text{ MPa}$$

Eq. (8-40)
$$\sigma_m = \frac{CP}{2A_i} + \frac{F_i}{A_i} = 7.350 + 487.5 = 494.9 \text{ MPa}$$

(a) Goodman: From Table 8-11, $S_{ut} = 900$ MPa, and from Table 8-17, $S_e = 140$ MPa

Eq. (8-45):
$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{\sigma_a \left(S_{ut} + S_e \right)} = \frac{140 \left(900 - 487.5 \right)}{7.350 \left(900 + 140 \right)} = 7.55 \qquad Ans.$$

(b) Gerber:

Eq. (8-46):

$$n_f = \frac{1}{2\sigma_a S_e} \left[S_{ut} \sqrt{S_{ut}^2 + 4S_e (S_e + \sigma_i)} - S_{ut}^2 - 2\sigma_i S_e \right]$$

$$= \frac{1}{2(7.350)140} \left[900\sqrt{900^2 + 4(140)(140 + 487.5)} - 900^2 - 2(487.5)(140) \right]$$

$$= 11.4 \qquad Ans.$$

(c) ASME-elliptic:

Eq. (8-47):

$$n_{f} = \frac{S_{e}}{\sigma_{a} \left(S_{p}^{2} + S_{e}^{2}\right)} \left(S_{p} \sqrt{S_{p}^{2} + S_{e}^{2} - \sigma_{i}^{2}} - \sigma_{i} S_{e}\right)$$

$$= \frac{140}{7.350 \left(650^{2} + 140^{2}\right)} \left[650 \sqrt{650^{2} + 140^{2} - 487.5^{2}} - 487.5 \left(140\right)\right] = 9.73 \quad Ans.$$

8-52 Instructors: See note preceding Prob. 8-33.

From Prob. 8-34, C = 0.299, $P_{\text{max}} = 1.443$ kips/bolt, $F_i = 9.05$ kips, $S_p = 85$ kpsi, and $A_t = 0.141$ 9 in²

$$\sigma_i = 0.75S_p = 0.75(85) = 63.75 \text{ kpsi}$$
Eq. (8-37):
$$\sigma_a = \frac{CP}{2A_i} = \frac{0.299(1.443)}{2(0.1419)} = 1.520 \text{ kpsi}$$

Eq. (8-38)
$$\sigma_m = \frac{CP}{2A_i} + \sigma_i = 1.520 + 63.75 = 65.27 \text{ kpsi}$$

(a) Goodman: From Table 8-9, $S_{ut} = 120$ kpsi, and from Table 8-17, $S_e = 18.8$ kpsi

Eq. (8-45):
$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{\sigma_a \left(S_{ut} + S_e \right)} = \frac{18.8 \left(120 - 63.75 \right)}{1.520 \left(120 + 18.8 \right)} = 5.01 \qquad Ans.$$

(b) Gerber:

Eq. (8-46):

$$n_{f} = \frac{1}{2\sigma_{a}S_{e}} \left[S_{ut} \sqrt{S_{ut}^{2} + 4S_{e} (S_{e} + \sigma_{i})} - S_{ut}^{2} - 2\sigma_{i}S_{e} \right]$$

$$= \frac{1}{2(1.520)18.6} \left[120\sqrt{120^{2} + 4(18.6)(18.6 + 63.75)} - 120^{2} - 2(63.75)(18.6) \right]$$

$$= 7.45 \qquad Ans.$$

(c) ASME-elliptic:

Eq. (8-47):

$$n_f = \frac{S_e}{\sigma_a \left(S_p^2 + S_e^2\right)} \left(S_p \sqrt{S_p^2 + S_e^2 - \sigma_i^2} - \sigma_i S_e\right)$$

$$= \frac{18.6}{1.520 \left(85^2 + 18.6^2\right)} \left[85\sqrt{85^2 + 18.6^2 - 63.75^2} - 63.75(18.6)\right] = 6.22 \quad Ans.$$

8-53 Instructors: See note preceding Prob. 8-33.

From Prob. 8-35, C = 0.228, $P_{\text{max}} = 7.679$ kN/bolt, $F_i = 36.1$ kN, $S_p = 830$ MPa, and $A_t = 58.0 \text{ mm}^2$

Eq. (8-37):
$$\sigma_{a} = 0.75 S_{p} = 0.75(830) = 622.5 \text{ MPa}$$

$$\sigma_{a} = \frac{CP}{2A_{t}} = \frac{0.228(7.679)10^{3}}{2(58.0)} = 15.09 \text{ MPa}$$

Eq. (8-38)
$$\sigma_m = \frac{CP}{2A_i} + \sigma_i = 15.09 + 622.5 = 637.6 \text{ MPa}$$

(a) Goodman: From Table 8-11, $S_{ut} = 1040$ MPa, and from Table 8-17, $S_e = 162$ MPa

Eq. (8-45):
$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{\sigma_a \left(S_{ut} + S_e \right)} = \frac{162 \left(1040 - 622.5 \right)}{15.09 \left(1040 + 162 \right)} = 3.73 \quad Ans.$$

(b) Gerber:

Eq. (8-46):

$$n_{f} = \frac{1}{2\sigma_{a}S_{e}} \left[S_{ut} \sqrt{S_{ut}^{2} + 4S_{e} (S_{e} + \sigma_{i})} - S_{ut}^{2} - 2\sigma_{i}S_{e} \right]$$

$$=\frac{1}{2(15.09)162}\left[1040\sqrt{1040^2+4(162)(162+622.5)}-1040^2-2(622.5)(162)\right]$$

$$=5.74$$
 Ans.

(c) ASME-elliptic:

Eq. (8-47):

$$n_{f} = \frac{S_{e}}{\sigma_{a} \left(S_{p}^{2} + S_{e}^{2}\right)} \left(S_{p} \sqrt{S_{p}^{2} + S_{e}^{2} - \sigma_{i}^{2}} - \sigma_{i} S_{e}\right)$$

$$=\frac{162}{15.09(830^2+162^2)} \left[830\sqrt{830^2+162^2-622.5^2}-622.5(162)\right] = 5.62 \quad Ans.$$

8-54 Instructors: See note preceding Prob. 8-33.

From Prob. 8-36, C = 0.291, $P_{\text{max}} = 1.244$ kips/bolt, $F_i = 9.57$ kips, $S_p = 120$ kpsi, and $A_t = 0.106$ 3 in²

$$\sigma_i = 0.75 S_p = 0.75 (120) = 90 \text{ kpsi}$$

Eq. (8-37):
$$\sigma_a = \frac{CP}{2A_t} = \frac{0.291(1.244)}{2(0.1063)} = 1.703 \text{ kpsi}$$

Eq. (8-38)
$$\sigma_m = \frac{CP}{2A_i} + \sigma_i = 1.703 + 90 = 91.70 \text{ kpsi}$$

(a) Goodman: From Table 8-9, $S_{ut} = 150$ kpsi, and from Table 8-17, $S_e = 23.2$ kpsi

Eq. (8-45):
$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{\sigma_a \left(S_{ut} + S_e \right)} = \frac{23.2 \left(150 - 90 \right)}{1.703 \left(150 + 23.2 \right)} = 4.72 \quad Ans.$$

(b) Gerber:

Eq. (8-46):

$$n_{f} = \frac{1}{2\sigma_{a}S_{e}} \left[S_{ut} \sqrt{S_{ut}^{2} + 4S_{e}(S_{e} + \sigma_{i})} - S_{ut}^{2} - 2\sigma_{i}S_{e} \right]$$

$$= \frac{1}{2(1.703)23.2} \left[150\sqrt{150^{2} + 4(23.2)(23.2 + 90)} - 150^{2} - 2(90)(23.2) \right]$$

$$= 7.28 \qquad Ans.$$

(c) ASME-elliptic:

Eq. (8-47):

$$n_f = \frac{S_e}{\sigma_a \left(S_p^2 + S_e^2\right)} \left(S_p \sqrt{S_p^2 + S_e^2 - \sigma_i^2} - \sigma_i S_e\right)$$

$$= \frac{23.2}{1.703 \left(120^2 + 18.6^2\right)} \left[120\sqrt{120^2 + 23.2^2 - 90^2} - 90(23.2)\right] = 7.24 \quad Ans.$$

8-55 Instructors: See note preceding Prob. 8-33.

From Prob. 8-51, C = 0.263, $S_e = 140$ MPa, $S_{ut} = 900$ MPa, $A_t = 84.4$ mm², $\sigma_i = 487.5$ MPa, and $P_{\text{max}} = 4.712$ kN.

$$P_{\min} = P_{\max} / 2 = 4.712/2 = 2.356 \text{ kN}$$

Eq. (8-35):
$$\sigma_a = \frac{C(P_{\text{max}} - P_{\text{min}})}{2A_t} = \frac{0.263(4.712 - 2.356)10^3}{2(84.3)} = 3.675 \text{ MPa}$$

Eq. (8-36):

$$\sigma_m = \frac{C(P_{\text{max}} + P_{\text{min}})}{2A_t} + \sigma_i$$

$$= \frac{0.263(4.712 + 2.356)10^3}{2(84.3)} + 487.5 = 498.5 \text{ MPa}$$

Eq. (8-38):

$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{S_{ut} \sigma_a + S_e \left(\sigma_m - \sigma_i \right)} = \frac{140 \left(900 - 487.5 \right)}{900 \left(3.675 \right) + 140 \left(498.5 - 487.5 \right)} = 11.9$$
 Ans.

Shigley's MED, 10th edition

8-56 Instructors: See note preceding Prob. 8-33.

From Prob. 8-52, C = 0.299, $S_e = 18.8$ kpsi, $S_{ut} = 120$ kpsi, $A_t = 0.141$ 9 in², $\sigma_i = 63.75$ kpsi, and $P_{\text{max}} = 1.443$ kips

$$P_{\min} = P_{\max} / 2 = 1.443/2 = 0.722 \text{ kips}$$

Eq. (8-35):
$$\sigma_a = \frac{C(P_{\text{max}} - P_{\text{min}})}{2A_t} = \frac{0.299(1.443 - 0.722)}{2(0.1419)} = 0.760 \text{ kpsi}$$

Eq. (8-36):

$$\sigma_m = \frac{C(P_{\text{max}} + P_{\text{min}})}{2A_t} + \sigma_i$$

$$= \frac{0.299(1.443 + 0.722)}{2(0.1419)} + 63.75 = 66.03 \text{ kpsi}$$

Eq. (8-38):

$$n_f = \frac{S_e(S_{ut} - \sigma_i)}{S_{ut}\sigma_a + S_e(\sigma_m - \sigma_i)} = \frac{18.8(120 - 63.75)}{120(0.760) + 18.8(66.03 - 63.75)} = 7.89$$
 Ans.

8-57 Instructors: See note preceding Prob. 8-33.

From Prob. 8-53, C = 0.228, $S_e = 162$ MPa, $S_{ut} = 1040$ MPa, $A_t = 58.0$ mm², $\sigma_i = 622.5$ MPa, and $P_{\text{max}} = 7.679$ kN.

$$P_{\text{min}} = P_{\text{max}} / 2 = 7.679/2 = 3.840 \text{ kN}$$

Eq. (8-35):
$$\sigma_a = \frac{C(P_{\text{max}} - P_{\text{min}})}{2A_t} = \frac{0.228(7.679 - 3.840)10^3}{2(58.0)} = 7.546 \text{ MPa}$$

Eq. (8-36):

$$\sigma_m = \frac{C(P_{\text{max}} + P_{\text{min}})}{2A} + \sigma_i$$

$$= \frac{0.228(7.679 + 3.840)10^3}{2(58.0)} + 622.5 = 645.1 \text{ MPa}$$

Eq. (8-38):

$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{S_{ut} \sigma_a + S_e \left(\sigma_m - \sigma_i \right)} = \frac{162 \left(1040 - 622.5 \right)}{1040 \left(7.546 \right) + 162 \left(645.1 - 622.5 \right)} = 5.88$$
 Ans.

8-58 Instructors: See note preceding Prob. 8-33.

From Prob. 8-54, C = 0.291, $S_e = 23.2$ kpsi, $S_{ut} = 150$ kpsi, $A_t = 0.106$ 3 in², $\sigma_i = 90$ kpsi, and $P_{\text{max}} = 1.244$ kips

$$P_{\text{min}} = P_{\text{max}} / 2 = 1.244 / 2 = 0.622 \text{ kips}$$

Eq. (8-35):
$$\sigma_a = \frac{C(P_{\text{max}} - P_{\text{min}})}{2A_t} = \frac{0.291(1.244 - 0.622)}{2(0.106 \text{ 3})} = 0.851 \text{ kpsi}$$

Eq. (8-36):

$$\sigma_m = \frac{C(P_{\text{max}} + P_{\text{min}})}{2A_t} + \sigma_i$$

$$= \frac{0.291(1.244 + 0.622)}{2(0.1063)} + 90 = 92.55 \text{ kpsi}$$

Eq. (8-38):

$$n_f = \frac{S_e(S_{ut} - \sigma_i)}{S_{ut}\sigma_a + S_e(\sigma_m - \sigma_i)} = \frac{23.2(150 - 90)}{150(0.851) + 23.2(92.55 - 90)} = 7.45$$
 Ans.

8-59 Let the repeatedly-applied load be designated as P. From Table A-22, $S_{ut} = 93.7$ kpsi. Referring to the Figure of Prob. 3-122, the following notation will be used for the radii of Section AA.

$$r_i = 1.5 \text{ in}, \quad r_o = 2.5 \text{ in}, \quad r_c = 2.0 \text{ in}$$

From Table 3-4, p. 135, with R = 0.5 in

$$r_n = \frac{R^2}{2(r_c - \sqrt{r_c^2 - R^2})} = \frac{0.5^2}{2(2 - \sqrt{2^2 - 0.5^2})} = 1.968 \ 246 \text{ in}$$

$$e = r_c - r_n = 2.0 - 1.968 \ 246 = 0.031 \ 754 \text{ in}$$

$$c_o = r_o - r_n = 2.5 - 1.968 \ 246 = 0.531 \ 754 \text{ in}$$

$$c_i = r_n - r_i = 1.968 \ 246 - 1.5 = 0.468 \ 246 \text{ in}$$

$$A = \pi(1^2) \ / \ 4 = 0.7854 \text{ in}^2$$

If *P* is the maximum load

$$M = Pr_c = 2P$$

$$\sigma_i = \frac{P}{A} \left(1 + \frac{r_c c_i}{e r_i} \right) = \frac{P}{0.785 \ 4} \left(1 + \frac{2(0.468)}{0.031 \ 754(1.5)} \right) = 26.29P$$

$$\sigma_a = \sigma_m = \frac{\sigma_i}{2} = \frac{26.294P}{2} = 13.15P$$

(a) Eye: Section AA,

Table 6-2, p. 296, a = 14.4 kpsi, b = -0.718

Eq. (6-19), p. 295,

$$k_a = 14.4(93.7)^{-0.718} = 0.553$$

Eq. (6-23), p. 297,

$$d_e = 0.370 d$$

Eq. (6-20), p. 296,

$$k_b = \left(\frac{0.37}{0.30}\right)^{-0.107} = 0.978$$

Eq. (6-26), p. 298,

$$k_c = 0.85$$

Eq. (6-8), p. 290,

$$S'_{a} = 0.5S_{ut} = 0.5(93.7) = 46.85$$
 kpsi

Eq. (6-18) p. 295,

$$S_e = 0.553(0.978)0.85(46.85) = 21.5 \text{ kpsi}$$

From Table 6-7, p. 315, for Gerber

$$n_f = \frac{1}{2} \left(\frac{S_{ut}}{\sigma_m} \right)^2 \frac{\sigma_a}{S_e} \left[-1 + \sqrt{1 + \left(\frac{2\sigma_m S_e}{S_{ut} \sigma_a} \right)^2} \right]$$

With $\sigma_m = \sigma_a$,

$$n_f = \frac{1}{2} \frac{S_{ut}^2}{\sigma_a S_e} \left[-1 + \sqrt{1 + \left(\frac{2S_e}{S_{ut}}\right)^2} \right] = \frac{1}{2} \frac{93.7^2}{13.15P(21.5)} \left[-1 + \sqrt{1 + \left(\frac{2(21.5)}{93.7}\right)^2} \right] = \frac{1.557}{P}$$

where *P* is in kips.

Thread: Die cut. Table 8-17 gives $S_e = 18.6$ kpsi for rolled threads. Use Table 8-16 to find S_e for die cut threads

$$S_0 = 18.6(3.0/3.8) = 14.7 \text{ kpsi}$$

 $S_e = 18.6(3.0/3.8) = 14.7 \text{ kpsi}$ Table 8-2, $A_t = 0.663 \text{ in}^2$, $\sigma = P/A_t = P/0.663 = 1.51 P$, $\sigma_a = \sigma_m = \sigma/2 = 0.755 P$ From Table 6-7, Gerber

$$n_f = \frac{1}{2} \frac{S_{ut}^2}{\sigma_a S_e} \left[-1 + \sqrt{1 + \left(\frac{2S_e}{S_{ut}}\right)^2} \right] = \frac{1}{2} \frac{93.7^2}{0.755P(14.7)} \left[-1 + \sqrt{1 + \left(\frac{2(14.7)}{93.7}\right)^2} \right] = \frac{19.01}{P}$$

Comparing 1910/P with 19 200/P, we conclude that the eye is weaker in fatigue. Ans.

- (b) Strengthening steps can include heat treatment, cold forming, cross section change (a round is a poor cross section for a curved bar in bending because the bulk of the material is located where the stress is small). *Ans*.
- (c) For $n_f = 2$

$$P = \frac{1.557(10^3)}{2} = 779 \text{ lbf, max. load}$$
 Ans.

8-60 Member, Eq. (8-22) with E = 16 Mpsi, d = 0.75 in, and l = 1.5 in

$$k_{m} = \frac{0.5774\pi Ed}{2\ln\left(5\frac{0.5774l + 0.5d}{0.5774l + 2.5d}\right)} = \frac{0.5774\pi(16)0.75}{2\ln\left[5\frac{0.5774(1.5) + 0.5(0.75)}{0.5774(1.5) + 2.5(0.75)}\right]} = 13.32 \text{ Mlbf/in}$$

Bolt, Eq. (8-13),

$$L_T = 2d + 0.25 = 2(0.75) + 0.25 = 1.75$$
 in

$$l = 1.5 \text{ in}$$

$$l_d = L - L_T = 2.5 - 1.75 = 0.75$$
 in

$$l_t = l - l_d = 1.5 - 0.75 = 0.75$$
 in

Table 8-2,

$$A_t = 0.373 \text{ in}^2$$

$$A_d = \pi (0.75^2)/4 = 0.442 \text{ in}^2$$

Eq. (8-17),

$$k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.442(0.373)30}{0.442(0.75) + 0.373(0.75)} = 8.09$$
 Mlbf/in

$$C = \frac{k_b}{k_b + k_m} = \frac{8.09}{8.09 + 13.32} = 0.378$$

Eq. (8-35),

$$\sigma_a = \frac{C(P_{\text{max}} - P_{\text{min}})}{2A_t} = \frac{0.378(6-4)}{2(0.373)} = 1.013 \text{ kpsi}$$

Eq.(8-36),

$$\sigma_m = \frac{C(P_{\text{max}} + P_{\text{min}})}{2A_t} + \frac{F_i}{A_t} = \frac{0.378(6+4)}{2(0.373)} + \frac{25}{0.373} = 72.09 \text{ kpsi}$$

(a) From Table 8-9, $S_p = 85$ kpsi, and Eq. (8-51), the yielding factor of safety is

$$n_p = \frac{S_p}{\sigma_m + \sigma_a} = \frac{85}{72.09 + 1.013} = 1.16$$
 Ans.

(b) From Eq. (8-29), the overload factor of safety is

$$n_L = \frac{S_p A_t - F_i}{CP_{\text{max}}} = \frac{85(0.373) - 25}{0.378(6)} = 2.96$$
 Ans.

(c) From Eq. (8-30), the factor of safety based on joint separation is

$$n_0 = \frac{F_i}{P_{\text{max}}(1-C)} = \frac{25}{6(1-0.378)} = 6.70$$
 Ans.

(**d**) From Table 8-17, $S_e = 18.6$ kpsi; Table 8-9, $S_{ut} = 120$ kps; the preload stress is $\sigma_i = F_i / A_t = 25/0.373 = 67.0$ kpsi; and from Eq. (8-38)

$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{S_{ut} \sigma_a + S_e \left(\sigma_m - \sigma_i \right)} = \frac{18.6 \left(120 - 67.0 \right)}{120 \left(1.013 \right) + 18.6 \left(72.09 - 67.0 \right)} = 4.56 \qquad Ans.$$

8-61 (a) Table 8-2, $A_t = 0.1419 \text{ in}^2$ Table 8-9, $S_p = 120 \text{ kpsi}$, $S_{ut} = 150 \text{ kpsi}$ Table 8-17, $S_e = 23.2 \text{ kpsi}$ Eqs. (8-31) and (8-32), $\sigma_i = 0.75 S_p = 0.75(120) = 90 \text{ kpsi}$

$$C = \frac{k_b}{k_b + k_m} = \frac{4}{4 + 16} = 0.2$$

$$\sigma_a = \frac{CP}{2A_t} = \frac{0.2P}{2(0.141 \text{ 9})} = 0.705P \text{ kpsi}$$

Eq. (8-45) for the Goodman criterion,

$$n_f = \frac{S_e \left(S_{ut} - \sigma_i \right)}{\sigma_a \left(S_{ut} + S_e \right)} = \frac{23.2(150 - 90)}{0.705P(150 + 23.2)} = \frac{11.4}{P} = 2 \implies P = 5.70 \text{ kips}$$
 Ans.

(b) $F_i = 0.75A_tS_p = 0.75(0.141 \ 9)120 = 12.77 \ \text{kips}$ Yield, Eq. (8-28),

$$n_p = \frac{S_p A_i}{CP + F_i} = \frac{120(0.141 \ 9)}{0.2(5.70) + 12.77} = 1.22$$
 Ans.

Load factor, Eq. (8-29),

$$n_L = \frac{S_p A_i - F_i}{CP} = \frac{120(0.1419) - 12.77}{0.2(5.70)} = 3.74$$
 Ans.

Separation load factor, Eq. (8-30)

$$n_0 = \frac{F_i}{P(1 - C)} = \frac{12.77}{5.70(1 - 0.2)} = 2.80$$
 Ans.

8-62 Table 8-2, $A_t = 0.969 \text{ in}^2 \text{ (coarse)}, A_t = 1.073 \text{ in}^2 \text{ (fine)}$ Table 8-9, $S_p = 74 \text{ kpsi}, S_{ut} = 105 \text{ kpsi}$ Table 8-17, $S_e = 16.3 \text{ kpsi}$

Coarse thread,

$$F_i = 0.75 A_t S_p = 0.75(0.969)74 = 53.78 \text{ kips}$$

 $\sigma_i = 0.75 S_p = 0.75(74) = 55.5 \text{ kpsi}$
 $\sigma_a = \frac{CP}{2A_t} = \frac{0.30P}{2(0.969)} = 0.155P \text{ kpsi}$

Gerber, Eq. (8-46),

$$n_f = \frac{1}{2\sigma_a S_e} \left[S_{ut} \sqrt{S_{ut}^2 + 4S_e (S_e + \sigma_i)} - S_{ut}^2 - 2\sigma_i S_e \right]$$

$$= \frac{1}{2(0.155P)16.3} \left[105\sqrt{105^2 + 4(16.3)(16.3 + 55.5)} - 105^2 - 2(55.5)16.3 \right] = \frac{64.28}{P}$$
With $n_f = 2$,

$$P = \frac{64.28}{2} = 32.14 \text{ kip}$$
 Ans.

Fine thread,

$$F_i = 0.75 A_t S_p = 0.75(1.073)74 = 59.55 \text{kips}$$

 $\sigma_i = 0.75 S_p = 0.75(74) = 55.5 \text{ kpsi}$
 $\sigma_a = \frac{CP}{2A_t} = \frac{0.32P}{2(1.073)} = 0.149P \text{ kpsi}$

The only thing that changes in Eq. (8-46) is σ_a . Thus,

$$n_f = \frac{0.155}{0.149} \frac{64.28}{P} = \frac{66.87}{P} = 2 \implies P = 33.43 \text{ kips}$$
 Ans.

Percent improvement,

$$\frac{33.43 - 32.14}{32.14}$$
(100) \Box 4% Ans.

8-63 For an M 30 × 3.5 ISO 8.8 bolt with P = 65 kN/bolt and C = 0.28

Table 8-1,
$$A_t = 561 \text{ mm}^2$$

Table 8-11, $S_p = 600 \text{ MPa}, S_{ut} = 830 \text{ MPa}$
Table 8-17, $S_e = 129 \text{ MPa}$

Eq. (8-31),
$$F_i = 0.75F_p = 0.75 A_t S_p$$
$$= 0.75(5610600(10^{-3})) = 252.45 \text{ kN}$$
$$\sigma_i = 0.75 S_p = 0.75(600) = 450 \text{ MPa}$$

Eq. (8-39),
$$\sigma_a = \frac{CP}{2A_t} = \frac{0.28(65)10^3}{2(561)} = 16.22 \text{ MPa}$$

Gerber, Eq. (8-46),

$$n_f = \frac{1}{2\sigma_a S_e} \left[S_{ut} \sqrt{S_{ut}^2 + 4S_e (S_e + \sigma_i)} - S_{ut}^2 - 2\sigma_i S_e \right]$$

$$= \frac{1}{2(16.22)129} \left[830\sqrt{830^2 + 4(129)(129 + 450)} - 830^2 - 2(450)129 \right]$$

$$= 4.75 \qquad Ans.$$

The yielding factor of safety, from Eq. (8-28) is

$$n_p = \frac{S_p A_t}{CP + F_i} = \frac{600(561)10^{-3}}{0.28(65) + 252.45} = 1.24$$
 Ans.

From Eq. (8-29), the load factor is

$$n_L = \frac{S_p A_i - F_i}{CP} = \frac{600(561)10^{-3} - 252.45}{0.28(65)} = 4.62$$
 Ans.

The separation factor, from Eq. (8-30) is

$$n_0 = \frac{F_i}{P(1-C)} = \frac{252.45}{65(1-0.28)} = 5.39$$
 Ans.

8-64 (a) Table 8-2,
$$A_t = 0.077 \, 5 \, \text{in}^2$$

Table 8-9, $S_p = 85 \, \text{kpsi}$, $S_{ut} = 120 \, \text{kpsi}$
Table 8-17, $S_e = 18.6 \, \text{kpsi}$
Unthreaded grip,

$$k_b = \frac{A_d E}{l} = \frac{\pi (0.375)^2 (30)}{4(13.5)} = 0.245 \text{ Mlbf/in per bolt} \quad Ans.$$

$$A_m = \frac{\pi}{4} [(D + 2t)^2 - D^2] = \frac{\pi}{4} (4.75^2 - 4^2) = 5.154 \text{ in}^2$$

$$k_m = \frac{A_m E}{l} = \frac{5.154(30)}{12} \left(\frac{1}{6}\right) = 2.148 \text{ Mlbf/in/bolt.} \quad Ans.$$

(b)
$$F_i = 0.75 A_t S_p = 0.75(0.0775)(85) = 4.94 \text{ kip}$$

$$\sigma_i = 0.75 S_p = 0.75(85) = 63.75 \text{ kpsi}$$

$$P = pA = \frac{2000}{6} \left[\frac{\pi}{4} (4)^2 \right] = 4189 \text{ lbf/bolt}$$

$$C = \frac{k_b}{k_b + k_m} = \frac{0.245}{0.245 + 2.148} = 0.102$$

$$\sigma_a = \frac{CP}{2A_t} = \frac{0.102(4.189)}{2(0.0775)} = 2.77 \text{ kpsi}$$

From Eq. (8-46) for Gerber fatigue criterion,

$$\begin{split} n_f &= \frac{1}{2\sigma_a S_e} \bigg[S_{ut} \sqrt{S_{ut}^2 + 4S_e \left(S_e + \sigma_i \right)} - S_{ut}^2 - 2\sigma_i S_e \bigg] \\ &= \frac{1}{2(2.77)18.6} \bigg[120\sqrt{120^2 + 4(18.6)(18.6 + 63.75)} - 120^2 - 2(63.75)18.6 \bigg] = 4.09 \quad Ans. \end{split}$$

(c) Pressure causing joint separation from Eq. (8-30)

$$n_0 = \frac{F_i}{P(1 - C)} = 1$$

$$P = \frac{F_i}{1 - C} = \frac{4.94}{1 - 0.102} = 5.50 \text{ kip}$$

$$p = \frac{P}{A} = \frac{5.50}{\pi (4^2) / 4} 6 = 2.63 \text{ kpsi} \quad Ans.$$

8-65 From the solution of Prob. 8-64, $A_t = 0.077 \, 5 \, \text{in}^2$, $S_{ut} = 120 \, \text{kpsi}$, $S_e = 18.6 \, \text{kpsi}$, C = 0.102, $\sigma_i = 63.75 \, \text{kpsi}$

$$P_{\text{max}} = p_{\text{max}}A = 2 \pi (4^2)/4 = 25.13 \text{ kpsi}, P_{\text{min}} = p_{\text{min}}A = 1.2 \pi (4^2)/4 = 15.08 \text{ kpsi},$$

Shigley's MED, 10th edition

Eq. (8-35),
$$\sigma_a = \frac{C(P_{\text{max}} - P_{\text{min}})}{2A_t} = \frac{0.102(25.13 - 15.08)}{2(0.077 5)} = 6.61 \text{ kpsi}$$
Eq. (8-36),
$$\sigma_m = \frac{C(P_{\text{max}} + P_{\text{min}})}{2A_t} + \sigma_i = \frac{0.102(25.13 + 15.08)}{2(0.077 5)} + 63.75 = 90.21 \text{ kpsi}$$
Eq. (8-38),
$$n_f = \frac{S_e(S_{ut} - \sigma_i)}{S_{ut}\sigma_a + S_e(\sigma_m - \sigma_i)} = \frac{18.6(120 - 63.75)}{120(6.61) + 18.6(90.21 - 63.75)} = 0.814 \quad Ans.$$

This predicts a fatigue failure.

8-66 Members: $S_y = 57$ kpsi, $S_{sy} = 0.577(57) = 32.89$ kpsi. Bolts: SAE grade 5, $S_y = 92$ kpsi, $S_{sy} = 0.577(92) = 53.08$ kpsi

Shear in bolts,

$$A_s = 2\left[\frac{\pi(0.25^2)}{4}\right] = 0.0982 \text{ in}^2$$

$$F_s = \frac{A_s S_{sy}}{n} = \frac{0.0982(53.08)}{2} = 2.61 \text{ kips}$$

Bearing on bolts,

$$A_b = 2(0.25)0.25 = 0.125 \text{ in}^2$$

$$F_b = \frac{A_b S_{yc}}{n} = \frac{0.125(92)}{2} = 5.75 \text{ kips}$$

Bearing on member,

$$F_b = \frac{0.125(57)}{2} = 3.56 \text{ kips}$$

Tension of members,

$$A_t = (1.25 - 0.25)(0.25) = 0.25 \text{ in}^2$$

$$F_t = \frac{0.25(57)}{2} = 7.13 \text{ kip}$$

 $F = \min(2.61, 5.75, 3.56, 7.13) = 2.61 \text{ kip}$ Ans

The shear in the bolts controls the design.

8-67 Members, Table A-20, $S_y = 42$ kpsi Bolts, Table 8-9, $S_y = 130$ kpsi, $S_{sy} = 0.577(130) = 75.01$ kpsi

Shear of bolts,

$$A_s = 2 \left[\frac{\pi (5/16)^2}{4} \right] = 0.1534 \text{ in}^2$$

$$\tau = \frac{F_s}{A_c} = \frac{5}{0.1534} = 32.6 \text{ kpsi}$$

$$n = \frac{S_{sy}}{\tau} = \frac{75.01}{32.6} = 2.30$$
 Ans.

Bearing on bolts,

$$A_b = 2(0.25)(5/16) = 0.1563 \text{ in}^2$$

$$\sigma_b = -\frac{5}{0.1563} = -32.0 \text{ kpsi}$$

$$n = \frac{S_y}{|\sigma_b|} = \frac{130}{32.0} = 4.06 \qquad Ans.$$

Bearing on members,

$$n = \frac{S_y}{|\sigma_b|} = \frac{42}{32} = 1.31$$
 Ans.

Tension of members,

$$A_t = [2.375 - 2(5/16)](1/4) = 0.4375 \text{ in}^2$$

$$\sigma_t = \frac{5}{0.4375} = 11.4 \text{ kpsi}$$

$$n = \frac{S_y}{\sigma_t} = \frac{42}{11.4} = 3.68$$
 Ans.

8-68 Members: Table A-20, $S_y = 490$ MPa, $S_{sy} = 0.577(490) = 282.7$ MPa Bolts: Table 8-11, ISO class 5.8, $S_y = 420$ MPa, $S_{sy} = 0.577(420) = 242.3$ MPa

Shear in bolts,

$$A_s = 2\left[\frac{\pi(20^2)}{4}\right] = 628.3 \text{ mm}^2$$

$$F_s = \frac{A_s S_{sy}}{n} = \frac{628.3(242.3)10^{-3}}{2.5} = 60.9 \text{ kN}$$

Bearing on bolts,

$$A_b = 2(20)20 = 800 \text{ mm}^2$$

$$F_b = \frac{A_b S_{yc}}{n} = \frac{800(420)10^{-3}}{2.5} = 134 \text{ kN}$$

Bearing on member,

$$F_b = \frac{800(490)10^{-3}}{2.5} = 157 \text{ kN}$$

Tension of members,

$$A_t = (80 - 20)(20) = 1200 \text{ mm}^2$$

$$F_t = \frac{1200(490)10^{-3}}{2.5} = 235 \text{ kN}$$

$$F = \min(60.9, 134, 157, 235) = 60.9 \text{ kN} \quad Ans.$$

The shear in the bolts controls the design.

<u>e</u>

8-69 Members: Table A-20,
$$S_y = 320 \text{ MPa}$$

Bolts: Table 8-11, ISO class 5.8, $S_y = 420$ MPa, $S_{sy} = 0.577(420) = 242.3$ MPa

Shear of bolts,

$$A_s = \pi (20^2)/4 = 314.2 \text{ mm}^2$$

$$\tau_s = \frac{90(10^3)}{3(314.2)} = 95.48 \text{ MPa}$$

$$n = \frac{S_{sy}}{\tau_s} = \frac{242.3}{95.48} = 2.54 \text{ Ans.}$$

Bearing on bolt,

$$A_b = 3(20)15 = 900 \text{ mm}^2$$

$$\sigma_b = -\frac{90(10^3)}{900} = -100 \text{ MPa}$$

$$n = \frac{S_y}{|\sigma_b|} = \frac{420}{100} = 4.2 \text{ Ans.}$$

Bearing on members,

$$n = \frac{S_y}{|\sigma_b|} = \frac{320}{100} = 3.2$$
 Ans.

Tension on members,

$$\sigma_t = \frac{F}{A} = \frac{90(10^3)}{15[190 - 3(20)]} = 46.15 \text{ MPa}$$

$$n = \frac{S_y}{\sigma_t} = \frac{320}{46.15} = 6.93 \quad Ans.$$

8-70 Members: $S_y = 57 \text{ kpsi}$

Bolts: $S_y = 100 \text{ kpsi}$, $S_{sy} = 0.577(100) = 57.7 \text{ kpsi}$

$$A = 3 \left[\frac{\pi (1/4)^2}{4} \right] = 0.1473 \text{ in}^2$$

$$\tau_s = \frac{F}{A_s} = \frac{5}{0.1473} = 33.94 \text{ kpsi}$$

$$n = \frac{S_{sy}}{\tau} = \frac{57.7}{33.94} = 1.70$$
 Ans.

Bearing on bolts,

$$A_b = 3(1/4)(5/16) = 0.2344 \text{ in}^2$$

$$\sigma_b = -\frac{F}{A_b} = -\frac{5}{0.2344} = -21.3 \text{ kpsi}$$

$$n = \frac{S_y}{|\sigma_b|} = \frac{100}{21.3} = 4.69$$
 Ans.

Bearing on members,

 $A_b = 0.2344 \text{ in}^2$ (From bearing on bolts calculation)

 $\sigma_b = -21.3$ kpsi (From bearing on bolts calculation)

$$n = \frac{S_y}{|\sigma_b|} = \frac{57}{21.3} = 2.68$$
 Ans.


Tension in members, failure across two bolts,

$$A_t = \frac{5}{16} [2.375 - 2(1/4)] = 0.5859 \text{ in}^2$$

$$\sigma_t = \frac{F}{A} = \frac{5}{0.5859} = 8.534 \text{ kpsi}$$

$$n = \frac{S_y}{\sigma_t} = \frac{57}{8.534} = 6.68$$
 Ans.

8-71 By symmetry, the reactions at each support is 1.6 kN. The free-body diagram for the left member is



$$\sum M_B = 0 \qquad 1.6(250) - 50R_A = 0 \quad \Rightarrow \quad R_A = 8 \text{ kN}$$
$$\sum M_A = 0 \qquad 200(1.6) - 50R_B = 0 \quad \Rightarrow \quad R_B = 6.4 \text{ kN}$$

Members: Table A-20, $S_y = 370 \text{ MPa}$

Bolts: Table 8-11, $S_v = 420$ MPa, $S_{sv} = 0.577(420) = 242.3$ MPa

Bolt shear,
$$A_s = \frac{\pi}{4}(12^2) = 113.1 \text{ mm}^2$$

 $\tau = \frac{F_{\text{max}}}{A_s} = \frac{8(10^3)}{113.1} = 70.73 \text{ MPa}$
 $n = \frac{S_{\text{sy}}}{\tau} = \frac{242.3}{70.73} = 3.43$

Bearing on member, $A_b = td = 10(12) = 120 \text{ mm}^2$ $\sigma_b = -\frac{8(10^3)}{120} = -66.67 \text{ MPa}$ $n = \frac{S_y}{|\sigma_b|} = \frac{370}{66.67} = 5.55$

Strength of member. The bending moments at the hole locations are: in the left member at A, $M_A = 1.6(200) = 320 \text{ N} \cdot \text{m}$. In the right member at B, $M_B = 8(50) = 400 \text{ N} \cdot \text{m}$. The bending moment is greater at B

$$I_B = \frac{1}{12} [10(50^3) - 10(12^3)] = 102.7(10^3) \text{ mm}^4$$

$$\sigma_B = \frac{M_A c}{I_A} = \frac{400(25)}{102.7(10^3)} (10^3) = 97.37 \text{ MPa}$$

$$n = \frac{S_y}{\sigma_A} = \frac{370}{97.37} = 3.80$$

At the center, call it point *C*,

$$M_C = 1.6(350) = 560 \text{ N} \cdot \text{m}$$


$$I_C = \frac{1}{12}(10)(50^3) = 104.2(10^3) \text{ mm}^4$$

$$\sigma_C = \frac{M_C c}{I_C} = \frac{560(25)}{104.2(10^3)}(10^3) = 134.4 \text{ MPa}$$

$$n = \frac{S_y}{\sigma_C} = \frac{370}{134.4} = 2.75 < 3.80 \text{ more critical at } C$$

$$n = \min(3.04, 3.80, 2.75) = 2.72 \text{ Ans.}$$

8-72 The free-body diagram of the bracket, assuming the upper bolt takes all the shear and tensile load is



$$F_s = 2500 \text{ lbf}$$

$$P = \frac{2500(3)}{7} = 1071 \text{ lbf}$$

Table A-31, H = 7/16 = 0.4375 in. Grip, l = 2(1/2) = 1 in. $L \ge l + H = 1.4375$ in. Use 1.5 in bolts.

Eq. (8-13),
$$L_T = 2d + 0.25 = 2(0.5) + 0.25 = 1.25$$
 in

Table 8-7,
$$l_d = L - L_T = 1.5 - 1.25 = 0.25$$
 in $l_t = l - l_d = 1 - 0.25 = 0.75$ in Table 8-2, $A_t = 0.141 \ 9 \ \text{in}^2$

Table 8-2,
$$A_t = 0.141 \text{ 9 in}^2$$

 $A_t = \pi (0.5^2) / 4 = 0.196.3 \text{ i}$

Eq. (8-17),
$$A_d = \pi (0.5^2) / 4 = 0.196 \text{ 3 in}^2$$

$$E_q. (8-17), \qquad k_b = \frac{A_d A_t E}{A_d l_t + A_t l_d} = \frac{0.196 \text{ 3} (0.141 \text{ 9}) 30}{0.196 \text{ 3} (0.75) + 0.141 \text{ 9} (0.25)} = 4.574 \text{ Mlbf/in}$$

Eq. (8-22),

$$k_{m} = \frac{0.5774\pi Ed}{2\ln\left(5\frac{0.5774l + 0.5d}{0.5774l + 2.5d}\right)} = \frac{0.5774\pi(30)0.5}{2\ln\left(5\frac{0.5774(1) + 0.5(0.5)}{0.5774(1) + 2.5(0.5)}\right)} = 16.65 \text{ Mlbf/in}$$

$$C = \frac{k_b}{k_b + k_m} = \frac{4.574}{4.574 + 16.65} = 0.216$$

Table 8-9,

Eqs. (8-31) and (8-32),
$$F_i = 0.75 A_t S_p = 0.75(0.141 \text{ 9})65 = 6.918 \text{ kips}$$

 $\sigma_i = 0.75 S_p = 0.75(65) = 48.75 \text{ kips}$


Eq. (a), p. 432,
$$\sigma_b = \frac{CP + F_i}{A_i} = \frac{0.216(1.071) + 6.918}{0.1419} = 50.38 \text{ kpsi}$$

Direct shear,
$$\tau_s \approx \frac{F_s}{A_t} = \frac{3}{0.1419} = 21.14 \text{ kpsi}$$

von Mises stress, Eq. (5-15), p. 237

$$\sigma' = (\sigma_b^2 + 3\tau_s^2)^{1/2} = [50.38^2 + 3(21.14^2)]^{1/2} = 62.3 \text{ kpsi}$$

$$n = \frac{S_p}{\sigma'} = \frac{65}{62.3} = 1.04$$
 Ans



$$2P(200) = 14(50)$$

 $P = \frac{14(50)}{2(200)} = 1.75 \text{ kN per bolt}$

$$F_{s} = 7 \text{ kN/bolt}$$

$$S_{p} = 380 \text{ MPa}$$

$$S_p = 380 \, \text{MPa}$$

$$A_t = 245 \text{ mm}^2$$
, $A_d = \frac{\pi}{4}(20^2) = 314.2 \text{ mm}^2$

$$F_i = 0.75(245)(380)(10^{-3}) = 69.83 \text{ kN}$$

$$\sigma_i = 0.75(380) = 285 \text{ MPa}$$

$$\sigma_b = \frac{CP + F_i}{A_i} = \left(\frac{0.25(1.75) + 69.83}{245}\right)(10^3) = 287 \text{ MPa}$$

$$F = 7(10^3)$$

$$\tau = \frac{F_s}{A_d} = \frac{7(10^3)}{314.2} = 22.3 \text{ MPa}$$

$$\sigma' = [287^2 + 3(22.3^2)]^{1/2} = 290 \text{ MPa}$$

$$n = \frac{S_p}{\sigma'} = \frac{380}{290} = 1.31$$
 Ans.

8-74 Using the result of Prob. 5-67 for lubricated assembly (replace 0.2 with 0.18 per Table 8-15)

$$F_{x} = \frac{2\pi f T}{0.18d}$$

With a design factor of n_d gives

$$T = \frac{0.18n_d F_x d}{2\pi f} = \frac{0.18(3)(1000)d}{2\pi (0.12)} = 716d$$

or T/d = 716. Also,

$$\frac{T}{d} = K(0.75S_p A_t)$$

$$= 0.18(0.75)(85\ 000)A_t$$

$$= 11\ 475A_t$$

Form a table

Size	A_t	$T/d = 11 \ 475A_t$	n
$\frac{1}{4}$ - 28	0.0364	417.70	1.75
$\frac{5}{16}$ - 24	0.058	665.55	2.8
$\frac{3}{8}$ - 24	0.0878	1007.50	4.23

where the factor of safety in the last column of the table comes from


$$n = \frac{2\pi f(T/d)}{0.18F_{\rm v}} = \frac{2\pi (0.12)(T/d)}{0.18(1000)} = 0.0042(T/d)$$

Select a $\frac{3}{8}$ - 24 UNF cap screw. The setting is given by

$$T = (11\ 475A_t)d = 1007.5(0.375) = 378\ \text{lbf} \cdot \text{in}$$

Given the coarse scale on a torque wrench, specify a torque wrench setting of 400 lbf \cdot in. Check the factor of safety

$$n = \frac{2\pi f \ T}{0.18F, d} = \frac{2\pi (0.12)(400)}{0.18(1000)(0.375)} = 4.47$$



Bolts, from Table 8-11, $S_y = 420$ MPa Channel, From Table A-20, $S_y = 170$ MPa. From Table A-7, t = 6.4 mm Cantilever, from Table A-20, $S_y = 190$ MPa

$$F'_A = F'_B = F'_C = F/3$$

$$M = (50 + 26 + 125) F = 201 F$$

$$F'''_A = F'''_C = \frac{201F}{2(50)} = 2.01F$$

Max. force,
$$F_C = F_C' + F_C'' = \left(\frac{1}{3} + 2.01\right)F = 2.343F$$
 (1)

Shear on Bolts: The shoulder bolt shear area, $A_s = \pi (10^2) / 4 = 78.54 \text{ mm}^2$

$$S_{sy} = 0.577(420) = 242.3 \text{ KPa}$$

$$\tau_{\text{max}} = \frac{F_C}{A} = \frac{S_{sy}}{n}$$

From Eq. (1), $F_C = 2.343 F$. Thus

$$F = \frac{S_{sy}}{n} \left(\frac{A_s}{2.343} \right) = \frac{242.3}{2.0} \left(\frac{78.54}{2.343} \right) 10^{-3} = 4.06 \text{ kN}$$

Bearing on bolt: The bearing area is $A_b = td = 6.4(10) = 64 \text{ mm}^2$. Similar to shear

$$F = \frac{S_y}{n} \left(\frac{A_b}{2.343} \right) = \frac{420}{2.0} \left(\frac{64}{2.343} \right) 10^{-3} = 5.74 \text{ kN}$$

Bearing on channel: $A_b = 64 \text{ mm}^2$, $S_y = 170 \text{ MPa}$.

Shigley's MED, 10th edition

$$F = \frac{S_y}{n} \left(\frac{A_b}{2.343} \right) = \frac{170}{2.0} \left(\frac{64}{2.343} \right) 10^{-3} = 2.32 \text{ kN}$$

Bearing on cantilever: $A_b = 12(10) = 120 \text{ mm}^2$, $S_y = 190 \text{ MPa}$.

$$F = \frac{S_y}{n} \left(\frac{A_b}{2.343} \right) = \frac{190}{2.0} \left(\frac{120}{2.343} \right) 10^{-3} = 4.87 \text{ kN}$$

Bending of cantilever: At C

$$I = \frac{1}{12} (12) (50^3 - 10^3) = 1.24 (10^5) \text{ mm}^4$$

$$\sigma_{\text{max}} = \frac{S_y}{n} = \frac{Mc}{I} = \frac{151Fc}{I} \implies F = \frac{S_y}{n} \left(\frac{I}{151c}\right)$$

$$F = \frac{190}{2.0} \left\lceil \frac{1.24(10^5)}{151(25)} \right\rceil 10^{-3} = 3.12 \text{ kN}$$

So F = 2.32 kN based on bearing on channel. Ans.

8-76 Bolts, from Table 8-11, $S_y = 420$ MPa Bracket, from Table A-20, $S_y = 210$ MPa

$$F' = \frac{12}{3} = 4 \text{ kN}; M = 12(200) = 2400 \text{ N} \cdot \text{m}$$

$$F'''_A = F'''_B = \frac{2400}{64} = 37.5 \text{ kN}$$

$$F_A = F_B = \sqrt{(4)^2 + (37.5)^2} = 37.7 \text{ kN}$$

$$F_O = 4 \text{ kN}$$




The shoulder bolt shear area, $A_s = \pi(12^2) / 4 = 113.1 \text{ mm}^2$

$$S_{sy} = 0.577(420) = 242.3 \text{ KPa}$$

$$\tau = \frac{37.7(10)^3}{113} = 333 \text{ MPa}$$

$$n = \frac{S_{sy}}{\tau} = \frac{242.3}{333} = 0.728 \quad Ans.$$



Bearing on bolts:

$$A_b = 12(8) = 96 \text{ mm}^2$$

$$\sigma_b = -\frac{37.7(10)^3}{96} = -393 \text{ MPa}$$

$$n = \frac{S_{yc}}{|\sigma_b|} = \frac{420}{393} = 1.07 \quad Ans$$

Bearing on member:

$$\sigma_b = -393 \text{ MPa}$$

$$n = \frac{S_{yc}}{|\sigma_b|} = \frac{210}{393} = 0.534 \qquad Ans.$$

Bending stress in plate:


$$I = \frac{bh^{3}}{12} - \frac{bd^{3}}{12} - 2\left(\frac{bd^{3}}{12} + a^{2}bd\right)$$

$$= \frac{8(136)^{3}}{12} - \frac{8(12)^{3}}{12} - 2\left[\frac{8(12)^{3}}{12} + (32)^{2}(8)(12)\right]$$


$$= 1.48(10)^{6} \text{ mm}^{4} \quad Ans.$$


$$\sigma = \frac{Mc}{I} = \frac{2400(68)}{1.48(10)^{6}}(10)^{3} = 110 \text{ MPa}$$

$$n = \frac{S_{y}}{\sigma} = \frac{210}{110} = 1.91 \quad Ans.$$



Failure is predicted for bolt shear and bearing on member.





$$F_A'' = F_B'' = \left(\frac{3625}{3}\right) = 1208 \text{ lbf}$$

$$F_A = 1208 - 125 = 1083 \text{ lbf}, \qquad F_B = 1208 + 125 = 1333 \text{ lbf}$$

Bolt shear:

$$A_s = (\pi/4)(0.375^2) = 0.1104 \text{ in}^2$$

$$\tau_{\text{max}} = \frac{F_{\text{max}}}{A_{\text{s}}} = \frac{1333}{0.1104} = 12\ 070\ \text{psi}$$

From Table 8-10, $S_y = 100 \text{ kpsi}$, $S_{sy} = 0.577(100) = 57.7 \text{ kpsi}$

$$n = \frac{S_{sy}}{\tau_{max}} = \frac{57.7}{12.07} = 4.78$$
 Ans.

Bearing on bolt: Bearing area is $A_b = td = 0.375 (0.375) = 0.1406 \text{ in}^2$.

$$\sigma_b = -\frac{F}{A_b} = -\frac{1333}{0.1406} = -9 \text{ 481 psi}$$

$$n = \frac{S_y}{|\sigma_b|} = \frac{100}{9.481} = 10.55$$
 Ans.

Bearing on member: From Table A-20, $S_v = 54$ kpsi. Bearing stress same as bolt

$$n = \frac{S_y}{|\sigma_b|} = \frac{54}{9.481} = 5.70$$
 Ans.

Bending of member: At B, M = 250(13) = 3250 lbf·in

$$I = \frac{1}{12} \left(\frac{3}{8} \right) \left[2^3 - \left(\frac{3}{8} \right)^3 \right] = 0.2484 \text{ in}^4$$

$$\sigma = \frac{Mc}{I} = \frac{3250(1)}{0.2484} = 13\ 080 \text{ psi}$$

$$n = \frac{S_y}{\sigma} = \frac{54}{13.08} = 4.13$$
 Ans

8-78 The direct shear load per bolt is F' = 2000/6 = 333.3 lbf. The moment is taken only by the four outside bolts. This moment is $M = 2000(5) = 10\,000$ lbf \cdot in.

Thus $F'' = \frac{10\ 000}{2(5)} = 1000\ \text{lbf}$ and the resultant bolt load is

$$F = \sqrt{(333.3)^2 + (1000)^2} = 1054 \text{ lbf}$$

Bolt strength, Table 8-9, $S_y = 100$ kpsi; Channel and Plate strength, $S_y = 42$ kpsi

Shear of bolt: $A_s = \pi (0.5)^2 / 4 = 0.1963 \text{ in}^2$

$$n = \frac{S_{sy}}{\tau} = \frac{(0.577)(100)}{1.054 / 0.1963} = 10.7$$
 Ans.

Bearing on bolt: Channel thickness is t = 3/16 in, $A_b = 0.5(3/16) = 0.09375$ in²

$$n = \frac{100}{1.054 / 0.09375} = 8.89 \quad Ans.$$

Bearing on channel: $n = \frac{42}{1.054 / 0.09375} = 3.74$ Ans.

Bearing on plate: $A_b = 0.5(0.25) = 0.125 \text{ in}^2$

$$n = \frac{42}{1.054 / 0.125} = 4.98$$
 Ans.

Strength of plate:

$$I = \frac{0.25(7.5)^3}{12} - \frac{0.25(0.5)^3}{12} - 2\left[\frac{0.25(0.5)^3}{12} + (0.25)(0.5)(2.5)^2\right] = 7.219 \text{ in}^4$$

$$M = 5000 \text{ lbf} \cdot \text{in per plate}$$

$$\sigma = \frac{Mc}{I} = \frac{5000(3.75)}{7.219} = 2597 \text{ psi}$$

$$n = \frac{42}{2.597} = 16.2 \quad Ans.$$

8-79 to 8-81 Specifying bolts, screws, dowels and rivets is the way a student learns about such components. However, choosing an array a priori is based on experience. Here is a chance for students to build some experience.