THE DEMING DIMENSION

HENRY R. NEAVE



Knoxville, Tennessee

CONTENTS

iii

Contents

Foreword by W. Edwards Deming				
Author's Foreword				
Preface				
Preface to Second Printing				
Ac	Acknowledgements			
PART 1:				
PAINTING THE BACKCLOTH				
	Introduction	3		
1.	Deming's View of Recent Industrial History	5		
2.	A Brief Biography	13		
3.	The 14 Points, the Diseases, and the Obstacles	29		
4.	Variation and the Control of Processes	57		

87

PART 2: SOME FUNDAMENTALS

Introduction

5.	The Funnel Experiment	89
6.	The Experiment on Red Beads	101
7.	Operational Definitions	109
8.	Processes and Systems	119
9.	The Deming Cycle	139
10.	Failures With Figures	151
11.	Is Conformance to Specifications Good Enough?	
	—The Taguchi Loss Function	159
12.	The Taguchi Loss Function—Some Detailed Study	181
	PART 3:	
	THE NEW CLIMATE	
	Introduction	195
13.	Joy in Work	197
14.	Innovation—Not Just Improvement	203
15.	Cooperation: Win-Win	
	—Backbone of the New Philosophy	213

Contents

Introduction

17. Quality and Best Efforts

16. Theory and the Search for Examples

PART 4: FOUNDATIONS OF KNOWLEDGE

243

245

253

18. A System of Profound Knowledge						
PART 5:						
THE 14 POINTS REVISITED						
Introductio	n	283				
19. Point 1:	Constancy of Purpose	287				
20. Point 2:	The New Philosophy	293				
21. Point 3:	Cease Dependence on Mass Inspection	297				
22. Point 4:	End Lowest-Tender Contracts	307				
23. Point 5:	Improve Every Process	319				
24. Point 6:	Institute Training	325				
25. Point 7:	Institute Leadership of People	333				
26. Point 8:	Drive Out Fear	341				
27. Point 9:	Break Down Barriers	351				
28. Point 10:	Eliminate Exhortations	357				

The Deming Dimension

29. Point 11:	Eliminate Arbitrary Numerical Targets	361	
30. Point 12:	Permit Pride of Workmanship	375	
31. Point 13:	Encourage Education	391	
32. Point 14:	Top Management Commitment and Action	405	
Epilogue			
List of Figures			
Bibliography			
Permissions			
The British Deming Association			
Index			