## The Six Sigma Practitioner's Guide to Data Analysis

Second Edition

## Donald J. Wheeler

Fellow of the American Statistical Association Fellow of the American Society for Quality



## Contents

		out the Author	xi xii
	Acknowledgments Preface to the Second Edition		
	Introduction		
PART ONE:	THE	FOUNDATIONS OF DATA ANALYSIS	1
One	Four	Statistical Problems	3
	1.1	Descriptive Statistics	3
	1.2	Probability Theory	5
	1.3	Statistical Inference	6
	1.4	The Homogeneity Question	8
	1.5	Two Perspectives on These Problems	9
	1.6	Axioms of Data Analysis	12
	1.7	Observational Studies and Experimental Studies	16
	1.8	Summary	17
Two	Descriptive Statistics and Homogeneity		19
	2.1	What Does the Standard Deviation Statistic Do?	19
	2.2	What Descriptive Statistics Do Not Do	29
	2.3	Local Measures of Dispersion	30
	2.4	Are the Data Homogeneous?	33
	2.5	The Difference between Global and Local	38
Three	Proce	ess Behavior Charts	41
	3.1	The Chart for Individual Values	41
	3.2	What Do We Gain from the <i>mR</i> Chart?	44
	3.3	What Makes the <i>XmR</i> Chart Work?	46
	3.4	How Many Values Do I Need for Limits?	50
	3.5	Rules for Detecting Nonhomogeneity	53
	3.6	Average and Range Charts	58
	3.7	Chunky Data	62
	3.8	Caution regarding Software	65
	3.9	Where Do We Go from Here?	66

Four	<b>Statis</b>	tics, Parameters, and Inference	67
	4.1	The Concept of a Probability Model	67
	4.2	Some Cautions regarding Probability Models	s 71
	4.3	Elements of Statistical Inference	72
	4.4	Interval Estimates of Location	76
	4.5	Interval Estimates of Dispersion	84
	4.6	Practical Statistical Inference	86
	4.7	Interpreting "Degrees of Freedom"	88
	4.8	Summary	91
PART TWO:	THE	TECHNIQUES OF DATA ANALYSIS	93
Five	Data (	Collected under One Condition	95
	5.1	What Can We Say about Our Process?	95
	5.2	But What about the Significance Levels?	99
	5.3	Bead Board No. 3	100
	5.4	The Data for NB10	105
	5.5	Summary	107
Six	Data Collected under Two Conditions		111
	6.1	Detecting a Difference with Histograms	111
	6.2	Detecting a Difference with <i>XmR</i> Charts	113
	6.3	Using an Average and Range Chart	116
	6.4	The Analysis of Means	119
	6.5	The Two-Sample Student's <i>t</i> -Test	122
	6.6	The Paired <i>t</i> -Test	125
	6.7	NB10 Revisited	128
	6.8	Summary of Comparing Two Conditions	130
Seven	Data Collected under Three or More Conditions		133
	7.1	XmR Charts for Each Treatment	133
	7.2	Average and Range Charts	135
	7.3	Analysis of Means	136
	7.4	Analysis of Variance	137
	7.5	The Tukey Post-Hoc Test	145
	7.6	NB10 Again	146
	7.7	Summary of Comparing Several Conditions	148

Eight	Data (	Collected at Three or More Values for $X$	151
	8.1	The Universe Had a Definite Beginning	151
	8.2	Evaluating Terms in the Model	154
	8.3	Regression: One Line or Two?	156
	8.4	A Deterministic Relation with Controlled X Values	158
	8.5	A Deterministic Relation with Uncertain X Values	160
	8.6	X and Y Are Random Variables	162
	8.7	Data Snooping	166
	8.8	Trends	170
	8.9	The Role of the Scatterplot	170
	8.10	The Problem of Regression Models	171
Nine	Coun	t-Based Data	175
	9.1	Two Types of Counts	175
	9.2	Interval Estimates for Universe Proportions	177
	9.3	Homogeneity for Counts	180
	9.4	Should I Compare Counts or Rates?	182
	9.5	A Caution regarding Counts on an XmR Chart	183
	9.6	Outliers or Signals?	186
	9.7	Comparing Two Proportions with Charts	187
	9.8	Comparing Two Single Proportions	189
	9.9	Comparing Proportions for Several Conditions	192
	9.10	Summary	196
Ten	Coun	ts of Events	197
	10.1	Inference for Counts of Events: One Condition	197
	10.2	Using the Poisson Model	201
	10.3	Comparing Two Conditions	202
	10.4	Comparing Several Conditions	205
	10.5	Summary	206
Eleven	Coun	ts for Three or More Categories	207
	11.1	Categorical Frequencies for One Condition	207
	11.2	Categorical Data for Two or More Conditions	215
	11 3	Summary	218

PART THRI	EE: TH	E KEYS TO EFFECTIVE DATA ANALYSIS	219
Twelve	The D	Pual Nature of Trouble	221
	12.1	"We Are in Trouble"	221
	12.2	A New Definition of Trouble	223
	12.3	The Four Possibilities for Any Process	225
	12.4	Research and Experimentation Are Not Enough	235
	12.5	Operating a Process Predictably	241
	12.6	Summary	242
Thirteen	Capab	oility and Performance Indexes	243
	13.1	The Voice(s) of the Process	243
	13.2	The Voice of the Customer	245
	13.3	The Capability Ratio, $C_p$	248
	13.4	The Centered Capability Ratio, $C_{pk}$	250
	13.5	The Performance Ratio, $P_p$	253
	13.6	The Centered Performance Ratio, $P_{pk}$	256
	13.7	Using the Four Ratios Together	257
	13.8	The Ratios and the Four Possibilities	259
	13.9	Operational Improvement	260
	13.10	Short-Term and Long-Term Capability	262
	13.11	Interval Estimates for Capability Indexes	262
	13.12	Summary	267
Fourteen	Using	the Effective Cost of Production and Use	269
	14.1	The Effective Cost of Production and Use	269
	14.2	The Baseline Cost of Production and Use	271
	14.3	The Centered Cost of Production and Use	272
	14.4	The Predictable Cost of Production and Use	273
	14.5	The Minimum Cost of Production and Use	275
	14.6	Using the Effective Cost of Production and Use	276
	14.7	Summary	280
Fifteen	The B	asis for the Effective Cost of Production and Use	281
	15.1	The Structure of the <i>Effective Cost of Production and Use</i>	281
	15.2	The Average Excess Costs	282
	15.3	Finding the Effective Cost of Production and Use	288
	15.4	Summary of ECP&U for Measurements	289
	15.5	The Effective Cost of Production for Counts of Items	290
	15.6	The Effective Cost of Production for Counts of Events	291

Sixteen	The Six Sigma Zone		293
	16.1	The Effective Cost of Production and Use Curves	293
	16.2	An Illustration	299
	16.3	The Six Sigma Zone	301
	16.4	Summary	302
Seventeen	Some Problems		305
	17.1	Problems with Defects per Million	305
	17.2	Problems with Defects per Million Opportunities	310
	17.3	Problems with FMEA Risk Priority Numbers	311
	17.4	Problems with Special Causes	316
	17.5	Problems with DMAIC Models	318
	17.6	Do We Need a Gauge R&R Study?	321
	17.7	Problems with Narrowly Defined Projects	323
	17.8	Summary	331
Eighteen	Two Models for Process Improvement		333
	18.1	Getting Started	333
	18.2	Characterize the Status of the Process Outcomes	334
	18.3	Outcomes in the State or Brink of Chaos	335
	18.4	Outcomes in the Threshold State	337
	18.5	Outcomes in the Ideal State	338
	18.6	Focusing Improvement on Strategic Objectives	338
	18.7	Summary	341
Nineteen	An Honest Gauge R&R Study		343
	19.1	The AIAG Gauge R&R Study	343
	19.2	The "Percentages" of the Total Variation	346
	19.3	The "Percentages" of the Specified Tolerance	350
	19.4	The "Number of Distinct Categories"	353
	19.5	The AIAG Guidelines	353
	19.6	What Can You Learn from the AIAG Study?	357
	19.7	An Honest Gauge R&R Study	358
	19.8	Summary	363

Appendix		367
Table A.1 Table A.2 Table A.3 Table A.4	Bias Correction Factors for Measures of Dispersion <i>XmR</i> Charts: Charts for Individual Values Average and Range Charts Based on the Average Range Average and Range Charts Based on the Median Range	368-369 370-371 372-373 374-375
Table A.5	Average and Standard Deviation Charts Based on the Average Standard Deviation Statistic	376-377
Table A.6	Average and Standard Deviation Charts Based on the Median Standard Deviation Statistic	378-379
Table A.7	Critical Values for Student's t Distributions	380-381
Table A.8 Table A.9 Table A.10	Percentiles of Chi-Square Distributions Overall Alpha-Levels for Average Charts Overall Alpha-Levels for Range Charts	382-383 384 385
Table A.12	Quick Scale Factors for Range-Based ANOM Quick Scale Factors for Pooled Variance ANOM Percentiles of the F-Distribution	386-388 389-391 392-397
Table A.15	Percentiles of the Studentized Range Distribution, $q$ Factors for 90% Interval Estimates of $C_p$ and $P_p$ Factors for 90% Interval Estimates of $C_{pk}$ and $P_{pk}$	398-403 404 405
Table A.17	The Effective Cost of Production and Use When All Nonconforming Units Are Scrapped	406-408
Table A.18	The Effective Cost of Production and Use When All Nonconforming Units Are Reworked	409-411
Table A.19	The Effective Cost of Production and Use When the Cost of Rework Is Half of the Cost of Scrap and the Average Is on the SCRAP Side of the Target	412-414
Table A.20	The Effective Cost of Production and Use When the Cost of Rework Is Half of the Cost of Scrap and the Average Is on the REWORK Side of the Target	415-417
Index		419