
Model 1: straight logistic (keeps rising)
Model 2: logistic + quadratic term (over-curing hurts)
P(pass)
1.0
0.8
0.6
0.4
0.2
0.0
bar height = weight
Optimal for Model 1 only
166
233
Optimal for Model 2 only
129
171
300
Compound design (serves both)
135
171
226
300
100
125
150
175
200
225
250
275
300
oven temperature (°C)