

INTERVENTION REPORT

Service Provider:	Your Company Name
Address:	123 Company Street, City, Country
Contact:	+1 (555) 123-4567
Email:	contact@yourcompany.com
Website:	www.yourcompany.com
Tax ID:	M2005110000307071
Registration:	CG/PNR/10 B 1445

Client:	John Smith
Address:	123 Main St, Anytown, USA
Contact:	john.smith@email.com (555) 123-4567
Reference:	TICKET#TKT-2023-045

Intervention ID	#INT-2023-001
Intervention Date	2025-09-07
Technician	Michael Johnson
Status	Completed
Start Time	12:22
End Time	12:22
Hours Worked	2.5 hours
Travel Time	0.5 hours
Total Time	3.0 hours
Transport Cost	\$25.0
Additional Costs	\$0.0
Total Cost	\$225.5

Intervention Details

Performed routine maintenance on the HVAC system. Replaced filters and cleaned ducts. System is now operating at optimal efficiency.

Materials Used

Material	Quantity	Cost
HVAC Filter	2 units	\$45.00
Duct Cleaner	1 bottle	\$18.50

Equipment Used

Vacuum system, pressure gauge, multimeter

Technician Notes

Customer should consider upgrading to a more efficient system within the next year.

Customer Feedback

Technician was punctual and professional. Explained everything clearly.

Customer Rating

5/5 stars

Technician Signature:

Michael Johnson

Date: 2025-09-07

Client Signature:

John Smith

Date: _____