

Notes: C4 is not required except in unusual circumstances. Headers H1—H8 and all optional components are not required for basic operation. See mirobo.tech/ubmp4 for details. PICkit ICSP header H9 is required for programming if the bootloader is not used.









USB-Based Beginner Multifunction Project UBMP4 is Open Hardware Schematic: CC-BY 4.0

mirobo.tech UBMP4

File: UBMP430.kicad_sch		Rev: 3
Size: B	Date: 2023-04-26	Page: 1/1
KiCad E.D.A. kicad 7.0.2-0		Sheet: