

INSPECTION REPORT (SCANNED COPY)

Facility: South Yard Tank Farm

Vessel Tag: V-101

Inspection Date: 2026-07-02

Findings: Minor surface corrosion noted near nozzle N-2. No active leakage observed.

Recommend re-coating within 6 months.

Inspector: J. Rao