## Mean Gap Height vs. Shaft Angle at 4500 RPM Comparison: Optimal vs Test Clearance

