

Warehouse Management Standard

1. Warehouse Classification

Warehouse A (Raw Materials): Steel, Aluminum — temperature 15–25C, humidity <60%

Warehouse B (Electronic Components): chips, resistors — temperature 20–25C, humidity <40%

Warehouse C (Finished Goods/Packaging): boxes, films — standard environment

2. Inventory Control Rules

FIFO (First In First Out) mandatory for all materials with expiry dates.

Weekly cycle count: 20% of SKUs per week, full count quarterly.

IF inventory variance > 2%, mandatory root-cause investigation within 48h.

Hazardous materials storage requires dedicated zone with fire suppression.

3. Receiving Procedures

Step 1: Check PO matching (quantity, spec, supplier).

Step 2: IQC sampling inspection — AQL 1.5 for critical materials.

Step 3: Barcode scan and ERP update within 2 hours of receipt.

IF IQC fail rate > 5%, reject entire lot and notify procurement.

4. Dispatch Procedures

Production requests must be submitted 24h in advance.

IF stock < request quantity, trigger emergency procurement alert.

All dispatches require dual authorization: warehouse keeper + production supervisor.