



2024 ANNUAL WATER QUALITY REPORT

Consumer Confidence Report for water delivered from 1 January to 31 December 2024 · Published 30 June 2025

Where your water comes from

In 2024, **78 percent** of your water came from the Tamsin Ridge Reservoir and was treated at the Cedar Bend Treatment Plant (coagulation, filtration and chlorine disinfection). The other **22 percent** came from Wells 2 and 3, which draw from the Upper Marl aquifer and are disinfected at the wellhead.

Results

We collected 1,640 samples in 2024. The table lists every substance that was detected. **The water met every federal and state drinking water standard; there were no violations.**

Substance (unit)	Limit (MCL or action level)	Our water	Typical source
Nitrate (mg/L)	10	2.1 (highest)	Fertilizer runoff
Fluoride (mg/L)	4	0.7 (average)	Added for dental health
Total trihalomethanes (µg/L)	80	41 (highest annual average)	By-product of disinfection
Haloacetic acids, HAA5 (µg/L)	60	22 (highest annual average)	By-product of disinfection
Lead (µg/L)	15 (action level)	3.2 (90th percentile); 0 of 30 homes above	Household plumbing
Copper (mg/L)	1.3 (action level)	0.21 (90th percentile)	Household plumbing
Turbidity (NTU)	1 (treatment technique)	0.08 (highest)	Soil runoff
Total coliform bacteria	5% of monthly samples	0 positive of 360	Naturally present in the environment

Lead in drinking water

Lead in drinking water comes mainly from materials in service lines and home plumbing. The Cooperative has no lead service lines in its inventory (updated October 2024). If water has been sitting for several hours, run the tap for 30 seconds before drinking or cooking.

Get involved

The Board of Directors meets on the second Wednesday of each month at 6:00 p.m. at 100 Reservoir Road; meetings are open to the public. For questions about this report, contact Tomás Ibarra, Operations Superintendent, at (555) 010-2420.