

Aviation Investigation Final Report

Location:	Parsons, Kansas	**Accident Number:**	CEN25LA064
Date & Time:	December 28, 2024, 13:25 Local	**Registration:**	N719LB
Aircraft:	Cozy Cub	**Aircraft Damage:**	Substantial
Defining Event:	Collision during takeoff/land	**Injuries:**	1 Serious
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot was on final approach to land when the airplane collided with power lines and impacted terrain. The airplane sustained substantial damage to the wings and fuselage and the pilot was seriously injured. When interviewed, the pilot stated he had no recollection of the accident. A witness reported the airplane was flying low and was in a left bank when it struck the power line. The witness thought the engine was running and the propeller was spinning at the time of the collision. A postaccident examination did not reveal any mechanical anomalies that would have precluded normal operations. The pilot did not return a completed NTSB Accident/Incident Report form 6120.1/2.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot’s failure to maintain clearance from power lines while on final approach to land.

Findings

Personnel issues	Monitoring environment - Pilot
Aircraft	Descent/approach/glide path - Not attained/maintained
Environmental issues	Wire - Awareness of condition

Factual Information

History of Flight

Approach-VFR pattern base	Collision during takeoff/land (Defining event)

Pilot Information

Certificate:	Private	**Age:**	26,Male
Airplane Rating(s):	Single-engine land	**Seat Occupied:**	Unknown
Other Aircraft Rating(s):	None	**Restraint Used:**	Unknown
Instrument Rating(s):	None	**Second Pilot Present:**	No
Instructor Rating(s):	None	**Toxicology Performed:**	
Medical Certification:	Class 3 Without waivers/limitations	**Last FAA Medical Exam:**	October 1, 2020
Occupational Pilot:	UNK	**Last Flight Review or Equivalent:**	
Flight Time:	447 hours (Total, all aircraft), 253 hours (Total, this make and model), 12 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cozy	**Registration:**	N719LB
Model/Series:	Cub	**Aircraft Category:**	Airplane
Year of Manufacture:	1992	**Amateur Built:**	Yes
Airworthiness Certificate:	Experimental (Special)	**Serial Number:**	1
Landing Gear Type:	Tailwheel	**Seats:**	4
Date/Type of Last Inspection:	Unknown	**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Ford
ELT:		**Engine Model/Series:**	3.8L V6
Registered Owner:	On file	**Rated Power:**	
Operator:	On file	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	**Condition of Light:**	Day
Observation Facility, Elevation:	KCNU,980 ft msl	**Distance from Accident Site:**	25 Nautical Miles
Observation Time:	13:39 Local	**Direction from Accident Site:**	335°
Lowest Cloud Condition:		**Visibility**	10 miles
Lowest Ceiling:	Overcast / 1500 ft AGL	**Visibility (RVR):**	
Wind Speed/Gusts:	9 knots / None	**Turbulence Type Forecast/Actual:**	None / None
Wind Direction:	320°	**Turbulence Severity Forecast/Actual:**	N/A / N/A
Altimeter Setting:	30.45 inches Hg	**Temperature/Dew Point:**	5°C / 0°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		**Type of Flight Plan Filed:**	None
Destination:		**Type of Clearance:**	Unknown
Departure Time:		**Type of Airspace:**	Class G

Airport Information

Airport:	Papas Dream Airport 39KS	**Runway Surface Type:**	Grass/turf
Airport Elevation:	890 ft msl	**Runway Surface Condition:**	Dry
Runway Used:	6	**IFR Approach:**	None
Runway Length/Width:	2000 ft / 60 ft	**VFR Approach/Landing:**	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Serious	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	None
Total Injuries:	1 Serious	**Latitude, Longitude:**	37.2983,-95.26311

Administrative Information

Investigator In Charge (IIC):	Miller, Bradley
Additional Participating Persons:	Ezra Olson; FAA, Wichita FSDO; Wichita, KS
Original Publish Date:	April 22, 2025
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=199479

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties … and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.