```
PisaSoftHand
+ PisaSoftHand()
+ start()
+ stop()
+ reset()
+ read()
+ write()
+ port selection()
```

+ pos_cmd_callback() + read status callback()

+ open_port() + set input()