

2021-07-13 Change LDO\_xc6228 CE\_input Update Button connector 1.5mm to 1.25mm Update LED connector 1.5mm to 1.25mm 2021-07-19 Add Pressure Sensor & HX711 Driver Change LED Driver that IO drives to GN1616 drives Add Charging\_connector for Type\_C 2021-07-20 Delete Buzzer----Add Power Switch PMOS

2021-07-21 Change LED+Button+Charing FPC connector to 1.27mm 2\*10 header Open the HX711 changle A that add NTC temperature 2021-08-4 Update connector-20-pin

Add H8118A50M5R DC-DC(3V-5V) PFM boost drivers Pump\_Motor

PTC Port:Add SS8050 NPN to drives MOSFET\_AO3401

2021-08-16 2021-09-06 Fix temperature bug; Update stc204s to stc205s

Change pump & ptc to DC3V 2021-09-14 change the ss8050 pull down resistor value 200K to 2K, fix bug that power on driver GPIO output high level

Change Vibration to DC5V Add SS8050 pull down resistor

Move control 2 control lines

Redo layout

2021-08-30 Add ss8050 to drives Vibration motor

Change the hx711 power supply 3V to 5V

Change the hx711 channel\_NTC input resistors

2021-08-31

Add 100R load\_resistor to gn1616 driver

Add Schottky Diode & Capacitor to mcu power supply