SEARCH BLOG | FLAG BLOG | Next Blog» Create Blog | Sign In

TaoSecurity

Dedicated to FreeBSD, network security monitoring, incident response, and network forensics. Email taosecurity at gmail dot com.

Tuesday, December 27, 2005

Taps and Hubs, Part Deux



Yesterday I described why the scenario depicted above does not work. Notice, however, that the hub in the figure is an EN104TP 10 Mbps hub. Sensors plugged into the hub see erratic traffic.

If that 10 Mbps hub is replaced with a 10/100 Mbps hub, like the DS108, however, the situation changes.



Blog Archive

▼ 2007 (242)

▼ July (28)

Goodbye AIA

Bejtlich Interviewed by TSSCI Blog

Enterprise Visibility Architect

Recent CVS Changes

Review of XSS Attacks Posted

Glutton for ROI Punishment

Managing and Monetizing Victims

NoVA Sec and NoVA BUG

Review Posted Plus NAC

No Undetectable Breaches

NORAD-Inspired Security Metrics

Another Review, Another Pre-Review

Security ROI Revisited

No ROI? No Problem

Bank Robber Demonstrates Threat Models

Thanks for the Memories Sys Admin Magazine

Ivan Voras FreeBSD 7 Live CD

Disk Usage Pages Added to NSM Wiki