














- PB0 -
- PB1 - CS_CONN_1
- PB2 - CS_FRAM
- PB3 - CS_CONN_2
- PB4 - CS_SDCARD
- PB5 - MOSI_SPI
- PB6 - MISO_SPI
- PB7 - SCK_SPI

VOLTAGE REFERENCE






Title: DATALOGGER02A

Author:






Size: A4

Page: 3/6

Date: 2026-08-09



INERTIAL MEASUREMENT UNIT



Title: DATALOGGER02A

Author:


Size: A4

Page: 4/6


Date: 2026-08-09



Pixhawk connectors



MLAB Pin Headers



Title: DATALOGGER02A

Author:

Size: A4


Page: 5/6

Date: 2026-08-09




SUPERCAP MANAGEMENT

Supercap charge current = 0 A
if load current = 1 A
 $R_s = 25 \text{ m}\Omega / I_{\text{load}}$




BUCK-BOOST CONVERTOR

1V6 – 5V5 IN
3V3 OUT




BUCK-BOOST CONVERTOR

1V6 – 5V5 IN
5V OUT



LDO

3V3 IN
1V8 OUT



Title: DATALOGGER02A

Author:

Size: A4

Page: 6/6

Date: 2026-08-09

