







Title: DATALOGGER02A





Author:

Size: A4

Page: 2/6


Date: 2026-08-09





- PB0 -
- PB1 - CS_CONN_1
- PB2 - CS_FRAM
- PB3 - CS_CONN_2
- PB4 - CS_SDCARD
- PB5 - MOSI_SPI
- PB6 - MISO_SPI
- PB7 - SCK_SPI

VOLTAGE REFERENCE







Title: DATALOGGER02A

Author:






Size: A4

Page: 3/6

Date: 2026-08-09



INERTIAL MEASUREMENT UNIT




Title: DATALOGGER02A


Author:

Size: A4 Page: 4/6 Date: 2026-08-09

Pixhawk connectors



MLAB Pin Headers



Title: DATALOGGER02A

Author:

Size: A4


Page: 5/6

Date: 2026-08-09




SUPERCAP MANAGEMENT


Supercap charge current = 0 A
if load current = 1 A
 $R_s = 25 \text{ m}\Omega / I_{\text{load}}$




BUCK-BOOST CONVERTOR 1V6 - 5V5 IN 3V3 OUT



BUCK-BOOST CONVERTOR 1V6 - 5V5 IN 5V OUT



LDO 3V3 IN 1V8 OUT



Title: DATALOGGER02A

Author:

Size: A4

Page: 6/6

Date: 2026-08-09

