

control	delay	GL/R/Ls/	Output
	Enable	Rs/C	Mode
values	On/Off	From 0.0	2_0_0,
		to 1.0	2_2_0,
			1_2_0,
			3_2_0
default	Off	0.5	1_2_0
value			

Tabela 1 – Korisničke kontrole