

control	Enable	Input gain	Mode	Output Mode
values	On/Off	From 0 to -∞ dB	0, 1	2_0_0, 3_0_0, 2_2_0, 3_2_0,
default value	On	-6 dB	1	2_0_0

Tabela 1 – Korisničke kontrole