

control	Enable	Input	Headroo	Output
		gain	m gain	Mode
values	On/Off	From 0	From 0	2_0_0,
		to -∞ dB	to -∞ dB	2_0_0,
				0_2_0,
				0_2_0,
				3_2_0
default	On	-6 dB	-3 dB	2_0_0
value				

Tabela 1 – Korisničke kontrole