

MIDI IN / OUT interface, 3.3 V or 5 V (SW1 must match VCC)


J3: TX RX GND VCC to the MCU UART. J4: i4 i5 o5 o2 o4 for panel jacks.


JP1 HARD THRU: fit a jumper cap to echo MIDI IN on the OUT jack; then leave J3 TX unconnected.

J1/J2 DIN jacks, J3/J4 headers: hand-soldered, not assembled by JLCPCB.
















































Sheet: /
File: midiboard.kicad_sch

Title:

Size: A4	Date:	**Rev:**
KiCad E.D.A. 10.0.7		Id: 1/1