## USE OF THE SCALE ON THE SPECTROMETER:


EXAMPLE

## ZERO POSITION:

VERNIER SCALE D'
COINCIDES NITH

MAIN SCALE 180'

[ ALSO V.S. 30' COIN- CIDES WITH M.S 194.5°
18 194° 30' (18=60')]



## TO TAKE A READING OTHER THAN ZERO

V.S. DIVISION COINCIDING WITH ANY

M.S. DIVISION = 16 H

STEPS:

1. READ M.S.

READING TO

IMMEDIATE LEFT OF

V.S 'O' (IN EXAMPLE

HIERE ITS 184° 30')

M.S. READING TO

IMMEDIATE LEFT OF VERNIER ZERO = 1841

- 2. RECORD WHICH V.S = 184°30'

  DIVISION COINCIDES WITH ANY M.S DIVISION ie 4th or 5th etc... (IN EXAMPLE HERE ITS 16th)
- 3. FINAL READING = M.S. READING + 1'x # OF V.S.D
  COINCIDING

IN EXAMPLE: FINAL READING = 184°30' + 16'

= 184°46'