

WWLLN Service Unit v4d 11/15/2013





- Ø 1/2" and Ø 3/8" need Ø 1/8" pilots
- Use file and nibbler after test fit
- Trim Service Unit board corners