

Hybrid III 6 y/o Lab

BME254L - Spring 2026 - Palmeri

Dr. Mark Palmeri, M.D., Ph.D.

2026-01-07

Table of contents

Tasks	1
What to submit	2
Bottom Plate	4
Top Plate	6
Nodding Plate	8
Molded Neck	10
Lower Neck Bracket	12
Load Cell	13
Assembly	14


Tasks

- Create all of the parts for the Hybrid III 6yo test setup based on the attached drawings.
- You should create all of these parts and their associated drawings and assemblies as part of the same “Document” and share that document with Dr. Palmeri and the TA(s).
- Create the mechanical drawings associated with each of those parts (i.e., recreate the drawings that you are using to generate the parts) and the assembly.
- Assemble your parts as guided by the assembly diagram and as shown in the uploaded animation.
- There are online tutorials on Assemblies if you need some refreshers:
 - <https://learn.onshape.com/courses/introduction-to-assembly-design>
 - <https://learn.onshape.com/courses/fundamentals-onshape-assemblies>


What to submit

Upload mechanical drawings and a screenshot of the part for all of your parts to the Hybrid III 6 y/o Gradescope assignment.


Bottom Plate




Top Plate




Nodding Plate



Molded Neck



Lower Neck Bracket



4 3 2 1

D

C

B

A

2X Ø.125
0.25 DP.

4X Ø.150 THRU
#10-24 T.125
X 0.25 DEEP TAP

Ø.438 X 0.040

R1.779

4X Ø.20
1/4-20

.700

.175

.438

2.12

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75

.37

.25

.5

2

1

.5

.25

4X R.25

2.25

1.6

1.26

1.08

.92

.58

.24

1.8

2.4

4X 25°

90°

4.75°

.525

1.25

1.05

.108

.17

.32

.72

Ø.315

Ø.68

1.06

.57

.25

.12

1.06

1.14

1.471

1.5

.75</

Assembly

