

## **RTOS :**

### **Team Member Info:**

- 1. Name : Tejas Mysore Lakshmikanth**  
**Matriculation No. : 269243**
- 2. Name : Pavan Shetty**  
**Matriculation No. : 266318**

### **Changes :**

- 1) main folder :**
  - Added trace.c , trace.h files
  - Updated main.cpp , CmakeLists.txt file
- 2) In path : freertos/config/include/freertos:**
  - Added freertos\_trace\_macros.h, trace\_events.h
  - Updated FreeRTOSConfig.h
- 3) In path : FreeRTOS-Kernel/include/freertos :**
  - Updated tasks.c and FreeRTOS.h from traceTASK\_DELAY() to traceTASK\_DELAY(xTicksToDelay)

### **Storage and visualization:**

Step (1): From Root folder directory (RTOS) execute bash file as ***./run.sh*** (It builds, flash, monitor, stores the serial output and parse it to write csv file).

Step (2): Visualize the csv file using command : ***python3 visualize\_pro.py log\_entries.csv***