***FICTIONAL ASSESSMENT FIXTURE***

# Preliminary basement inspection

## Reference and date

Incident IMG_003 / inspection INS-003 / 22 September 2026. This report concerns the flooded basement shown in the corresponding image.

## Observed damage

Standing water affects the basement, including stored belongings and low wall surfaces. Severe water damage is visible. The basement is one affected area for the exercise.

## Unresolved cause

The source of the water has not been established. A supply-pipe failure and external floodwater remain possible explanations. No policy rider or additional coverage document has been supplied. Do not infer the cause from a superficially similar historical claim.

## Next action

Request evidence of the water source or refer the coverage question to an adjuster. A provisional repair assessment with clearly stated uncertainty is useful. Do not promise coverage or a settlement.

*Synthetic training material. Not a real inspection, invoice, insurance decision or payment commitment.*